

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR; USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO 30-015-22723
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease: STATE ☒ FEE ☐
2. Name of Operator Mack Energy Corporation		6. State Oil & Gas Lease No. VO-8933
3. Address of Operator P.O. Box 960 Artesia, NM 88210		7. Lease Name or Unit Agreement Name Chip State
4. Well Location Unit Letter: G 1910 feet from the North line and 1977 feet from the East line Section 32 Township 23S Range 23E NM PM County Eddy		8. Well Number
11. Elevation (Show whether DR, RKB, RT, GR etc.) 4332' GR		9. OGRID Number 013837
		10. Pool Name or Wildcat Paddock

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO		SUBSEQUENT REPORT OF	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS ☐	P AND A ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐	CASING/CEMENT JOB ☐	
DOWNHOLE COMMINGLE ☐			
OTHER: ☒		OTHER: ☐	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion

Mack Energy Corporation proposes to Plug and Abandon this well as follows:

Well was drilled down to top of cement plug @ 2663

1. 8 5/8 Packer is currently stuck @ 2070'. Set 25sx plug on top of packer
2. Circulate hole w/mud laden fluid. Set 35sx from 500-400'
3. Circulate hole w/mud laden fluid. Circulate cement from 60-0'
4. Install Dry Hole Marker.

13 3/8 casing is set @ 440'
8 5/8 casing is set @ 2750'



Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Jerry W. Sherrell

TITLE Production Clerk

DATE 1/21/14

Type or print name Jerry W. Sherrell

E-mail address: jerry@mec.com

PHONE: (575) 748-1288

For State Use Only

APPROVED BY

R. Dade

TITLE

D. J. H. Serrano

DATE

Jan 21, 2014

Conditions of Approval (if any):