Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

OCD Artesia

. FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

5. Lease Serial No. NM114356

6. If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals.							
SUBMIT IN TRIPLICATE - Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No. 35251		
1. Type of Well					- 35251		
Oil Well Gas Well Other					8. Well Name and No. SANDY FED 003		
2. Name of Operator STRATA PRODUCTION COMPANY					9. API Well No. 30-015-40055		
3a. Address 3b. P			Phone No. (include area code)		10. Field and Pool or Exploratory Area		
PO BOX 1030, ROSWELL, NM 88202	575-623-1127	,		FORTY NINER RIDGE DELAWARE			
4. Location of Well (Footage, Sec., T., I	1)			11. County or Parish, State			
330 FSL & 330 FWL SEC 24-T23S-R30E			·		EDDY		
12. CHEC	K THE APPROPRIATE BO	OX(ES) TO IND	CATE NATUR	E OF NOTIC	CE, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF				CTION		
Notice of Intent	Acidize	Deepe	en	Prod	uction (Start/Resume)	Water Shut-Off	
	Alter Casing	Alter Casing Fracture Treat		Recla	clamation		
Subsequent Report	Casing Repair New Construction		Construction	√ Reco	Recomplete		
Subsequent report	Change Plans	Plug	and Abandon	Temp	porarily Abandon	ADD ADDITIONAL PAY	
Final Abandonment Notice	Final Abandonment Notice Convert to Injection Plug			☐ Wate	er Disposal		
testing has been completed. Final determined that the site is ready for 9-07-2013 MIRU Standard #50 wor 9-11-2013 Set CIBP @ 7991' Perforate from 7940'-50 with 6 spf - 9-16-2013 Frac Stage #1 from 7940'-50' with 1 Perf 7735 to 7530.5. 7445,44,43,42 Frac Stage #2 with 115,000# at 30 to Perforate stage #3 from 6460-65, 64 Frac stage #3 with 117000# at 20 to Perforate stage #4 from 6344-39, 62 9-17-2013 Frac stage #4 with 70,000# at 25 to Perforate from 6080-85, 6054-59,60 Frac stage #5 with 101,000# at 25 to Tag up on liner top at 7060'. Left CI MIRU Halliburton artificial lift equipm Make up and go in the hole with sub Turn well to production	r final inspection.) rkover rig. 66 total holes 100,000# at 30 bpm. ,41,40, 7310,09,08,07,06 pm. 470-75, 6524-29 with 18 t pm. 230-35 with 24 total holes pm. 103-08 with 18 total holes pm. 1BP @ 7840' not drilled. nent. p pump. EOT @ 6065.	,05, 7082,81,80 total holes shot s 2 jspf.	្ចុះ 0,79,78,77 with	28 total hol	Sully Record ACCEPTE		
PAUL RAGSDALE			Title OPERATIONS MANAGER				
Signature and So	Date 01/09/2014						
	THIS SPACE	FOR FEDE	RAL OR ST	TATE OF	FICE USE		
Approved by							
			Title			Date	
Conditions of approval, if any, are attached that the applicant holds legal or equitable the applicant to conduct operations	title to those rights in the subjective the subjection.	ect lease which we	certify ould Office				
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it	a crime for any p	erson knowingly	and willfully	to make to any departmen	t or agency of the United States any false.	