Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

R)	UREAU OF LAND MANA	GEMENT				51,2010
SUNDRY NOTICES AND REPORTS ON WELLS					Lease Serial No. NMLC029387C	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tri	be Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreemen	t, Name and/or No.
Type of Well ☐ Gas Well ☐ Oth	ner		,		8. Well Name and No. SHUGART (APCO) "A	\" 002
Name of Operator CIMAREX ENERGY CO OF C	Contact:	DAVID A E MILAGRO-R	YLER ES.COM		9. API Well No. 30-015-05628	
3a. Address 600 N. MARIENFELD, SUITE 600 MIDLAND, TX 79701			3b. Phone No. (include area code) Ph. 432-687-3033		10. Field and Pool, or Expl SHUGART; YATES	
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description	n) .			11. County or Parish, and S	State
Sec 29 T18S R31E Mer NMP NWNE 660FNL 1980FEL			, e		EDDY COUNTY, NI	M
12. CHECK APPR	ROPRIATE BOX(ES) T	O INDICAT	E NATURE OF	NOTICE, RE	EPORT, OR OTHER D	ATA
TYPE OF SUBMISSION			ТҮРЕ С	F ACTION		
☑ Notice of Intent	☐ Acidize	□ De	•		, , , , , , ,	Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	_	acture Treat	☐ Reclama		Well Integrity
	☐ Casing Repair	_	w Construction	☐ Recomp		Other
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection		g and Abandon Tempora g Back Water D		arily Abandon Disposal	
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Attached that the site is ready for final that the site is that the site is that the site is that the site is the site is that the site is the site is the site is that the site is t	rk will be performed or provided operations. If the operation repaid operation in the operation repaid of the performed operation of the performance of the performan	e the Bond No. esults in a multi led only after a 3,250'-3,110 0'-1,930'(B/S	on file with BLM/BI ple completion or rec I requirements, inclu D'; PRES. TEST (ALT, B/ANHY); V CSC, SHOE, T/SA	A. Required subcompletion in a noding reclamation CSG. VOC X TAG. LT), TAG.	osequent reports shall be filed new interval, a Form 3160-4 s n, have been completed and MAR 1	within 30 days hall be filed once he operator has 4 2014
DURING THIS PROCEDURE THE REQUIRED DISPOSAL,	WE PLAN TO USE THE	CLOSED-L				Control of the Contro
Appended for resolution 3)	PIL	RECLAMA A	TION PROCEDU TTACHED	T & Same .	EE ATTACHED ONDITIONS OF	
14. I hereby certify that the foregoing is Name (Printed/Typed) DAVID A	Electronic Submission For CIMAREX ENE Committed to AFMSS	RGY CO OF	COLÓRADO, sem	t to the Carlsb IAM on 03/07/2	pad . ,	
Name (17 mear 19 pear) DAVIDA	TILEN		THE AGEN	1		
Signature (Electronic S	Submission)		Date 03/06/2	2014		
	THIS SPACE F	OR FEDER	AL OR STATE	OFFICE US	SE .	
Approved By James	Q. amos		Title 5	EPS		Date 3-1/-14
Conditions of approyal, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	nitable title to those rights in the ct operations thereon.	e subject lease	Office Cf	O		· · · · · · · · · · · · · · · · · · ·
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s					ke to any department or agen	cy of the United
	,		and the second s			

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Ground level Dry Hole Marker Required

	Cimarex Energy Co. of Colorado
	Shugart A #2 (APCO)
Zinian di Linian	660' FNL & 1980' FEL
rilled 1942	Sec 29 – T18S – R31E, Eddy Co NM
	API; 30-015-05628 J Piwetz 10/21/2013
	10/21/2013
	FIFE CALL
	- हामहें हिस्सी हैं
	PERF. X CIRC. 100 SXS. CIMT @100'-3'
	F 221. K 222C, 700 3 x 3. C 1 1 (2 7 0 0 - 3
	PXA I
$\mathcal{F}_{i} = \{\chi_{i}, \dots, \chi_{i}\}$	
,	
•	
	ाष्ट्रका । विकास के किस्से के किस
	1 1 2 1 C 1 C 1 C 1 C 1 C 1 C 1 C 1 C 1
	8-5/8" csg @ 768' 50 sxs; TOC @
•	
	fight str. F left
	PERF. X 502. 55 5X5. CMT @ 818-718-774
,	
•	
•	10 E-207 0
	The state of the s
	PERF. X 592. 55 5X5.CMT C 2050 - 1930- TAC
* · · · · · · · · · · · · · · · · · · ·	
	3250'-3110'
	Pump 25 3×5.cmTCD
	- SET 51/2" CTBPC 3250'
•	Queen Perfs:
	3260-68
	2070.00
	3272-80
	3272-80 3284-94 Penrose Perfs: 3531-38
	Penrose Perfs:
	3531-38
	5-1/2" 14# csg @ 3540"
	2-1/2 14# csg @ 3540
	160 sxs cmt; TOC @



Drilled 1942

Cimarex Energy Co. of Colorado

Shugart A #2 (APCO) 660' FNL & 1980' FEL

Sec 29 - T18S - R31E, Eddy Co NM API: 30-015-05628

J Piwetz

10/21/2013

8-5/6" csg @ 768' ✓ 50 sxs; TOC @

7/Salt 800

Quantity	Description	Length .	Setting Depth
113		3491.70	3491.70
1	2-3/8' API SN	1.10	3492.80
1	2-3/8" Perf Sub	4.00	3496,80
1	2-3/8" J-55 Tbg w/Bull Plug	31,00	3527.80

Quantity		Description	Length	
	1 .	1 1/4" x 16" PR	. 16	
	1	1 1/2" x 8' PRL	~ 14.00	
	5	7/8" x 2',2',2',4',5'	3575.00	
	65:	7/8" rcds	2.00	
	73	3/4" rcds	12.00	
	1	2" x 1 1/2" x 20' RWBC	3619.00	

Queen Perfs:

3260-68

3272-80

3284-94

Penrose Perfs:

3531-38

5-1/2" 14# csg @ 3540"

460 sxs cmt; TOC @ 100 SX

Open hole to 3729', plug back with Calseal & Hydromite

PBTD: 3668' TD: 3729'



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 E. Greene St.
Carlsbad, New Mexico 88220-6292
www.blm.gov/nm



In Reply Refer To: 1310

Interim Reclamation Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses.

Interim reclamation consists of minimizing the footprint of disturbance by reclaiming all portions of the well site not needed for production operations. The portions of the cleared well site not needed for operational and safety purposes are recontoured to a final or intermediate contour that blends with the surrounding topography as much as possible. Sufficient level area remains for setup of a workover rig and to park equipment. Topsoil is respread over areas not needed for all-weather operations. Production facilities should be clustered to maximize the opportunity for interim reclamation. In order to inspect and operate the well or complete workover operations, it may be necessary to drive, park, and operate on restored, interim vegetation within the previously disturbed area. This is generally acceptable provided damage is repaired and reclaimed following use.

To reduce final reclamation costs, maintain healthy, biologically active topsoil; and to minimize habitat, visual, and forage loss during the life of the well, all salvaged topsoil should be spread over the area of interim reclamation, rather than stockpiled.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). Interim reclamation is to be completed within 6 months of well completion.
- 3. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with interim reclamation as per approved APD or Sundry Notice. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 4. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 5. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909 (Office), 575-361-2648 (Cell)

Linda Denniston Environmental Protection Specialist 575-234-5974

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Mike Burton Environmental Protection Specialist 575-234-2226

Jeffery Robertson Natural Resource Specialist

Solomon Hughes Natural Resource Specialist 575-234-5951

Douglas Hoag Civil Engineering Technician 575-234-5979

Requirements for ground level dry hole markers <u>Well Identification Markers</u> Conditions of Approval (COA)

The BLM Carlsbad Field Office (CFO) Conditions of Approval (COA) Requires that ground level dry hole markers be placed on well within the Lesser Prairie Chicken habitat area. The dry hole markers will be to the following specifications. The operator will construct the markers as follows:

- 1. An 8 inch X 8 inch steel plate 1/8 to 3/16 of an inch thick is to be placed on the old dry hole marker stand pipe 2 inches from ground level, in the Lesser Prairie Chicken habitat area.
- 2. Steel plate may be welded or bolted approximately 2 inches from ground level on the stand pipes. If plates are bolted to the stand pipe, the person installing the plate will be required to weld a pipe collar on the plate and place a minimum of two set screws/bolt on each collar. Aluminum data plates may be bolted with minimum ¼ inch bolt and locking nuts or self tapping fine threaded screws. A minimum of one in each corner is to be installed on each plate.
- 3. An 8 inch x 8 inch aluminum plate, which is 12 gauge or .080 sign material (1/8 inch aluminum plate may be used in place of the .080 plate) with the required information for that well stamped or engraved in a minimum 3/8 inch tall letter or number.
- 4. The following information will be stamped or engraved on the 8 inch X 8 inch aluminum plate in the following order.
 - a. First row: Operators name
 - b. Second row: Well name and number
 - c. Third row: Legal location to include ¼ ¼, Section, Township, and range. If the legal location cannot be placed on one row it can be split into two rows with the ¼ ¼ (example: 1980 FNL 1980 FWL) being on the top row.
 - d. Fourth row: Lease Number and API number.
 - i. Example marker plate: (attached)

NMOCD Order No. R-12965 also required the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a ground level dry hole marker was installed as required in the COA's from the BLM.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.