

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM A	PPRO	VED
OMB No	. 1004-	0137
Cuningal	1 2.1	201

OCD Artesia

CUMPRY NOTICES AND REPORTS ON WELL O			5. Lease	5. Lease Serial No.6. If Indian, Allottee or Tribe Name		
			an			
SUBMIT IN TRIPLICATE - Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No. East Shugart Unit		
1. Type of Well ✓ Oil Well ☐ Gas Well ☐ Other			8: Well N	8: Well Name and No. ESU # 21		
2. Name of Operator Americo Energy Resources, LLC			9. API W 30-015-0	Tell No. 05693		
3a. Address		3b. Phone No. (include area of 713-984-9700	· · · · · · · · · · · · · · · · · · ·	10. Field and Pool or Exploratory Area Shugart: Yates- 7Rs-Queens- Grayburg		
4. Location of Wcll (Footage, Sec., T.,R.,M., or Survey Description) 2310' FSL & 1650' FWL of Sec. 35, T-18S, R 31-E				11. Country or Parish, State Eddy. NM		
12. CHEC	K THE APPROPRIATE B	OX(ES) TO INDICATE NATU	RE OF NOTICE, REPO	RT OR OTHER D	PATA	
TYPE OF SUBMISSION		1	TYPE OF ACTION			
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Sta	rt/Resume)	Water Shut-Off Well Integrity	
Subsequent Report	Change Plans	New Construction□ Plug and Abandon	Recomplete Temporarily At	L	Other	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal			
 13. Describe Proposed or Completed Opthe proposal is to deepen directional Attach the Bond under which the word following completion of the involvent testing has been completed. Final determined that the site is ready for 1- MIRU workover rig, ND wealhead 2- Fish in the hole. Pull production erace 3- Clean out wellbore to TD 4- Check the casing. 5- RIH w/ SN and tbgs and put well in the proposal size in the size is ready for the size is rea	ally or recomplete horizonta york will be performed or pred operations. If the operat Abandonment Notices must r final inspection.) NU BOP quipment, fish out stucke	lly, give subsurface locations and ovide the Bond No. on file with ion results in a multiple comple be filed only after all requirements.	nd measured and true ver h BLM/BIA. Required si stion or recompletion in a ents, including reclamation	tical depths of all ubsequent reports new interval, a Fe on, have been com	pertinent markers and zones. must be filed within 30 days orm 3160-4 must be filed once upleted and the operator has	
LRD 3/17/14 Accepted for repord MICEOD	MA	CEIVED AR 1 4 2014 CD ARTESIA	SEE AT CONT	TACHED F INTIONS OF	OR APPROVAL	
 I hereby certify that the foregoing is to Name (Printed/Typed) Mehdi Sadeghi 	rue and correct.	Title Petrole	eum Engineer			
.1 \ 1	۱ ۱ -		****			

Date 01/06/2014 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

(Instructions on page 2)

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Jun.

East Shugart Unit 21 30-015-05693 Americo Energy Resources, LLC March 11, 2014 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by June 11, 2014.

- 1. Must conduct a casing integrity test to a minimum of 500 psi. Submit results to BLM. The CIT is to be performed on the production casing per Onshore Oil and Gas Order 2.III.B.1.h.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a **2000** (**2M**) **BOP** to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done. Operator to include well bore schematic of current well condition when work is complete.

JAM 031114