Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD	Artesia

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010 5. Lease Serial No.

6 If Indian Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottce o	or Tribe Name		
SUBMI	T IN TRIPLICATE - Other	r instructions on page 2.			ement, Name and/or No.	
1. Type of Well				East Shugart Unit		
Oil Well Gas W	/ell	ection Well		8. Well Name and No. ESU # 6		
2. Name of Operator Americo Energy Resources, LLC				9. API Well No. 30-015-05696		
3a. Address		3b. Phone No. (include area co	ode)	10. Field and Pool or Exploratory Area		
7575 San Filpie, Ste. 200 ,Houston, TX 77063		713-984-9700		Shugart: Yates- 7Rs	3-Queens- Grayburg	
4. Location of Well (Footage, Sec., T., 990' FSL & 2310' FWL of Sec. 35 - 18s, Rge 31	•	1)		11. Country or Parish, Eddy. NM	State	
12. CHEC	CK THE APPROPRIATE BO	OX(ES) TO INDICATE NATUR	E OF NOT	ICE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
✓ Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	=	duction (Start/Resume)	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair	New Construction	Rec	complete	Other	
Change Plans	Change Plans	Plug and Abandon	Ten	Temporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Wa	ter Disposal		
13. Describe Proposed or Completed O the proposal is to deepen direction Attach the Bond under which the v following completion of the involvesting has been completed. Final determined that the site is ready for the complete of the comple	ally or recomplete horizonta work will be performed or proved operations. If the operat Abandonment Notices must r final inspection.)	lly, give subsurface locations and ovide the Bond No. on file with ion results in a multiple completi be filed only after all requirement	d measured a BLM/BIA. on or recom	and true vertical depths of Required subsequent republication in a new interval	of all pertinent markers and z ports must be filed within 30 l, a Form 3160-4 must be file	ones. days d once

1- RU Flow line to Frack tank . Open well flowing back to clean up the well.

2- Put well back on injection. Report injection rate for 2 days.
3- RU acid pump & truck. Acidize Queens perfs with 3500 gals acid 15% NeFe

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

4- Put well back in injection.

(Instructions on page 2)



NMOCD ARTESY

SEE ATTACHED FOR CONDITIONS OF APPROVAL

I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Mehdi Sadeghi	Title Petroleum Engineer	
Signature Melle Scoleym	Date 01/06/2014	APPROVED
THIS SPACE I	FOR FEDERAL OR STATE OFF	ICE USE AR 1 1 2014
Approved by	Title	money I man
Conditions of approval, if any, are attached. Approval of this notice does that the applicant holds legal or equitable title to those rights in the subjecentitle the applicant to conduct operations thereon.		BURLAU OF LAND MAYAGEMENT CARLSBAD FIELD OFFICE
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a	crime for any person knowingly and willfully to	make to any department or agency of the United States any false

Di::

East Shugart Unit 6 30-015-05696 Americo Energy Resources, LLC March 11, 2014 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by June 11, 2014.

1. Mechanical Integrity Test

- a) Conduct a Mechanical Integrity Test of the tubing/casing annulus after a tubing, packer or casing seal is established.
- b) The minimum test pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with a minimum 200 psig differential between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need to be reduced). An alternate method for a BLM approved MIT is to have the fluid filled system open to atmospheric pressure and have a loss of less than five barrels in 30 days witnessed by a BLM authorized officer.
- c) Document the pressure test on a one hour full rotation calibrated recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict injection approval.
- d) Notify BLM 575-200-7902, if there is no response, 575-361-2822 as work begins. Some procedures are to be witnessed. If no answer, leave a voice mail or email with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.
- e) Submit a subsequent Sundry Form 3160-5 relating the MIT activity. Include a copy of the recorded MIT pressure chart. List the name of the BLM witness, or the notified person and date of notification. NMOCD is to retain the original recorded MIT chart.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.

- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a **2000** (**2M**) **BOP** to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done. Operator to include well bore schematic of current well condition when work is complete.

JAM 031114