Form 3160-5 (August 2007)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD	Artesia

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

6	If	Indian	Alla	ottee	or '	Tribe	Nami

5. Lease Serial No.

abandoned well.	Use Form 3160-3 ( <i>A</i>	(PD) for such proposa	ls.			
SUBMIT IN TRIPLICATE - Other instructions on page 2.			7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well				East Shugart Unit		
Oil Well Gas Well Other			8. Well Name and No. ESU # 46			
2. Name of Operator Americo Energy Resources, LLC				9. API Well No. 30-015-27870		
3a. Address	3b. Phone No. (include area co	No. (include area code) 10. Field and Pool or		Exploratory Area		
7575 San Filpie, Ste. 200 ,Houston, TX 77063	713-984-9700		Shugart: Yates- 7Rs-Queens- Grayburg			
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)			11. Country or Parish, State			
180' FSL & 1660' FEL of Sec. 34-TWP 18-S, Rge 31-E				Eddy. NM		
12. CHEC	CK THE APPROPRIATE BO	DX(ES) TO INDICATE NATUR	E OF NOT	ICE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION		TY	PE OF AC	TION		
✓ Notice of Intent	Acidize	Deepen	<b>✓</b> Pro	duction (Start/Resume)	Water Shut-Off	
Notice of Intell	Alter Casing	Fracture Treat	Rec	clamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Rec	complete	Other	
	Change Plans	Plug and Abandon	Ten	nporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Wa	ter Disposal		
12 Describe Proposed or Completed O	noration: Clearly state all no	rtinant datails, including actimate	d starting d	ate of any proposed work	k and anneximate duration thereof If	

- the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)
- 1- MIRU Workover Rig, ND well head and NU BOP.
- 2- Pull the well, Scan out and pressure test tubigs.
- 3- Replace tbg as needed

(Instructions on page 2)

- 4- Tag bottom to make sure perfs are not covered.
- 5- RIH w/ SN and TBG and put well back on production.



SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Mehdi Sadeghi	Title Petroleum Engine	per
Signature March Salm	Date 01/15/2014	APPROVED
THIS SPACE FO	OR FEDERAL OR STATE O	FFICE USE
Approved by	Title	MAR 1 1 2014
Conditions of approval, if any, are attached. Approval of this notice does not that the applicant holds legal or equitable title to those rights in the subject legal to conduct operations thereon.		BURTAU OF LAND MUNAGEMENT CARLSBAD FIFT OFFICE
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a cr. fictitious or fraudulent statements or representations as to any matter within		

## East Shugart Unit 46 30-015-27870 Americo Energy Resources, LLC March 11, 2014 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by June 11, 2014.

- 1. Must conduct a casing integrity test to a minimum of 500 psi. Submit results to BLM. The CIT is to be performed on the production casing per Onshore Oil and Gas Order 2.III.B.1.h.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a **2000** (**2M**) **BOP** to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done. Operator to include well bore schematic of current well condition when work is complete.

**JAM 031114**