Form 3160-5 (August 2007)

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	FORM APPROVE
OCD Artesia	OMB No. 1004-01.
	Expires: July 31, 20

ON	ив N	o. 10	04-	0137
Ex	oires:	July	31.	2010

	OMB No. 1004-01.				
	Expires: July 31, 20				
5. Lease Serial No. NM 88134					

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.		6. If Indian, Allottee or Tribe Name							
SUBMIT IN TRIPLICATE – Other instructions on page 2.		7. If Unit of CA/Agreement, Name and/or No.							
1. Type of Well					9 W - 11 N	J N(
Oil Well Gas W	ell Other				8. Well Name a H B 11 Federa	al 11			
2. Name of Operator DEVON ENERGY PRODUCTION C	OMPANY, LP				9. API Well No 30-015-29739	9. API Well No. 30-015-29739			
3a. Address 333 West Sheridan Avenue, Oklahoma City, OK 73102-5015 3b. Phone No. (include area code) 405-552-4615		10. Field and Pool or Exploratory Area CEDAR CANYON; DELAWARE							
4. Location of Well (Footage, Sec., T., 2080' FSL & 1930' FEL; SEC 11-†24S-R29E	R.,M., or Survey Description	i)			11. Country or Eddy, NM	Parish, State			
12. CHEC	K THE APPROPRIATE BO	DX(ES) TO IND	ICATE NATUR	RE OF NOTI	CE, REPORT OF	R OTHER DA	ATA		
TYPE OF SUBMISSION			T	YPE OF AC	ΓΙΟΝ	-			_
Notice of Intent	Acidize Alter Casing	Deepe	en ure Treat	=	luction (Start/Resulamation	ıme)	Water Shut-Off Well Integrity		
✓ Subsequent Report	Casing Repair	_	Construction	Rec	omplete		Other		
Final Abandonment Notice	Change Plans Convert to Injection	Plug :	and Abandon		nporarily Abandon er Disposal	i			_
determined that the site is ready for Wellbore Plug & Abandonment 1. 1/8/14-MIRU plugging rig. 2. POOH w/2-7/8" production tubing 3. Set CIBP @ 6,950'. Dump bail 34 4. Set CIBP @ 6,456'. Dump bail 34 5. Set CIBP @ 5,260'. Dump bail 34 6. Cut and POOH w/5-1/2" casing fr 7. Spot 105 sx CI C @ 666'. Tag TO 8. Spot 30 sx CI C 60' to surface. 9. 2/5/14-Cut wellhead off and set defended between places.	Drill out existing cemen 4' cement on top. PBD @ 4' cement on top. PBD @ 4' cement on top. PBD @ om 3,400'. Set tubing & pDC @ 302'.) 6,916'.) 6,422'.) 5,226'. oacker @ 2,800)'. Pumped 17		Tagged TOC @) 2,873'	REC MAR NMOCD	1 4 2014	
9# mud circulated between plugs. Accepted for 1800 (20) 1810003/17	AOY REC	CLAMAT C.Z.27-	ION		Accepted w Liability un Surface resi	s to pluggi der bond i toration is	ing of the well b ts reisions antifi completed.	97 e,	
 I hereby certify that the foregoing is to Name (Printed/Typed) Ronnie Slack 	ue and correct.	/	Title Operat	ions Techni	cian				
Signature Romie S	lack		Date	2/6/	14 ACC	FPTED	FOR REC	מפח'	
	THIS SPACE	FOR FEDE	RAL OR S	TATE OF	FICE USE			1	_
Approved by			Title			MAR	1 0 2014		_
Conditions of approval, if any, are attached that the applicant holds legal or equitable tientitle the applicant to conduct operations	tle to those rights in the subje-	s not warrant or c	ertify		RIID		AND MANAGER		_
Title 18 U.S.C. Section 1001 and Title 43 fictitious or fraudulent statements or repre	U.S.C. Section 1212, make it a sentations as to any matter wi	a crime for any pe	erson knowingly	and willfully	17 200	SECTION 1	CHARLE OF BUILDING COLUMN	States any fal	sc

