

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JAN 09 2014

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

NJM 1402149370

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Old Ranch Canyon 7 Federal #5y	Facility Type	Well Location

Surface Owner	BLM	Mineral Owner		API No.	30-015-30653
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	7	22S	24E	1315	North	2315	West	Eddy County, NM

Latitude N 32.40886° Longitude W 104.53740°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	15 bbls	Volume Recovered	5 bbls
Source of Release	Failure of a Victaulic clamp on a 1.5" steel line	Date and Hour of Occurrence	12/20/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	M. Bratcher, J.M. Warren- OCD, J. Amos, J. Van Curen- BLM		
By Whom?	Christopher Jones	Date and Hour	12/20/2013 @ 3:33 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The failure of a Victaulic clamp on a 1.5" steel line caused 15 bbls of produced water to leak onto the ground. 5 bbls of produced water were recovered via vacuum truck and the clamp was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 50' x 150'. Remediation will be completed in accordance with a plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Christopher Jones	Approved by District Supervisor: Signed By <u>Mike Scanlon</u>		
Title: HES Specialist	Approval Date: JAN 21 2014	Expiration Date:	
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 1/9/14	Phone: (575) 628-4121	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: February 21, 2014	

\* Attach Additional Sheets If Necessary

2RP-2153