District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

MAR **11** 2014

RECEIVE

Form C-141 Revised October 10, 2003

2RP ZZIY

Oil Conservation Division 1220 South St. Francis Dr. NMOCSubmit PCopy to appropriate District Office in accordance with 19.15.29 NMAC

1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 Release Notification and Corrective Action n HMP 1407332688 **OPERATOR** Initial Report Final Report Name of Company: Linn Operating 9324 Contact: Brian Wall Address: 2130 W. Bender Hobbs, NM 88240 Telephone No.: 575-738-1739 Facility Name: State AZ Battery Flare(closest well State AZ) Facility Type: Battery Surface Owner: State Mineral Owner: API No.: (closest well) 3001505163 LOCATION OF RELEASE North/South Line Unit Letter Section Township Range Feet from the Feet from the East/West Line County M 16 17S 31E South 990 West Eddy Latitude: 32.8300337113083 Longitude: -103.880113741649 NATURE OF RELEASE Type of Release: Oil Volume of Release: 10 gal Volume Recovered: 0 Source of Release: Valve Heater Date and Hour of Occurrence: Date and Hour of Discovery: 01/26/2014 01/26/2014 0233 Was Immediate Notice Given? If YES, To Whom? ☑ Yes ☐ No ☐ Not Required Mike Burton- BLM Mike Bratcher-NM OCD By Whom? Brian Wall Date and Hour 01/27/2014 0900 Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.*: Describe Cause of Problem and Remedial Action Taken.*: At 2.33 am.I got a call from Larry Kincaid, the night rider. He told me there was a fire at the flare at the State AZ Battery. I had him turn well 606 off. I was enroute and called the fire department. Larry called me back and informed me the fire had burnt out. The fire was contained inside the firewall at flare. I called the fire department and canelled the trucks but they came out anway and looked at the scene and left.I arrived on scene about 3.40 am.Larry was panicking a little so i got him calmed down ,got his name, and released him from site.Upon investigating the the incident, I discovered that the production kimray had malfuntioned and dumped all the gas to the flare causing about 10 gallons of oil to go to the flare, causing the fire on the ground. All fluids were contained inside the firewall. I called a crew to change the kimray out. then i put well 606 back into operation. I also called Joe hernandez and gave him an update of the situation. Describe Area Affected and Cleanup Action Taken.*: Delineate spill site and turn in PLA to BLM &OCD. Remove contaminated soils and haul to approved site. Return clean soils to natural surface. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION Signature: Approved by District Supervisor: Printed Name: Brian Wall Approval Date: 3-14-16 Title: Construction Foreman II **Expiration Date:** E-mail Address: bwall@linnenergy.com Conditions of Approval: Attached Remediation per OCD Rule & Guidelines, & Date: 01/27/2014 Phone: 806-367-0645

like approval by BLM. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN: