•													
District I 1625 N. French Dr., Hobbs, NM 88240 State						of New Mexico RECEIVED Form C-141							
<u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210 Energy Miner						rals and Natural Resources MAR 0 5 2014 Revised October 10, 2003							
						nservation Division Sugmit 2 Copies to appropriate District Office in accordance							
District IV					outh St. Francis Dr. NMOCD ARTESIA with Rule 116 on back								
1220 3. 31. 14a	1220 S. SL Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 side of form Release Notification and Corrective Action												
			Rela	ease Notifi	catio			Action				_	
Name of Co		COG Opera	······		OPERATOR Initial Report Final Report								
			nd, Texas 7970	1	Telephone No. (432) 230-0077								
Facility Nat	me Jenkins	B Federal W	(Northwest Cent	ral)	Facility Type Tank Battery -								
Surface Ow	vner: Feder	al	Mineral ()wner	Lease No. (API #) 30-015-21945 Closest well location								
LOCATION OF RELEASE													
Unit Letter C	Section 20	Township 17S	Range 30E	Feet from the	North	/South Line	Feet from the	East/	West Line	County			
Latitude 32 49.813 Longitude 103 59.736													
NATURE OF RELEASE													
Type of Rele	ase: Produce		Volume of Release 3 bbls oil 17 bbls water			Volume Recovered 3 bbls oil 15 bbls water							
Source of Re	lease: Skim	Tank		Date and Hour of Occurrence Date and Hour of				Hour of Dis	r of Discovery				
Was Immedia	ate Notice G	liven?		3/23/2012 3/23/2012 11:30 a.m.									
Was Immediate Notice Given?													
By Whom? Was a Watero			Date and Hour										
was a watero	course Reac			If YES, Volume Impacting the Watercourse. N/A									
If a Watercourse was Impacted, Describe Fully.* N/A													
Describe Cau	se of Proble	m and Remed	lial Action	Taken.*							·		
Describe Cause of Problem and Remedial Action Taken.* Due to a rush of fluid from a new well and a plugged strainer at our Texaco BE #8 Injector the skim tank overflowed. The strainer at the Texaco BE #8 Injector has been cleaned out.													
Describe Area Affected and Cleanup Action Taken.*													
Initially 20 bbls was released from the skim tank and 18 bbls was recovered with a vacuum truck. The spill area measures 20'x20' around the skim tank. The release was contained on the location. The contaminated area was excavated to approximately 4.0' below surface, a 40 mil plastic liner was installed, and the area was backfilled with clean material.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Signature:	11	1 57		OIL CONSERVATION DIVISION									
Printed Name:	Ike Tavarez	(ilg	′)	Approved by District Supervisor:									
Title: Project M	Manager		A	Approval Date: 4/29/14 Expiration Date: NA									
E-mail Addres	s: Ike.Tavar	ez@TetraTec	c	Conditions of Approval:									
Date: /	1-19-	- 13			Final	Į –							

 Date:
 /////
 //////

 * Attach Additional Sheets If Necessary

:

2RP-1094