District I 1625 N. French Dr., Hobbs, NM 88240 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

AMMOOD ARTES

Form C-141

Revised August 8, 2011

**Release Notification and Corrective Action** 

	OPERÁTOR	2	Initial Report	🛛 Final Report
Name of Company: BOPCO	Contact: Ton	y Savoie		
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No.	432-556-8730		
Facility Name: Poker Lake Unit #227 2RP-774	Facility Type:	E&P		
Surface Owner Federal Mineral Owne	r Federal		API No. 30-015-3	3929

## LOCATION OF RELEASE

Unit Letter P	Section 30	Township 24S	Range 30E	Feet from the 330	North/South Line South	Feet from the 560	East/West Line East	County Eddy	
		L			<u> </u>	L			

Latitude 32.86647 Longitude 103.8571

## NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 50bbis	Volume Recovered 0		
Source of Release: 2" poly line connected to a water transfer pump	Date and Hour of Occurrence 4/19/11 time unknown	<ul> <li>Date and Hour of Discovery: 04/19/11 at 7:29 PM</li> </ul>		
Was Immediate Notice Given?	If YES. To Whom?	[ 7.29 FM		
Yes 🗌 No 🗌 Not Required		· · · · · · · · · · · · · · · · · · ·		
By Whom?	Date and Hour			
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*				
Describe Cause of Problem and Remedial Action Taken.* A 2" poly line failed where it was connected to a water transfer pump. T repaired later that evening.	he pump was shut down causing the f	low of water to stop. The poly line was		
Describe Area Affected and Cleanup Action Taken.* The produced water traveled down a lease road for approximately 900 ft and arroyo down with fresh water and capture the excess using a vacuum leak area. The area immediately south of the source that was not include submitted to a commercial lab for confirmation. Based on sample result installed in the area of highest chloride concentration. The excavations w I hereby certify that the information given above is true and complete to	n truck. On 04/25/11 approximately 3 ed in the wash activities, was delineate s, the impacted areas not previously w were backfilled with clean, imported s	00 bbls of fresh water was used to rinse the ed. Soil samples were field screened and rashed were excavated and a liner was oil and leveled.		
regulations all operators are required to report and/or tile certain release public health or the environment. The acceptance of a C-141 report by to should their operations have failed to adequately investigate and remedia or the environment. In addition, NMOCD acceptance of a C-141 report federal, state, or local laws and/or regulations.	notifications and perform corrective a he NMOCD marked as "Final Report" are contamination that pose a threat to	ctions for releases which may endanger does not relieve the operator of liability ground water, surface water, human health		
Signature: 1 ong Sund		VATION DIVISION		
Printed Name: Tony Savoie	Approved by Environmental Special	ist that can		
Title: Waste Mgmt. & Remediation Specialist	Approval Date: 5/4/14	Expiration Date: MA		
E-mail Address: TASavoie@BassPet.com Date: <u>3/12/14</u> Phone: 432-556-8730	Conditions of Approval:	Attached 🗆		
Attach Additional Sheets If Necessary		APR 2 9 2014		