
Submit 1 Copy To Appropriate District Office	State of New Me			Form C-103 Revised August 1, 2011	
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natu	irai Resources	WELL API NO		
<u>District II</u> – (575) 748-1283	OIL CONSEDUATION	DIVISION	30-015-03050		
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178			5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 8			X FEE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa I C, INIVI 6		6. State Oil & C	jas Lease No.	
	ICES AND REPORTS ON WELLS	S	7. Lease Name	or Unit Agreement Name	
	OSALS TO DRILL OR TO DEEPEN OR PL				
PROPOSALS.)	CATION FOR PERMIT" (FORM C-101) FO	JR SUCH	LEONARD STA		
1. Type of Well: Oil Well G	as Well X Other		8. Well Numbe	r .	
2. Name of Operator			9. OGRID Num	nher	
CIMAREX ENERGY CO. OF CO	DLORADO		162683		
3. Address of Operator			10. Pool name of		
600 N. MARIENFELD, SUITE 60	00, MIDLAND, TEXAS 79701		GRAYBURG A	TOKA, NORTH (GAS)	
4. Well Location					
	980 feet from the NORTH			VEST line	
Section 22	Township 17S	Range 29E	NMPM	EDDY County	
	11. Elevation (Show whether DR	, KKB, KI, GK, etc.,	,		
			Prof. to		
12. Check	Appropriate Box to Indicate N	lature of Notice,	Report or Othe	r Data	
NOTICE OF IN	NTENTION TO:	SUB	SEQUENT RI	FPORT OF	
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WOR		ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS ☐	COMMENCE DRI	LLING OPNS.	P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	T JOB 🗆	,	
DOWNHOLE COMMINGLE					
OTHER:		OTHER:			
13. Describe proposed or comp	oleted operations. (Clearly state all	pertinent details, and			
	ork). SEE RULE 19.15.7.14 NMAG	C. For Multiple Cor	npletions: Attach	wellbore diagram of	
proposed completion or re-	completion.				
1) SET 7" CIBP @ 10,300'; PU	JMP 45 SXS. CMT. @ 10,300'-10,	130' (T/ATOKA); C	CIRC. WELL W/ I	PXA MUD.	
2) PUMP 50 SXS. CMT. @ 7,2			•	•	
	120'-5,960' (T/ABO); WOC X TAC				
4) PERF. X ATTEMPT TO SQ 5) CUT X PULL 7" CSG. @ +	OZ. 55 SXS. CMT. @ 3,865'-3,735'	(1/GLOR.).			
	7 5,460 : 550'-3,420' (7" CSG.CUT, 9-5/8" C	SG.SHOE); WOC	X TAG CMT. PLU	JG.	
7) PUMP 50 SXS. CMT. @ 2,0	060'-1,940' (T/GB).				
	0'-638' (13-3/8" CSG.SHOE, B/SA		CMT. PLUG.		
	40 SXS. CMT. @ 338'-3' (T/SALT) :LLHEAD 3' B.G.L.; WELD ON ST		SGS X INSTALI	L DRY HOLE MARKER	
10)BIG 001 / 001 WE	Editerio 3 B.G.E., Webb Civis		.505. 7. 111517121	BORT HOLD WINKER.	
	WE WILL USE THE CLOSED-LO RED DISPOSAL, PER OCD RUNL		H A STEEL TAN	IK AND HAUL	
CONDITIONS OF APPROVAL ATTAC					
CONDITIONS OF APPROVAL ATTAC	Apr	proved for plugging of we	Il bore only.	RECEIVED	
Approval Granted providing wor	kis — his	oility u <mark>nder kond is rethi</mark> 3-103 (Subsequent Repor	erif Wall Phinging)	- "FOEIVED	
Completed by, AA	Rig Release water	ch máy be found at OCD		MAY 08 2014	
May be d	<u>313</u>	ms, www.cmnrd-state.nm	us/ocu.	NMOCD ARTES	
I hereby certify that the information	above is true and complete to the b	est of my knowledge	e and belief.	MINIOCD ARTESIA	
		-			
SIGNATURE SIGNATURE		AGENT		DATE: 05/02/14	
Type or print name: DAVID A. E. For State Use Only	r lek – E-mail address: DE	EYLER@MILAGRO	J-KES.COM P	HONE: 432.687.3033	
APPROVED BY:	De TITLE OCS	A Sylew 18	ν Λ Γ	ATE S/12/14	
Conditions of Approval (if any):	See Attacked Co	M's	υ <u>~ ν</u> υ		
• •	J-C I HULLEU	·· J			



Cimarex Energy Co. of Colorado CINIARE) KB - 14' above GL Leonard State Com #1 1980' FNL & 660' FWL Sec. 22, T-17-S, R-29-E, Eddy Co., NM M. Ketter 30-0/5 - 03050 5/29/2013 CIRC, 140 5x5.@ 338'-3' 13-38" 54.5#, J55 csg @ 750' 800 sxs; Circl'd Cmt Pump 70 5x5 @ 800'-638'-196 Pump 50 5x5.@ 2060'-1940' CUT X PULL 7" CSG. (2 3486) 9-5/8", 40#, J55 csg @ 3,486" 1,400 sxs; Circl'd Cmt Pump 60 5x5.@ 3550'-3420'- 74/-MEGRAFIA PERF. X 592. 55 5X50 3865-3735 PXF MUP TOC @ 5,843' Pump 45 sxs.@ 6120'-5960'-7AG PKA Pump 50 5x5.@ 7325'- 7155! AXG -Pump 45 SXS.@ 10300'-10130' Atoka Perfs: 10,342'-360' SET 7"OIBP @10300! Could be a CIBP @ 10,630', Topped with 35' Cmt Morrow Perfs: RECEIVED 10,680'-760' MAY **08** 2014 Perfs: 11,054'-060' NMOCD ARTES 50 sx plug across perfs: 11,054'-060' 7", 32#, S95 csg @ 11,060' 600 sxs; TOC - 5,843' 110 sx Plugg to 11,087' PBTD: 10,590' DAE 05/02/14

TD: 11,441'

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

(CONDITIONS	OF APPROV	AL FOR	PHICGING	& AR	ANDONMENT
₹.		 	-1 I . I . I . I . I . I . I . I . I . I		AX MAD	MANUAL PROPERTY OF MANUAL AND A STREET AND A

Operator: Uwwex	
Well Name & Number: <u>Leonard</u> State Con	/
API#: 30-015-03050	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 5/12/14

APPROYED BY:

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).