

District I
1625 N. French Dr., Hobbs, NM 88240.
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP 1413427828

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Linn Operating, Inc. <i>269 324</i>	Contact: Brian Wall	
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No. 575-738-1739	
Facility Name: Turner B #101	Facility Type: Injection	
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-26695

LOCATION OF RELEASE

Unit Letter D	Section 20	Township 17S	Range 31E	Feet from the 690	North/South Line North	Feet from the 1150	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	-------------

Latitude 32.8245657898873 Longitude -103.896766902005

NATURE OF RELEASE

Type of Release: Produced Water/Oil	Volume of Release 4 bbls/1 bbl	Volume Recovered 0
Source of Release: Poly Pipeline	Date and Hour of Occurrence 10/09/2013 12:00 P.M.	Date and Hour of Discovery 10/09/2013 12:00 P.M.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton BLM	
By Whom?	Date and Hour 10/15/13 11:45 A.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA

RECEIVED

APR 29 2014

NMOCD-ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

10-09-13 received phone call from an Apache pumper that there had been a poly line leak. Placed a temporary clamp on the line until a crew was available to bleed down the line and fuse it.

Describe Area Affected and Cleanup Action Taken.*

There was an approximate affected area of 40X20. There was a small misted area with a nominal amount of standing water. DFSI was retained to remediate the spill and reclaim the pad. On February 05, 2014 the site was reclaimed and seeded according to NMOCD and BLM guidelines. DFSI respectfully requests closure of this C-141.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Fred B Wall</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Brian Wall	Approval Date: <i>5/14/14</i>	Expiration Date: <i>NA</i>
Title: Construction Foreman II	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
E-mail Address: bwall@linenergy.com		
Date: 03/25/2014 Phone: 806-367-0645		

* Attach Additional Sheets If Necessary

22P-2299