			RECE	VED			
		UNITED STATES	TERIOR MMADIZ	0.2014	[)[VISION FORM OMB N	APPROVED IO. 1004-0135 July 31, 2010	
		UREAU OF LAND MANAG	JEMENT 811	Nutra and	5 Lesse Serial No.	July 51, 2010	
	Do not use th	is form for proposals to I. Use form 3160-3 (APL	RTS ON WEBBOCD A drill or to re-enter an) for such proposals.	CI II DELSINA OP	6. If Indian, Allottee o	or Tribe Name	
= *	SUBMIT IN TRI	PLICATE - Other instruc	tions on reverse side.		7. If Unit or CA/Agre	ement, Name and/or No.	
	I. Type of Well	ype of Well 🖸 Gas Well 📋 Other			8. Well Name and No. GERRY FEDERA		
· -	2. Name of Operator YATES PETROLEUM CORPO	erator Contact: TINA HUERTA ETROLEUM CORPORATIONE-Mail: tinah@yatespetroleum.com			9. API Well No. 30-005-61155-00-S1		
	^{3a.} Address 105 SOUTH 4TH STREET ARTESIA, NM 88210	105 SOUTH 4TH STREET Ph: 575-748-4168			10. Field and Pool, or Exploratory PECOS SLOPE-ABO		
_	4. Location of Well <i>(Footage, Sec., T</i> Sec 1 T8S R25E NWNW 6601	,			11. County or Parish, CHAVES COUI		
-	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
_	TYPE OF SUBMISSION	E OF SUBMISSION TYPE OF ACTION					
-	Notice of Intent		Deepen	_	on (Start/Resume)	U Water Shut-Off	
	□ Subsequent Report	Alter Casing	Fracture Treat	🗖 Reclamat		U Well Integrity	
	· . ·	Casing Repair	New Construction	Recompl		□ Other	
	Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	 Tempora Water Di 	rily Abandon		
· · ·	 with tubing. 2. Set a CIBP at 3750 ft and of 3. Perforate at 1895 ft and sp 100 ft plug across intermediate 4. Perforate at 1408 ft and sp 100 ft plug across top of Glorid 5. Perforate at 880 ft and spo 	cap it with 35 ft cement. T ot a 30 sx Class C cemen e casing shoe, inside and ot a 25 sx Class C cemen eta, inside and outside cas t a 25 sx Class C cement shoe, inside and outside ca a 15 sx Class C cement p	his puts a plug over Abo. t plug from 1795 ft -1895 ft. outside casing. WOC and t t plug from 1908 ft -1408 ft. sing. plug from 780 ft - 880 ft. Th asing. WOC and tag plug. lug from 60 ft up to surface	This puts a This puts a This puts a This puts a his puts 100	CONDITION Incos	S OF APPROM	
	 with tubing. 2. Set a CIBP at 3750 ft and of 3. Perforate at 1895 ft and sp 100 ft plug across intermediate 4. Perforate at 1408 ft and sp 100 ft plug across top of Glorid 5. Perforate at 880 ft and spo ft plug across surface casing s 6. Perforate at 60 ft and spot 	cap it with 35 ft cement. T ot a 30 sx Class C cemen e casing shoe, inside and ot a 25 sx Class C cemen eta, inside and outside cas t a 25 sx Class C cement shoe, inside and outside ca a 15 sx Class C cement p with	his puts a plug over Abo. t plug from 1795 ft -1895 ft. outside casing. WOC and t t plug from 1908 ft -1408 ft. sing. plug from 780 ft - 880 ft. Th asing. WOC and tag plug. lug from 60 ft up to surface	This puts a This puts a This puts a his puts 100 This puts 100 This puts 100	CONDITION Incos	8 OF AFPROM	
· · · · ·	 with tubing. 2. Set a CIBP at 3750 ft and of 3. Perforate at 1895 ft and sp 100 ft plug across intermediate 4. Perforate at 1408 ft and sp 100 ft plug across top of Glorid 5. Perforate at 880 ft and spo ft plug across surface casing se 6. Perforate at 60 ft and spot 14. Thereby certify that the foregoing is Committee 	cap it with 35 ft cement. T ot a 30 sx Class C cemen e casing shoe, inside and ot a 25 sx Class C cemen eta, inside and outside cas t a 25 sx Class C cement shoe, inside and outside cas a 15 sx Class C cement p with true and correct. Electronic Submission #2 For YATES PETRO d to AFMSS for processing	his puts a plug over Abo. t plug from 1795 ft -1895 ft. outside casing. WOC and t t plug from 1808 ft -1408 ft. sing. y from 780 ft - 880 ft. Tr asing. WOC and tag plug. lug from 60 ft up to surface s 42164 verified by the BLM W DEUM CORFORATION, sent by BEVERLY WEATHERFOR	This puts a tag plug. 2,7 This puts a this puts 100 w i Ches PPROVED INDINU ell Information t to the Roswell D on 04/14/201	CONDITIOR 5	S OF APPROM	
-	 with tubing. 2. Set a CIBP at 3750 ft and of 3. Perforate at 1895 ft and sp 100 ft plug across intermediate 4. Perforate at 1408 ft and sp 100 ft plug across top of Glorid 5. Perforate at 880 ft and spo ft plug across surface casing se 6. Perforate at 60 ft and spot 14. Thereby certify that the foregoing is Committee Name (Printed/Typed) TINA HUE 	cap it with 35 ft cement. T ot a 30 sx Class C cemen e casing shoe, inside and ot a 25 sx Class C cemen eta, inside and outside cas t a 25 sx Class C cement shoe, inside and outside cas t a 25 sx Class C cement p with true and correct. Electronic Submission #2 For YATES PETRO d to AFMSS for processing RTA	his puts a plug over Abo. t plug from 1795 ft -1895 ft. outside casing. WOC and t t plug from 1908 ft -1408 ft. sing. plug from 780 ft - 880 ft. Th asing. WOC and tag plug. lug from 60 ft up to surface s 42164 verified by the BLM W DLEUM CORFORATION, sent by BEVERLY WEATHERFOF Title REG F	This puts a tag plug. L , T This puts a his puts 100 L PPROVED INDING ell Information to the Roswell RD on 04/14/201 REPORTING S	CONDITION Access FOR 3 FOR 3 VIEW System 4 (14BMW1660SE) UPERVISOR Accessed 1	MONTH PERIC	
· · · · · · · · · · · · · · · · · · ·	 with tubing. 2. Set a CIBP at 3750 ft and of 3. Perforate at 1895 ft and sp 100 ft plug across intermediate 4. Perforate at 1408 ft and sp 100 ft plug across top of Glorid 5. Perforate at 880 ft and spo ft plug across surface casing se 6. Perforate at 60 ft and spot 14. Thereby certify that the foregoing is Committee 	cap it with 35 ft cement. T ot a 30 sx Class C cemen e casing shoe, inside and ot a 25 sx Class C cemen eta, inside and outside cas t a 25 sx Class C cement shoe, inside and outside ca a 15 sx Class C cement p <i>with</i> true and correct. Electronic Submission #2 For YATES PETRO d to AFMSS for processing ERTA	his puts a plug over Abo. L t plug from 1795 ft -1895 ft. outside casing. WOC and t t plug from 1908 ft -1408 ft. sing. L 77655 plug from 780 ft - 880 ft. Th asing. WOC and tag plug. lug from 60 ft up to surface s 42164 verified by the BLM W DLEUM CORFORATION, sem by BEVERL WEATHERFOF Title REG F Date 04/14/	This puts a This puts a This puts a his puts 100 This puts 100	CONDITION Acres FOR <u>3</u> System 4 (14BMW1660SE) UPERVISOR ACCORTEC 1 NULL	MONTH PERIC	
-	 with tubing. 2. Set a CIBP at 3750 ft and sp 3. Perforate at 1895 ft and sp 100 ft plug across intermediate 4. Perforate at 1408 ft and sp 100 ft plug across top of Glorid 5. Perforate at 880 ft and spot ft plug across surface casing se 6. Perforate at 60 ft and spot 14. Thereby certify that the foregoing is Committee Name (<i>Printed/Typed</i>) TINA HUE Signature (Electronic Section 2014)	cap it with 35 ft cement. T ot a 30 sx Class C cemen e casing shoe, inside and ot a 25 sx Class C cemen eta, inside and outside cas t a 25 sx Class C cement shoe, inside and outside ca a 15 sx Class C cement p <i>with</i> true and correct. Electronic Submission #2 For YATES PETRO d to AFMSS for processing ERTA	his puts a plug over Abo. t plug from 1795 ft -1895 ft. outside casing. WOC and t t plug from 1808 ft -1408 ft. sing. plug from 780 ft - 880 ft. Th asing. WOC and tag plug. lug from 60 ft up to surface 42164 verified by the BLM W DEUM CORFORATION, sem by BEVERLY WEATHERFOF Title REG F Date 04/14/	This puts a tag plug. 2,7 This puts a this puts 100 This puts 100 The provided of the puts PPROVED INDING INDING INDING COPPROVED INDING COPPROVED	CONDITION Acres FOR <u>3</u> System 4 (14BMW1660SE) UPERVISOR ACCORTEC 1 NULL	MONTH PERIC	
C	 with tubing. 2. Set a CIBP at 3750 ft and of 3. Perforate at 1895 ft and sp 100 ft plug across intermediate 4. Perforate at 1408 ft and sp 100 ft plug across top of Glorid 5. Perforate at 880 ft and spo ft plug across surface casing se 6. Perforate at 60 ft and spot 14. Thereby certify that the foregoing is 14. Thereby certify that the foregoing is Committee Name (<i>Printed/Typed</i>) TINA HUE Signature (Electronic S 	cap it with 35 ft cement. T ot a 30 sx Class C cemen e casing shoe, inside and ot a 25 sx Class C cemen eta, inside and outside cas t a 25 sx Class C cement shoe, inside and outside cas t a 25 sx Class C cement p withit Electronic Submission #2 For YATES PETRO d to AFMSS for processing RTA Dubmission) THIS SPACE FO	his puts a plug over Abo. t plug from 1795 ft -1895 ft. outside casing. WOC and t t plug from 1808 ft -1408 ft. sing. plug from 780 ft - 880 ft. Tr asing. WOC and tag plug. lug from 60 ft up to surface. 42164 verified by the BLM W DEUM CORFORATION, sent by BEVERLY WEATHERFOR Title REG F Date 04/14/ R FEDERAL OR STATE Title CE	This puts a tag plug. 2,7 This puts a this puts 100 This puts 100 This puts 100 The prove of the provided of the prove of the prove of the provided of t	CONDITION Seas FOR <u>3</u> System 4 (14BMW1660SE) UPERVISOR ACCORECT MUD E	MONTH PERIC <u>20 14</u> <u>CD S/W/14</u> <u>CD S/W/14</u>	
C c w	 with tubing. 2. Set a CIBP at 3750 ft and sp 3. Perforate at 1895 ft and sp 100 ft plug across intermediate 4. Perforate at 1408 ft and sp 100 ft plug across top of Glorid 5. Perforate at 880 ft and spo ft plug across surface casing signature 6. Perforate at 60 ft and spot 14. Thereby certify that the foregoing is Committee Name (Printed/Typed) TINA HUE Signature (Electronic Signature) Approved By Arguman Arguman	cap it with 35 ft cement. T ot a 30 sx Class C cemen e casing shoe, inside and ot a 25 sx Class C cement eta, inside and outside cas t a 25 sx Class C cement shoe, inside and outside cas t a 25 sx Class C cement p with t true and correct. Electronic Submission #2 For YATES PETRO d to AFMSS for processing RTA THIS SPACE FO Manual of this notice does in intable title to those rights in the ct operations thereon. U.S.C. Section 1212, make it a compared to the section U.S.C. Section 1212, make it a compared to the section of the	his puts a plug over Abo. t plug from 1795 ft -1895 ft. outside casing. WOC and t t plug from 1808 ft -1408 ft. sing. plug from 780 ft - 880 ft. Th asing. WOC and tag plug. lug from 60 ft up to surface 42164 verified by the BLM W DLEUM CORFORATION, sent by BEVERLY WEATHERFOF Title REG F Date 04/14/ R FEDERAL OR STATE Title C Title	This puts a tag plug. 2,7 This puts a this puts 100 This puts 100 The puts 100 The prove PROVED TO PROVED TO PROVED	CONDITION Acres FOR 3 FOR 3 FOR 3 FOR 4 (14BMW1660SE) UPERVISOR ACCEPTED E FIELD OFFICE	MONTH PERIO	
C c w	 with tubing. 2. Set a CIBP at 3750 ft and of 3. Perforate at 1895 ft and sp 100 ft plug across intermediat 4. Perforate at 1408 ft and sp 100 ft plug across top of Glorid 5. Perforate at 880 ft and spot ft plug across surface casing s 6. Perforate at 60 ft and spot 14. Thereby certify that the foregoing is Committee Name (<i>Printed/Typed</i>) TINA HUE Signature (Electronic S Approved By Approved By Approved By Conditions of approval, if any, are attacheserify that the coplicant holds legal or equivich would entitle the applicant to conduct fitte 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent sectors.	cap it with 35 ft cement. T ot a 30 sx Class C cemen e casing shoe, inside and ot a 25 sx Class C cement eta, inside and outside cas t a 25 sx Class C cement p withit true and correct. Electronic Submission #2 For YATES PETRO d to AFMSS for processing RTA Mubmission) THIS SPACE FO	his puts a plug over Abo. t plug from 1795 ft -1895 ft. outside casing. WOC and t t plug from 1808 ft -1408 ft. sing. plug from 780 ft - 880 ft. Th asing. WOC and tag plug. lug from 60 ft up to surface 42164 verified by the BLM W DLEUM CORFORATION, sent by BEVERLY WEATHERFOF Title REG F Date 04/14/ R FEDERAL OR STATE Title C Title	This puts a tag plug. L J T This puts a his puts 100 L T T T T T T T T T T T T T T T T T T T	CONDITION hers FOR 3 FOR 3 Yes System / / / / / / System / / / / / System / / / / / / / / / System / / / / / / / / / / System / / / / / / / / / / / / System / / / / / / / / / / / / System / / / / / / / / / / / / / / / / / / /	$\frac{MONTH PERIO}{20 + 4}$	
C c w	 with tubing. 2. Set a CIBP at 3750 ft and of 3. Perforate at 1895 ft and sp 100 ft plug across intermediat 4. Perforate at 1408 ft and sp 100 ft plug across top of Glorid 5. Perforate at 880 ft and spot ft plug across surface casing s 6. Perforate at 60 ft and spot 14. Thereby certify that the foregoing is Committee Name (<i>Printed/Typed</i>) TINA HUE Signature (Electronic S Approved By Approved By Approved By Conditions of approval, if any, are attacheserify that the coplicant holds legal or equivich would entitle the applicant to conduct fitte 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent sectors.	cap it with 35 ft cement. T ot a 30 sx Class C cemen e casing shoe, inside and ot a 25 sx Class C cement eta, inside and outside cas t a 25 sx Class C cement p withit true and correct. Electronic Submission #2 For YATES PETRO d to AFMSS for processing RTA Mubmission) THIS SPACE FO	his puts a plug over Abo. L t plug from 1795 ft -1895 ft. outside casing. WOC and t t plug from 1808 ft -1408 ft. sing. L 77653 plug from 780 ft - 880 ft. Th asing. WOC and tag plug. lug from 60 ft up to surface s 42164 verified by the BLM W DEUM CORFORATION, sent by BEVERLY WEATHERFOF Title REG F Date 04/14/ R FEDERAL OR STATE office crime for any person knowingly an to any matter within its jurisdiction	This puts a tag plug. L J T This puts a his puts 100 L T T T T T T T T T T T T T T T T T T T	CONDITION hers FOR 3 FOR 3 Yes System / / / / / / System / / / / / System / / / / / / / / / System / / / / / / / / / / System / / / / / / / / / / / / System / / / / / / / / / / / / System / / / / / / / / / / / / / / / / / / /	$\frac{MONTH PERIO}{20 / 4}$	

Additional data for EC transaction #242164 that would not fit on the form

32. Additional remarks, continued

7. Remove all surface equipment, weld dry hole marker and clean location as per regulations.

Wellbore schematics attached

Ŀ

Revisions to Operator-Submitted EC Data for Sundry Notice #242164

ŝ

. L


.;

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	ABD NOI	ABD NOI
Lease:	NMNM14756	NMNM14756
Agreement:		
Operator:	YATES PETROLEUM CORPORATION 105 SOUTH FOURTH STREET ARTESIA, NM 88210 Ph: 575-748-1471	YATES PETROLEUM CORPOR 105 SOUTH 4TH STREET ARTESIA, NM 88210
Admin Contact:	TINA HUERTA REG REPORTING SUPERVISOR E-Mail: tinah@yatespetroleum.com	TINA HUERTA REG REPORTING SUPERVISO E-Mail: tinah@yatespetroleum.co
	Ph: 575-748-4168 Fx: 575-748-4585	Ph: 575-748-4168 Fx: 575-748-4585
Tech Contact:	TINA HUERTA REG REPORTING SUPERVISOR E-Mail: tinah@yatespetroleum.com	TINA HUERTA. REG REPORTING SUPERVISC E-Mail: tinah@yatespetroleum.c
	Ph: 575-748-4168 Fx: 575-748-4585	Ph: 575-748-4168 Fx: 575-748-4585
Location: State: County:	NM CHAVES	NM CHAVES
Field/Pool:	PECOS SLOPE; ABO	PECOS SLOPE-ABO
Well/Facility:	GERRY FEDERAL 1 Sec 1 T8S R25E NWNW 660FNL 660FWL	GERRY FEDERAL 1 Sec 1 T8S R25E NWNW 660FN


ABD NOI NMNM14756 YATES PETROLEUM CORPORATION 105 SOUTH 4TH STREET ARTESIA, NM 88210 TINA HUERTA REG REPORTING SUPERVISOR E-Mail: tinah@yatespetroleum.com Ph: 575-748-4168 Fx: 575-748-4585

TINA HUERTA. REG REPORTING SUPERVISOR E-Mail: tinah@yatespetroleum.com

GERRY FEDERAL 1 Sec 1 T8S R25E NWNW 660FNL 660FWL



•



BUREAU OF LAND MANAGEMENT

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90th day provide the BLM Roswell Field Office, prior to the 90th day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can. expect the well to be plugged. Failure to do so will result in enforcement action.

2. <u>Notification:</u> Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours call (575) 627-0205 or after office hours call (575) 420-2832. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10 feet in length, 4 feet above the ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged**.

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.