

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Righthand Canyon 35-7 SWD Battery	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	API No. 30-015-34529 (nearest well)

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	35	21S	24E					Eddy County, NM

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

#### NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	800 bbls	Volume Recovered	720 bbls
Source of Release	Bad service card on PLC caused power loss to pumps so tanks spilled over	Date and Hour of Occurrence	01/01/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD, James Amos-BLM		
By Whom?	Jennifer Gilkey, BBC International	Date and Hour	01/02/2014 @ 1:58 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*



A bad service card on the PLC caused a power loss to the pumps causing the tanks to spill 800 bbls of produced water onto the ground. 720 bbls of produced water were recovered via vacuum truck and the service card was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 60' x 100' on location. Remediation was completed in accordance with a remediation plan approved by Mike Bratcher of NMOCD via email on 11/13/2012 and approved by James Amos of the BLM via email on 12/17/2012.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor: 		
Printed Name: Christopher Jones	Approval Date: 5/16/14	Expiration Date: NA	
Title: HES Specialist	Conditions of Approval: Final		
E-mail Address: Christopher_Jones@oxy.com	Attached <input type="checkbox"/>		
Date: 2/12/14	Phone: (575) 628-4121		

\* Attach Additional Sheets If Necessary

22P-2152

leak 2