

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP 1416430522

Name of Company Devon Energy		OPERATOR Roy White	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address PO Box 250 Artesia, NM 88211		Telephone No. 575-748-3371	
Facility Name Burton Flats 52-56 Battery		Facility Type Oil	
Surface Owner Federal		Mineral Owner Federal	API No. 30-015-40693

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	3	21S	27E	4000	FNL	50	FEL	Eddy

Latitude: _____ Longitude: _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 5 BBLs	Volume Recovered 5 BBLs
Source of Release Treads on water tank fill line corroded causing a spill.	Date and Hour of Occurrence 6/4/2014 3:00 AM	Date and Hour of Discovery 6/4/2014 3:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jennifer Vancuerin BLM & left message with Karen West OCD	
By Whom? Mike McMahan	Date and Hour 4/5/2014 2:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully.*		

NM OIL CONSERVATION
ARTESIA DISTRICT

JUN 09 2014

Describe Cause of Problem and Remedial Action Taken.*

RECEIVED

Oil hauler was getting a load of oil and noticed the leak. 5 bbls of produced water was all in contained area. He immediately called the flowback hand who in turn called the lease operator. Lease operator showed up on location and immediately shut the wells down. Called a roustabout crew out and fixed the problem within 4 hours.

Describe Area Affected and Cleanup Action Taken.*

Called a vacuum truck and recovered 5BBL produced water from secondary containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>6/13/14</i>	Expiration Date: <i>NA</i>
E-mail Address: Jeanette.barron@dvn.com	Conditions of Approval: Remediation per OGD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	
Date: 6/5/2014 Phone: 575-748-1813	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

7/13/14

2RP-2343