Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
District 1 – (575) 393-6161	Energy, Minerals and Natural Re	esources	Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL AI 30-015-03		
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIV		te Type of Lease	
<u>District III</u> – (505) 334-6178	1220 South St. Francis I	11*	ATE X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505		Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM		B-1266	on & Gas Bease No.	
87505	IOEC AND DEPONTS ON WELLS	7.1	Name and Marie Advanced Name	
	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BA		Name or Unit Agreement Name	
	CATION FOR PERMIT" (FORM C-101) FOR SUC	N	Γ COOP UNIT	
PROPOSALS.)		8. Well N		
1. Type of Well: Oil Well X	Gas Well Other	028	dunioci	
2. Name of Operator			O Number	
COG OPERATING LLC		229137		
3. Address of Operator			name or Wildcat	
600 W. ILLINOIS AVE., MIDLA	ND, TEXAS 79701	GJ; 7RVS	G-QN-GB-S.A.	
4. Well Location				
Unit Letter; L ;	1650 feet from the SOUTH line a	and 990 feet from the	e WEST line	
Section 22	Township 17S R	ange 29E N	NMPM EDDY County	
	11. Elevation (Show whether DR, RKB	RT, GR, etc.)		
	3,548' - GR			
12. Check	Appropriate Box to Indicate Nature	of Notice, Report or	Other Data	
NOTICE OF IN	ITENTION TO:	CLIDCECLIEN	IT DEDORT OF:	
	ITENTION TO:	MEDIAL WORK	NT REPORT OF: ☐ ALTERING CASING ☐	
PERFORM REMEDIAL WORK		•		
TEMPORARILY ABANDON DULL OR ALTER CASING		MMENCE DRILLING OPN		
PULL OR ALTER CASING	MULTIPLE COMPL CAS	SING/CEMENT JOB		
DOWNHOLE COMMINGLE				
OTHER:	□ OTH	IER:		
13. Describe proposed or comp	oleted operations. (Clearly state all pertine			
	ork). SEE RULE 19.15.7.14 NMAC. For	· Multiple Completions:	Attach wellbore diagram of	
proposed completion or rec	completion.			
1) SET 5 1/2" CIRD @ 2 250	'. DUMD 45 SYS CMT @ 2 250' 2 010'	· CIRC WELL W/ DYA	MUD	
 SET 5-1/2" CIBP @ 2,250'; PUMP 45 SXS. CMT. @ 2,250'-2,010'; CIRC. WELL W/ PXA MUD. PRES. TEST 5-1/2" CSG. TO 500# X HOLD FOR 15 MINS. 				
3) PUMP 35 SXS. CMT. @ 900'-700' (T/YATES, B/SALT); WOC X TAG CMT. PLUG.				
4) PERF. X ATTEMPT TO CIRC. TO SURF. 130 SXS. CMT. @ 357'-3' (8-5/8" CSG.SHOE, T/SALT0>				
5) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER.				
DUDDIC THE DROCEDING WE	DI ANITO LICE THE CLOSED LOOP C	VOTEM W/ A OTERL'T	ANIC AND HALL CONTENTS	
TO THE REQUIRED DISPOSAL,	PLAN TO USE THE CLOSED-LOOP S	YSIEM W/ A SIEEL I.	ANK AND HAUL CONTENTS	
CONDITIONS OF APPROVAL ATTAC		•	NM OIL CONSERVATION	
			ARTESIA DISTRICT	
Approval Granted providing wor	k is Rig Release Date:			
Completed by			JUN 1 7 2014	
6-24-20	015			
r notody cortify that the intermeden	true and complete to the best of	my knowledge and belief	RECEIVED	
		•		
SIGNATURE (TITLE: AGENT		DATE: 06/14/14	
SIGNATURE JAME	TILE. AGENT		DATE: 00/14/14	
Type or print name: DAVID A. EY	LER E-mail address: DEYLER	@MILAGRO-RES.COM	PHONE: 432.687.3033	
For State Use Only	\			
ADDD OVED THE	rollo ministration	4 Y Du 1/Sh	DUM 6/14/14	
APPROVED BY (/ // // Conditions of Approval (if any):	117LE //3/1	yan'ar	DATE_6/29/19	
Conditions of Approval (II any):			· /	
	11/20/201/	////c		
(A) VOO	/+/77/10/00 ()	<i>'기</i> 7)		
of CEC.				
1 4				

Concho

Lease & Well # GJ West COOP Unit # 28 30-015-03039 Spud - 10/27/58 KB-Elevation - 3548' 8 5/8" 24# @ 307', 50 sx cmt. Top of cmt @2100', survey. perf'd @ 2070', cemented with 3,150 sx to stop water flow. Perfs: GB/SA 2252 - 2561 (re-perf) Frac w/25,000 gal GW, 25,000 # sd 2392-2412 Acidized w/500 gal MCA Frac w/20,000 gal GW, 16,500 # sd San Andres 2676-2828 Acidized w/5000 gal IM-38, 500 gal MCA Acidized w/10,000 gal 15% NEFE PBTD-3253' 5 1/2" 15.5# csg @ 3139', cmt w/2010 sx. Top of cmt @ 2100', survey. San Andres Fraced w/34,000 gal oil, 30,000 # sd

OH TD @ 3253

Concho


Lease & Well #

GJ West COOP Unit # 28

Spud - 10/27/58

30-015-03039

Elevation - 3548'



DAE 06/14/14

OH TD @ 3253

PBTD-3253'

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: COG	
Well Name & Number: 6J West Coop Unit	28
API#: 30 - 0/5- 03039	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 6/24/14

APPROVED BY:

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub
 plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).