4	• • • • •	and a second					
DEPARTMENT	(August 2007) * UNITED STATES		APPROVED O. 1004-0135 July 31, 2010				
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.		5. Lease Serial No. NMNM18626	5. Lease Serial No. NMNM18626				
		6. If Indian, Allottee of	6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on reverse side.		7. If Unit or CA/Agre	ement, Name and/or No.				
 1. Type of Well ☐ Oil Well		8. Weil Name and No. SPITFIRE 25 1	SPITFIRE 25 1				
2. Name of Operator Contact: JODY NOERDLINGER RKI EXPLORATION & PRODUCTION E-Mail: jnoerdlinger@rkixp.com		9. API Well No. 30-015-25450	30-015-25450				
3a. Address3b. Phone No. (include area code)210 PARK AVE. SUITE 900Ph: 405-996-5774OKLAHOMA CITY, OK 73102Ph: 405-996-5774) 10. Field and Pool, or WOLFCAMP	10. Field and Pool, or Exploratory WOLFCAMP				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish,	11. County or Parish, and State				
Sec 25 T26S R30E Mer NMP SWNE 1980FN	IL 1980FEL	EDDY COUNTY	Υ, NM				
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION						
 ☑ Notice of Intent ☑ Acidize ☑ Alter Casi 	ing Deepen	 Production (Start/Resume) Reclamation 	 Water Shut-Off Well Integrity 				
□ Subsequent Report □ Casing Re	pair 🛛 New Construction	🛛 Recomplete	Other				
Final Abandonment Notice Change Pl Convert to		 Temporarily Abandon Water Disposal 	·				
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) RKI Exploration and Production requests approval to recomplete the subject well in the Delaware formation. Proposed recompletion procedure:							
Proposed recompletion procedure:		JUI	V 3 0 2014				
Proposed recompletion procedure: Set 4 1/2 inch 10K# CIBP at 12,150 feet. Cut 4 1/2 inch 10K CIBP at 9,075 feet. Cut 4 1/2 inch casing at 9,025 feet. Pull 4 1/2 inch pipe. Durchail Seacks cement on plug. Run CEL from 7,500 feet to TOC. Perf and stimulate from 6,596 feet to 6,610 feet. Perf and stimulate from 5,801 feet to 5,815 feet. Put well on rod pump production.							
				A			
				FILE CIOZ NMOCD JE76-30"			
14. I hereby certify that the foregoing is true and correct. Electronic Submission #243080 verified by the BLM Well Information System For RKI EXPLORATION & PRODUCTION, sent to the Carlsbad							
Committed to AFMSS for processing by ANGEL MAYES on 05/29/2014 ()							
Name (Printed/Typed) JODY NOERDLINGER	Title REGUL						
Signature (Electronic Submission)	Date 04/22/20						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
_Approved By		UUN 2 3 20	HAR AND				
Conditions of approval, if any, are attached. Approval of this certify that the applicant holds legal or equitable title to those which would entitle the applicant to conduct operations there	rights in the subject lease Office	BUDEAU OF LAND MAN					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							


** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Additional data for EC transaction #243080 that would not fit on the form


32. Additional remarks, continued

Ì

Please see attached current and proposed well bore diagrams.



Ì



Spitfire 25 1 30-015-25450 RKI Exploration & Production LLC June 23, 2014 Conditions of Approval

Work to be completed by September 23, 2014.

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

- 1. Operator shall set CIBP at 12,150' with a minimum of 25sx Class H cement on top to cover the shoe. Tag at a minimum of 11,860' required.
- 2. Operator shall set solid Class H Cement plug from 11,100'-10,890' to seal the top of the Wolfcamp formation.
- 3. Operator shall set CIBP at 9,075' (a minimum of 50' below stub) with a minimum of 40sx Class H cement on top. Tag required at a minimum of 8,870'.
- 4. Submit results of the CBL to the BLM. <u>If there is no or little cement behind casing</u> <u>at the interval of the following plug and/or production interval operator may not</u> <u>continue without consulting with the BLM.</u>
- 5. Operator shall set solid Class II Cement plug from 7,650'-7,474' to seal the top of the Bone Spring formation.
- 6. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 7. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.

8. Surface disturbance beyond the originally approved pad must have prior approval.

9. Closed loop system required.

10. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.

- 11. Operator to have H2S monitoring equipment on location.
- 12. A minimum of a **3000** (**3M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 13. Subsequent sundry required detailing work done and completion report for the new formation. Operator to include well bore schematic of current well condition when work is complete.

14. See attached for general requirements.

JAM 062314

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

General Requirements for Plug Backs

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. **Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class** "C", for up to 7,500 feet of depth or **Neat Class** "H", for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting</u>: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed</u>.

7. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.