Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD	Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

	ΕX	pires:	Jul
Lease Seri	al l	Vo.	
A LEAR LEAG		^-	

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			NMNM35607			
			If Indian, Allottee or Tribe Name If Unit or CA/Agreement, Name and/or No.			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.						
1. Type of Well				8. Well Name and No.		
⊠ Oil Well □ Gas Well □ Other				UCBHWW FEDE	HAL /	
Name of Operator Contact: JODY NOERDLINGER RKI EXPLORATION & PROD LLC E-Mail: jnoerdlinger@rkixp.com			9. API Well No. 30-015-25313-00-S1			
3a. Address 210 PARK AVE SUITE 900 OKLAHOMA CITY, OK 7310	b. Phone No. (include area code h: 405-996-5774	e)	10. Field and Pool, or Exploratory BRUSHY DRAW			
4. Location of Well (Footage, Sec., 7	C., R., M., or Survey Description)			11. County or Parish, and State ;		
Sec 25 T26S R29E NENW				EDDY COUNTY, NM		
				;		
12. CHECK APP	ROPRIATE BOX(ES) TO I	NDICATE NATURE OF	NOTICE, R	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION		TYPE O	F ACTION			
The state of the s	· 🗖 Acidize	☐ Deepen	☐ Produc	tion (Start/Resume)	☐ Water Shut-	Off
Notice of Intent	☐ Alter Casing	☐ Fracture Treat	Reclan	nation	─ Well Integrit	ty
☐ Subsequent Report	□ Casing Repair	■ New Construction	Recom	plete .	Other	
☐ Final Abandonment Notice	Change Plans	□ Plug and Abandon	☐ Tempo	rarily Abandon		
	☐ Convert to Injection	Plug Back	■ Water :	Disposal		•
determined that the site is ready for f RKI Exploration and Production these proposed procedures: Clean out well bore, test casing the perf Delaware from 5,844 feet	on requests permission to rec	Surface	SE	ACCE E ATTACHE NDITIONS		7
Perf Delaware from 5,844 feet Fracture/stimulate with 57,000			icid.			
Perf Delaware from 5,556 feet Fracture/stimulate with 51,550	to 5604 feet. Acidize with 2, gals fluid and 85,000 lbs pro	000 gallons 15% NEFE acoppant.	cid.	NM OIL CONS ARTESIA DI	ERVATION STRICT	
				JUL 14	2014	
_	Electronic Submission #2504 For RKI EXPLORAT mitted to AFMSS for processin	ION & PROD LLC, sent to t ig by JENNIFER MASON or	the Carlsbad 1 07/09/2014	(14JAM035BECEIV	/ED	
Name(Printed/Typed) JODY NC	DERDLINGER	Title REGUL	ATORY AN	ALYSI		
Signature (Electronic S	Submission)	Date 06/23/2	014	APPRO	VED_	
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE U	SE	/	
_Approved By		Title			2014	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductive the applicant to conductive the applicant to conductive the applicant to conduct	itable title to those rights in the sub			BURFAU OF /AND N ARLSD/D FIEL	NAGEMENT D OFFICE	
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a crim	e for any person knowingly and	willfully to m	ake to any department or a	agency of the United	

Additional data for EC transaction #250453 that would not fit on the form

32. Additional remarks, continued

Install pump and revamped surface electric equipment.

RKI proposes to complete the work by July 23, 2014.

UCBHWW Federal 7 30-015-25313 RKI Exploration & Production LLC July 09, 2014 Conditions of Approval

Work to be completed by October 09, 2014.

Notify BLM at 575-393-3612 a minimum of 24 hours prior to commencing work.

- 1. Submit results of the CBL to the BLM (CBL is to be run from TD to surface). <u>If</u> <u>TOC is below 4500 feet the operator may not continue without consulting with the BLM.</u>
- 2. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.

Note: If operator is fracturing down tubing. The casing shall be tested per Onshore Order 2.III.B.1.h

- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.

- 8. A minimum of a **2000** (**2M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 9. Subsequent sundry required detailing work done and completion report for the additional pay. Operator to include well bore schematic of current well condition when work is complete.

JAM 070914