Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Artesia

FORM APPROVED OMB No. 1004-0137 2014

	Expires: October 31,
5. Lease Serial No. NM 91502	


SUNDRY NOTICES AND REPORTS ON WELLS


Do not use this form for proposals to drill or to re-enter an

6. If Indian, Allottee or Tribe Name N/A

abandoned well.	Use Form 3160-3 (Al	PD) for such pi	oposais.					
SUBMIT IN TRIPLICATE – Other instructions on page 2.				1	7. If Unit of CA/Agreement, Name and/or No. N/A			
1. Type of Well Oil Well Gas W	/eil Other			8. V	Vell Name and No. BULLSEYE FEDE	RAL#1 (303	3796	
2. Name of Operator NADEL AND GUSSMAN PERMIAN, L.L.C. (155615)			9. A	9. API Well No. 30-015-28919				
3a. Address 601 NORTH MARIENFELD, SUITE 508 MIDLAND, TX 79701 3b. Phone No. (include area code) (432) 682-4429				10. Field and Pool or Exploratory Area INDIAN LOAFER DRAW; UPPER PENN				
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1880' FNL, 660' FEL, SEC. 28, T21S, R22E				11. County or Parish, State EDDY CO., NM				
12. CHEC	K THE APPROPRIATE BO	X(ES) TO INDICAT	E NATURE OF 1	NOTICE, R	REPORT OR OTHE	ER DATA	-	
TYPE OF SUBMISSION TYPE OF ACT								
✓ Notice of Intent	Acidize Alter Casing	Deepen Fracture Tre	at	Reclamati		Water Shut-Of Well Integrity	f	
Subsequent Report	Casing Repair	New Constr		Recomple		Other		
Final Abandonment Notice	Change Plans Convert to Injection	☐ Plug and At ✓ Plug Back	andon	Temporar Water Dis	ily Abandon posal			
DETERMINED THE SITE IS READY FOR MIRU PULLING UNIT. RIH WITE EXISTING MORROW PERFS APPROXIMATE START DATE APPROXIMATE DURATION - 7	TH TUBING TO PBTD +- 9 ARE AT 9,007'-9,027'. WIT PSTX TAG 7307'-7418' AND ACIDIZE NYON TOP JUNE 1, 2014	H TUBING @ +- 91 E WITH 5000 GAL (ISCO) S (2) NM O	7550 Pe	C Con	npletion N	,	OR	
BLM BOND # NM 2812	Accepted for NMOC	record	JUL 142	:014 =D	CONDI	HONS OF		
14. I hereby certify that the foregoing is to	rue and correct. Name (Printed	l/Typed)	- 112023			-		
SARAH PRESLEY		Title	REGULATOR	RY ANALY	ST	NEW / N		
Signature Swahpus	ly	Date	04/07/2014		AP	PRUVEU		
	THIS SPACE	FOR FEDERAL	OR STATE	OFFIC	EUSE //	0/2014/	<u>b</u>	
Approved by Conditions of approval, if any, are attached that the applicant holds legal or equitable to entitle the applicant to conduct operations. Title 18 U.S.C. Section 1001 and Title 43	itle to those rights in the subjecthereon.	t lease which would	Title Office	 fully to ma	BUYEAU OF CARLSE	AND FIELD OFFICE		
fictitious or fraudulent statements or repre			nowingly and will	nuny to ma	ac toyany departmen	tor agency of the Office	A states any raise,	

Provide CIOZ to NMOCD





Bullseye Federal 30-015-28919 Nadel and Gussman Permian, L.L.C. July 09, 2014 Conditions of Approval

Work to be completed by October 09, 2014.

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

- 1. Operator shall set CIBP at 8,957' with a minimum of 25sx Class H cement on top. Tag at a minimum of 8,760' required.
- 2. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.

Note: If operator is fracturing down tubing. The casing shall be tested per Onshore Order 2.III.B.1.h

- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a **3000** (**3M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

9. Subsequent sundry required detailing work done and completion report for the new formation. Operator to include well bore schematic of current well condition when work is complete.

10. See attached for general requirements.

JAM 070914

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

General Requirements for Plug Backs

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class** "C", for up to 7,500 feet of depth or **Neat Class** "H", for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting</u>: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.