

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 27097
7. Lease Name or Unit Agreement Name Walker 33 State
8. Well Number 1
9. OGRID Number 24010
10. Pool name or Wildcat Travis Bone Springs (97257)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

V-F Petroleum Inc.

3. Address of Operator

P.O. Box 1889, Midland, Texas 79702

4. Well Location

Unit Letter K: 1650 feet from the South line and 1650 feet from the West line

Section 33 Township 18-S Range 28-E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3544 GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Pull all production equipment.
2. Set RBP @ 7,900'.
3. 3rd Bone Springs Carbonate Perforations from Cased Hole Log: 7,755' to 7,815' OA.
4. Acidize with 2,400 gallons 15% NeFe HCl acid.
5. Swab back acid & test.
6. Put well on production.

NM OIL CONSERVATION


ARTESIA DISTRICT

JUL 25 2014

RECEIVED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE Engineering Technician

DATE: 07/22/2014

Type or print name Eric Sprinkle

E-mail address: eric@vfpetroleum.com

PHONE: 432-683-3344

For State Use Only

APPROVED BY:



TITLE District Supervisor

DATE 7-29-14

Conditions of Approval (if any):