Office	State of New Me	ex1co	Form C-10	
• <u>District 1</u> – (575) 393-6161	Energy, Minerals and Nati	ural Resources	Revised July 18, 20	13
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> – (575) 748-1283	OIL CONSERVATION	MOISIMIGE	30-015-34639	
811 S. First St., Artesia, NM 88210			5. Indicate Type of Lease	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fra		STATE  FEE	
District IV – (505) 476-3460	Santa Fe, NM 8	7505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
	CES AND REPORTS ON WELLS	S	7. Lease Name or Unit Agreement Name	_
(DO NOT USE THIS FORM FOR PROPOS			Frey BIR	
DIFFERENT RESERVOIR. USE "APPLIC	CATION FOR PERMIT" (FORM C-101) F	OR SUCH	8. Well Number	
PROPOSALS.)			8. Well Number	
1. Type of Well: Oil Well	Gas Well 🛛 Other		1	
2. Name of Operator			9. OGRID Number	
Yates Petroleum Corporation			025575	
3. Address of Operator			10. Pool name or Wildcat	
105 South Fourth Street, Artesia, N	M 88210		Eagle Creek; Permo Penn	
4. Well Location	<del></del>			
Unit Letter P:	660 feet from the Sout	h line and	710 feet from the East line	e
Section 13	Township 17S Ra	ange 25E	NMPM Eddy County	
	11. Elevation (Show whether DF	R, RKB, RT, GR, etc		
	el '	ı' GR		
Security (2) Co. 187 F 2207 Last Co. Types Company (2) 1990 Security (2) 1990 Securi	<u> </u>			
12. Check A	Appropriate Box to Indicate N	Nature of Notice.	Report or Other Data	
			•	
NOTICE OF IN			SSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🛛	REMEDIAL WOR	RK	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	RILLING OPNS.□ P AND A □	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	IT JOB 🔲	
DOWNHOLE COMMINGLE	_			
CLOSED-LOOP SYSTEM				
OTHER:		OTHER:	Г	٦
	leted operations (Clearly state all		nd give pertinent dates, including estimated of	<u> </u>
			ompletions: Attach wellbore diagram of	iau
		.c. For Muniple Co	ompletions. Attach welloofe diagram of	
proposed completion or rec	ompletion.			
Vita Ditalon Comments along		11		
Yates Petroleum Corporation plans t			TOTAL CLASS	
	U BOP. Release packer. TIH to 6	•		
	basket to 7,610' and set a CIBP at	7,600'. Cap it with	25 sx Class "H" cement.	
	up it with 25 sx Class "H" cement.			
			olfcamp. WOC and tag. Spot a 130' Class "C	
	500'. WOC and tag. Spot a 120'	Class "C" cement p	lug from 1,180'-1,300'. Spot a 100' Class "	C"
cement plug at surface.	CONDIT	IONS OF APPROVA	L ATTACHED	
5. Cut off wellhead, install ma	irker and clean location.	ions of All the Vi	2711131112	
XX 10 1 2 4 1 1	Approv	al Granted provid	ling work is	
Wellbore schematics attached		•	COMPERANTION	
	Comple	eted by 1 0 10	resia district	
		Julyda	- <del> </del>	
		, , , , , , , , , , , , , , , , , , ,	JUL <b>2</b> 3 2014	
Spud Date:		)ate:		
-	Rig Release D	atc.		
	Kig Release L	rate.	DECEIVED.	
	Kig Release L	vate.	RECEIVED	
I hereby certify that the information		,		
I hereby certify that the information		,		
-/- 1,	above is true and complete to the b	pest of my knowleds	ge and belief.	
I hereby certify that the information	above is true and complete to the b	pest of my knowleds		
-/- 1,	above is true and complete to the b	pest of my knowleds	ge and belief.	
-/- 1,	above is true and complete to the b	pest of my knowleds	ge and belief.  Fechnician DATE July 23, 2014	
SIGNATURE AND Laura W.	above is true and complete to the b	pest of my knowledg	ge and belief.  Fechnician DATE July 23, 2014	
SIGNATURE Jame M	above is true and complete to the b	pest of my knowledg	ge and belief.    Fechnician   DATE   July 23, 2014	
SIGNATURE AND Laura W.	above is true and complete to the b	pest of my knowledg	ge and belief.  Fechnician DATE July 23, 2014	

\$ See Attached COA'S


Well Name: Frey BIR #1 Field: Eagle Creek
Location: 660' FSL & 710' FEL Sec 13-17S-25E


County: Eddy State: New Mexico
GL: 3,441' Zero: KB: 3,459'

Spud Date: <u>2/27/2006</u> Completion Date: <u>4/23/2006</u>

Comments: API # 30-015-34639

<b>BEFORE</b>	





DATE: 4/8/2014

Well Name: Frey BIR #1 Field: Eagle Creek Location: 660' FSL & 710' FEL Sec 13-17S-25E

County: Eddy State: New Mexico
GL: 3,441' Zero: KB: 3,459'

Spud Date: <u>2/27/2006</u> Completion Date: <u>4/23/2006</u>

Comments: API # 30-015-34639

## AFTER

100' Cement plug at


Casing Program

Size/Wt/Grade Depth Set

13 %" 48# H-40 377'

9 %" 36# J-55 1,246'

5 ½" 15.5#-& 17# J-55 & 8,350'
HCP-110 8,350'



# NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

### CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Vates	·
Well Name & Number: FRey BIR	Z/
API #: 30-0/5-34639	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 7-29-2014

APPROVED BY: ADad.

#### GUIDELINES FOR PLUGGING AND ABANDONMENT

### DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
  - o Fusselman
  - o Devonian
  - o Morrow
  - o Wolfcamp
  - o Bone Spring
  - o Delaware
  - Any Salt Section (Plug at top and bottom)
  - o Abo
  - o Glorieta
  - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).