Form 3160-5	UNITED STATE				FORM APPROVED OMB No. 1004-0137		
	PARTMENT OF THE I	· · ·	· ·		Expires: July 31, 2010		
BUREAU OF LAND MANAGEMENT		AGEMENT		5. Lease Serial No NMNM86024	).		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name			
SUBMI	T IN TRIPLICATE – Other	instructions on page 2	2.	7. If Unit of CA/A	greement, Name and/or No.		
Type of Well		· · · · · · · · · · · · · · · · · · ·			·		
🔲 Oil Well 🔀 Gas V	Vell Other			8. Well Name and Cochiti 28 Fede			
, Name of Operator Devon Energy Production Company, L.P.			· · · · ·		9. API Well No. 30-015-30113		
a. Address 33 West Sheridan Avenue		3b. Phone No. (include area code)		10. Field and Pool or Exploratory Area			
klahoma City, OK 73102		405-552-3364		· · · · · · · · · · · · · · · · · · ·	SWD; Bell Canyon		
Location of Well (Footage, Sec., T., R., M., or Survey Description) 980' FNL 660' FWL Section 28-235-29E					11. Country or Parish, State Eddy, NM		
12. CHEC	CK THE APPROPRIATE BO	DX(ES) TO INDICATE	NATURE OF NOT	ICE, REPORT OR C	THER DATA		
TYPE OF SUBMISSION			TYPE OF A	TION	· · · · · · · · · · · · · · · · · · ·		
Notice of Intent	Acidize	Deepen	_	oduction (Start/Resum	·		
·	Alter Casing	Fracture Treat		clamation	Well Integrity		
Subsequent Report "	Casing Repair	New Construct		complete	Other MIT Tes	it	
Final Abandonment Notice	Change Plans	Plug and Aban	_	mporarily Abandon			
the proposal is to deepen direction Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready fo	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.)	ly, give subsurface locat ovide the Bond No. on fil on results in a multiple c be filed only after all req	ions and measured le with BLM/BIA. ompletion or recor uirements, includin	and true vertical dept Required subsequen ppletion in a new inte g reclamation, have l	hs of all pertinent markers a t reports must be filed within rval, a Form 3160-4 must be	nd zones. 1 30 days 1 filed once	
the proposal is to deepen direction Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready fo	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.)	ly, give subsurface locat ovide the Bond No. on fil on results in a multiple c be filed only after all req	ions and measured le with BLM/BIA. ompletion or recor uirements, includin	and true vertical dept Required subsequen ppletion in a new inte g reclamation, have l	hs of all pertinent markers a t reports must be filed within rval, a Form 3160-4 must be	nd zones. 1 30 days 1 filed once	
the proposal is to deepen direction Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready fo	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.)	ly, give subsurface locat ovide the Bond No. on fil on results in a multiple c be filed only after all req	ions and measured le with BLM/BIA. ompletion or recor uirements, includin	and true vertical dept Required subsequen opletion in a new inte g reclamation, have l CD.	hs of all pertinent markers a t reports must be filed within rval, a Form 3160-4 must be been completed and the oper	nd zones. 130 days filed once ator has	
the proposal is to deepen direction Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready fo	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must b r final inspection.) ) psi for 30 minutes, Good	ly, give subsurface locat ovide the Bond No. on fil on results in a multiple c be filed only after all req MIT test witnessed by	ions and measured le with BLM/BIA. ompletion or recor uirements, includin	and true vertical dept Required subsequen opletion in a new inte g reclamation, have l CD.	the of all pertinent markers a t reports must be filed within rval, a Form 3160-4 must be been completed and the oper completed and the oper	nd zones. a 30 days filed once ator has ATION	
the proposal is to deepen direction Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready fo	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.) b psi for 30 minutes, Good be minutes, Good be mi	ly, give subsurface locat: ovide the Bond No. on fi on results in a multiple c be filed only after all req MIT test witnessed by	ions and measured le with BLM/BIA. ompletion or recor uirements, includin	and true vertical dept Required subsequen opletion in a new inte g reclamation, have l CD.	the of all pertinent markers a t reports must be filed within rval, a Form 3160-4 must be been completed and the oper <b>IM OIL CONSERV</b> ARTESIA DISTRIC	nd zones. a 30 days filed once ator has <b>ATION</b> T	
the proposal is to deepen direction Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready fo	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must b r final inspection.) ) psi for 30 minutes, Good	ly, give subsurface locat: ovide the Bond No. on fi on results in a multiple c be filed only after all req MIT test witnessed by	ions and measured le with BLM/BIA. ompletion or recor uirements, includin	and true vertical dept Required subsequen opletion in a new inte g reclamation, have l CD.	the of all pertinent markers a t reports must be filed within rval, a Form 3160-4 must be been completed and the oper completed and the oper	nd zones. a 30 days filed once ator has <b>ATION</b> T	
the proposal is to deepen direction Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready fo	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.) b psi for 30 minutes, Good be minutes, Good be mi	ly, give subsurface locat: ovide the Bond No. on fi on results in a multiple c be filed only after all req MIT test witnessed by	ions and measured le with BLM/BIA. ompletion or recor uirements, includin	and true vertical dept Required subsequen opletion in a new inte g reclamation, have l CD.	the of all pertinent markers a t reports must be filed within rval, a Form 3160-4 must be been completed and the oper <b>IM OIL CONSERV</b> ARTESIA DISTRIC	nd zones. a 30 days filed once ator has ATION T	
the proposal is to deepen direction Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready fo	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.) b psi for 30 minutes, Good be minutes, Good be mi	ly, give subsurface locat: ovide the Bond No. on fi on results in a multiple c be filed only after all req MIT test witnessed by	ions and measured le with BLM/BIA. ompletion or recor uirements, includin	and true vertical dept Required subsequen opletion in a new inte g reclamation, have l CD.	the of all pertinent markers a t reports must be filed within rval, a Form 3160-4 must be been completed and the oper <b>IM OIL CONSERV</b> ARTESIA DISTRIC JUL <b>3 1</b> 2014	nd zones. a 30 days filed once ator has ATION T	
the proposal is to deepen direction Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo 18/14 - Pressure up casing to 500	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.) b psi for 30 minutes, Good be psi for 30 minutes, Bo for 30 minutes, Good be psi for 30 minutes, Bo for	ly, give subsurface locat: ovide the Bond No. on fi on results in a multiple c be filed only after all req MIT test witnessed by	ions and measured le with BLM/BIA. ompletion or recor uirements, includin	and true vertical dept Required subsequen opletion in a new inte g reclamation, have l CD.	the of all pertinent markers a t reports must be filed within rval, a Form 3160-4 must be been completed and the oper <b>IM OIL CONSERV</b> ARTESIA DISTRIC JUL <b>3 1</b> 2014	nd zones. a 30 days filed once ator has ATION T	
the proposal is to deepen direction Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo 18/14 - Pressure up casing to 500 18/14 - Pressure up casing to 500	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.) b psi for 30 minutes, Good be psi for 30 minutes, Bo for 30 minutes, Good be psi for 30 minutes, Bo for	ly, give subsurface locat ovide the Bond No. on fi on results in a multiple c be filed only after all req MIT test witnessed by /2-/Y f record D	ions and measured le with BLM/BIA. ompletion or recor uirements, includin Richard Inges/O	and true vertical dept Required subsequen apletion in a new inte g reclamation, have l CD.	the of all pertinent markers a t reports must be filed within rval, a Form 3160-4 must be been completed and the oper <b>IM OIL CONSERV</b> ARTESIA DISTRIC JUL <b>3 1</b> 2014	nd zones. a 30 days filed once ator has ATION T	
the proposal is to deepen direction Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo 18/14 - Pressure up casing to 500 18/14 - Pressure up casing to 500	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.) b psi for 30 minutes, Good be psi for 30 minutes, Bo for 30 minutes, Good be psi for 30 minutes, Bo for	ly, give subsurface locat ovide the Bond No. on fi on results in a multiple c be filed only after all req MIT test witnessed by /2-/Y f record D	ions and measured le with BLM/BIA. ompletion or recor uirements, includin	and true vertical dept Required subsequen apletion in a new inte g reclamation, have l CD.	the of all pertinent markers a t reports must be filed within rval, a Form 3160-4 must be been completed and the oper <b>IM OIL CONSERV</b> ARTESIA DISTRIC JUL <b>3 1</b> 2014	nd zones. a 30 days filed once ator has ATION T	
the proposal is to deepen direction Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo 18/14 - Pressure up casing to 500 18/14 - Pressure up casing to 500	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.) b psi for 30 minutes, Good be psi for 30 minutes, Bo for 30 minutes, Good be psi for 30 minutes, Bo for	ly, give subsurface locat: ovide the Bond No. on fi on results in a multiple c be filed only after all req MIT test witnessed by /2-/Y # I@COTCI D	ions and measured le with BLM/BIA. ompletion or recor uirements, includin Richard Inges/O	and true vertical dept Required subsequen opletion in a new inte g reclamation, have b CD.	the of all pertinent markers a t reports must be filed within rval, a Form 3160-4 must be been completed and the oper <b>IM OIL CONSERV</b> ARTESIA DISTRIC JUL <b>3 1</b> 2014	nd zones. a 30 days filed once ator has ATION T	
the proposal is to deepen direction Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo 18/14 - Pressure up casing to 500 18/14 - Pressure up casing to 500	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.) b psi for 30 minutes, Good psi for 30 minutes, Good PSI for 30 minutes, Good NMOC	ly, give subsurface locat: ovide the Bond No. on fi on results in a multiple c be filed only after all req MIT test witnessed by /2-/Y # I@COTCI D	ions and measured le with BLM/BIA. ompletion or recor uirements, includin Richard Inges/O Regulatory Analys	and true vertical dept Required subsequen spletion in a new inte g reclamation, have I CD.	the of all pertinent markers a t reports must be filed within rval, a Form 3160-4 must be been completed and the oper ARTESIA DISTRIC JUL 3 1 2014 RECEIVED	nd zones. a 30 days filed once ator has ATION T	
the proposal is to deepen direction Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo '18/14 - Pressure up casing to 500 '18/14 - Pressure up casing to 500	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.) b psi for 30 minutes, Good psi for 30 minutes, Good PSI for 30 minutes, Good NMOC	ly, give subsurface locat: poide the Bond No. on fil on results in a multiple c be filed only after all req MIT test witnessed by /2-/// f I@COTCI D Title F	ions and measured le with BLM/BIA. ompletion or recor uirements, includin Richard Inges/O Regulatory Analys	and true vertical dept Required subsequen spletion in a new inte g reclamation, have I CD.	the of all pertinent markers a t reports must be filed within rval, a Form 3160-4 must be been completed and the oper ARTESIA DISTRIC JUL 3 1 2014 RECEIVED	nd zones. a 30 days filed once ator has ATION T	
the proposal is to deepen direction Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready for /18/14 - Pressure up casing to 500 /18/14 - Press	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.) b) psi for 30 minutes, Good psi for 30 minutes, Good RED 8-/ CODIECTION NMOC	ly, give subsurface locat: povide the Bond No. on fil on results in a multiple c be filed only after all req MIT test witnessed by /2 - / Y f I@CCfci D FOR FEDERAL C	ions and measured le with BLM/BIA. ompletion or recor uirements, includin Richard Inges/O Regulatory Analys 03/24/2014 DR STATE OI	and true vertical dept Required subsequen spletion in a new inte g reclamation, have I CD.	the of all pertinent markers a treports must be filed within rval, a Form 3160-4 must be been completed and the oper ARTESIA DISTRIC JUL 3 1 2014 RECEIVED	nd zones. a 30 days filed once ator has ATION T	
the proposal is to deepen direction Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready for (18/14 - Pressure up casing to 500 (18/14 - Press	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.) b psi for 30 minutes, Good be provided for the second for NMOC THIS SPACE I	ly, give subsurface locat: poide the Bond No. on fill on results in a multiple c be filed only after all req MIT test witnessed by /2 - /Y f I@COTCI D Title F Date C FOR FEDERAL C	ions and measured le with BLM/BIA. ompletion or recor uirements, includin Richard Inges/O Regulatory Analys 03/24/2014 DR STATE OI	and true vertical dept Required subsequen spletion in a new inte g reclamation, have I CD.	the of all pertinent markers a treports must be filed within rval, a Form 3160-4 must be been completed and the oper ARTESIA DISTRIC JUL 3 1 2014 RECEIVED	nd zones. a 30 days c filed once ator has ATION T ORD	
Attach the Bond under which the of following completion of the invol- testing has been completed. Final determined that the site is ready for /18/14 - Pressure up casing to 500 /18/14 - Pressure up casing to 500	ally or recomplete horizontall work will be performed or pro- ved operations. If the operation Abandonment Notices must be r final inspection.) b psi for 30 minutes, Good be minutes, Good be mi	ly, give subsurface locat: poide the Bond No. on fill on results in a multiple c be filed only after all req MIT test witnessed by /2-/Y # I@COTCI D FOR FEDERAL C FOR FEDERAL C Title F Date C FOR FEDERAL C	ions and measured le with BLM/BIA. ompletion or recor uirements, includin Richard Inges/O Regulatory Analys 03/24/2014 DR STATE OI tle	and true vertical dept Required subsequen spletion in a new inte g reclamation, have I CD. The ACCEP FICE USE BUREAL	the of all pertinent markers a treports must be filed within rval, a Form 3160-4 must be been completed and the oper ARTESIA DISTRIC JUL 3 1 2014 RECEIVED TED FOR REC JUN 3 0 2014 JUN 3 0 2014 JUN 3 0 2014 JUN 3 0 2014 JUN 3 0 2014	nd zones. a 30 days c filed once ator has ATION T ORD ENT	

