		OCD Artes	la		
i orm 3160-5 August 2007) DE	UNITED STATES	NTERIOR	· · · · · · · · · · · · · · · · · · ·	ORM APPROVED MB NO. 1004-0135 cpires: July 31, 2010	
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS		5. Lease Serial NMNM386	No.		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				ottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA	7. If Unit or CA/Agreement, Name and/or No	
1. Type of Well			8. Well Name an AMOCO FE		
☐ Oil Well ☐ Gas Well ☑ Oth 2. Name of Operator	Contact:	PAULA BRUNSON	9. API Well No		
CIMAREX ENERGY COMPAI	NY E-Mail: pbrunson@	Dcimarex.com	. 30-015-24	466	
3a. Address 600 N MARIENFELD STE 600 MIDLAND, TX 79701) .	3b. Phone No. (include area code Ph: 432-571-7848		ool, or Exploratory DRAW CHERRY CANY	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description			11. County or P	11. County or Parish, and State	
Sec 27 T26S R29E 1665FSL	330FEL		. EDDY CO	UNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE NATURE OF	NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION		TYPE C	TYPE OF ACTION		
Notice of Intent	Acidize	Deepen	Production (Start/Resun	ne) 🔲 Water Shut-Of	
Subsequent Report	☐ Alter Casing	Fracture Treat	Reclamation	U Well Integrity	
☐ Final Abandonment Notice	Casing Repair Change Plans	New Construction Plug and Abandon	Recomplete Temporarily Abandon	□ Other	
A mar / condomnent rouce	Convert to Injection	Plug Back	U Water Disposal		
following completion of the involved testing has been completed. Final Al determined that the site is ready for f	l operations. If the operation re bandonment Notices shall be fil inal inspection.)	e the Bond No. on file with BLM/Bl sults in a multiple completion or re- led only after all requirements, inclu	ding reclamation, have been comp	hall be filed within 30 days rm 3160-4 shall be filed once bleted, and the operator has	
 following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 3970 	l operations. If the operation re pandonment Notices shall be fil inal inspection.) pressure on tubing and o) ft. Mix and spot 30 sack	the Bond No. on file with BLM/BI sults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub cs Class C Cement on CIBP.	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been comp ing with 10 ppSEE ATT/	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has	
 following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 3970 well with mud laden PxA fluid 	operations. If the operation re pandonment Notices shall be fil inal inspection.) pressure on tubing and o ft. Mix and spot 30 sack as per NMOCD and BLM	the Bond No. on file with BLM/BJ sults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub ts Class C Cement on CIBP. I requirements.	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been comp ing with 10 ppSEE ATT/	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has	
 following completion of the involvec testing has been completed. Final Al determined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 3970 well with mud laden PxA fluid 3) PU and spot 30 sacks Cla 	l operations. If the operation re pandonment Notices shall be fil inal inspection.) pressure on tubing and o 0 ft. Mix and spot 30 sach as per NMOCD and BLM ss C cement from 3000 f	the Bond No. on file with BLM/BJ sults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub ks Class C Cement on CIBP. I requirements.	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been comp ing with 10 ppSEE ATT/ PU and displace NDITI	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has ACHED FOR ONS OF APPR(
 following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 3970 well with mud laden PxA fluid 	operations. If the operation re pandonment Notices shall be fil inal inspection.) pressure on tubing and o ft. Mix and spot 30 sack as per NMOCD and BLM ss C cement from 3000 f pany and perf squeeze ho WOC & Tag.	the Bond No. on file with BLM/BJ sults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub ts Class C Cement on CIBP. I requirements. t. bles @ 2750 ft, TIH with tubin A_{2} . $A_{c} + \int_{c} $	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been comp ing with 10 ppSEE ATT/ PU and displace NDITION by and squeeze 80 from 2245	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has ACHED FOR ONS OF APPR(
 following completion of the involvec testing has been completed. Final Al determined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 3970 well with mud laden PxA fluid 3) PU and spot 30 sacks Cla 4) RU wire line service comp sacks cement back to 2620 ft. 	operations. If the operation re pandonment Notices shall be fil inal inspection.) pressure on tubing and of the Mix and spot 30 sack as per NMOCD and BLM iss C cement from 3000 f pany and perf squeeze ho WOC & Tag.	the Bond No. on file with BLM/B) sults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub cs Class C Cement on CIBP. I requirements. t. les @ 2750 ft, TIH with tubing $A = \frac{1}{2}$. $A = \frac{1}{2} = \frac{1}{2}$ les @ 550 ft. TH with tubing	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been completion ing with 10 ppSEE ATT/ PU and displace NDITION by and squeeze 80 From 2245- grand squeeze 45	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has ACHED FOR DNS OF APPRC 2/25: 600C To TISAIN	
following completion of the involvec testing has been completed. Final Al determined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 397(well with mud laden PxA fluid 3) PU and spot 30 sacks Cla 4) RU wire line service comp sacks cement back to 2620 ft. 5) RU wire line service comp	operations. If the operation re pandonment Notices shall be fil inal inspection.) pressure on tubing and of the Mix and spot 30 sack as per NMOCD and BLM uss C cement from 3000 f pany and perf squeeze ho WOC & Tag.	the Bond No. on file with BLM/BJ sults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub ts Class C Cement on CIBP. I requirements. t. bles @ 2750 ft, TIH with tubin A_{2} . $A_{c} + \int_{c} $	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been completion ing with 10 ppSEE ATT/ PU and displace NDITION by and squeeze 80 From 2245- grand squeeze 45	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has ACHED FOR DNS OF APPRC 2/25: 600C To TISAIN	
following completion of the involvec testing has been completed. Final Al determined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 397(well with mud laden PxA fluid 3) PU and spot 30 sacks Cla 4) RU wire line service comp sacks cement back to 2620 ft. 5) RU wire line service comp	operations. If the operation re bandonment Notices shall be fil inal inspection.) pressure on tubing and o 0 ft. Mix and spot 30 sack as per NMOCD and BLM ss C cement from 3000 f bany and perf squeeze ho WOC & Tag.	the Bond No. on file with BLM/BI sults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub cs Class C Cement on CIBP. I requirements. I requirements. t. bles @ 2750 ft, TIH with tubin A = 3. $A = A = A = Ables @ 550 ft. THH with tubingA = 3$. $A = A = A = Ables @ 550 ft. THH with tubingA = 3$. $A = A = A = A$	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been completion ing with 10 ppSEE ATT/ PU and displace NDITION by and squeeze 80 From 2245- grand squeeze 45	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has ACHED FOR DNS OF APPR(2/25: 600c To TISAM	
 following completion of the involvec testing has been completed. Final Al determined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 397(well with mud laden PxA fluid 3) PU and spot 30 sacks Cla 4) RU wire line service comp sacks cement back to 2620 ft. 5) RU wire line service comp 14. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) PAULA B 	l operations. If the operation re pandonment Notices shall be fil inal inspection.) pressure on tubing and of the Mix and spot 30 sack as per NMOCD and BLM ass C cement from 3000 f wany and perf squeeze ho WOC & Tag.	the Bond No. on file with BLM/B) sults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub cs Class C Cement on CIBP. I requirements. I requirements. t. bles @ 2750 ft, TIH with tubin the second secon	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been completion ing with 10 ppSEE ATT/ PU and displace NDITION by and squeeze 80 from 2245 grand squeeze 45 ell Information System the Carlsbad A LATORY ANALYST	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has ACHED FOR ONS OF APPRC	
 following completion of the involvectes ting has been completed. Final Aldetermined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 3970 well with mud laden PxA fluid 3) PU and spot 30 sacks Cla 4) RU wire line service complexes compensation to 2620 ft. 5) RU wire line service complexes and the same the service complexes of the service	I operations. If the operation re pandonment Notices shall be fil inal inspection.) Pressure on tubing and of the Mix and spot 30 sack as per NMOCD and BLM iss C cement from 3000 f pany and perf squeeze ho WOC & Tag.	the Bond No. on file with BLM/BI sults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub cs Class C Cement on CIBP. I requirements. t. les @ 2750 ft, TIH with tubin A.g. A.g. A.g. les @ 550 ft. THH with tubin EXESTATION OF THE WITH THE SECON PANY, sent to Title REGU Date 08/01/	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been completion ing with 10 ppSEE ATT/ PU and displace NDITION by and squeeze 80 from 2245 grand squeeze 45 ell Information System the Carlsbad A LATORY ANALYST	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has ACHED FOR DNS OF APPR(2/25: 600c To TISAM	
 following completion of the involvec testing has been completed. Final Al determined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 397(well with mud laden PxA fluid 3) PU and spot 30 sacks Cla 4) RU wire line service comp sacks cement back to 2620 ft. 5) RU wire line service comp 14. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) PAULA B 	I operations. If the operation re pandonment Notices shall be fil inal inspection.) Pressure on tubing and of the Mix and spot 30 sack as per NMOCD and BLM iss C cement from 3000 f pany and perf squeeze ho WOC & Tag.	the Bond No. on file with BLM/B) sults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub cs Class C Cement on CIBP. I requirements. I requirements. t. bles @ 2750 ft, TIH with tubin the second secon	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been completion ing with 10 ppSEE ATT/ PU and displace NDITION by and squeeze 80 from 2245 grand squeeze 45 ell Information System the Carlsbad A LATORY ANALYST	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has ACHED FOR DNS OF APPR(2/25: 600c To TISAM	
following completion of the involvec testing has been completed. Final Al determined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 397(well with mud laden PxA fluid 3) PU and spot 30 sacks Cla 4) RU wire line service comp sacks cement back to 2620 ft. 5) RU wire line service comp 14. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) PAULA B Signature (Electronic is Approved By	I operations. If the operation re pandonment Notices shall be fil inal inspection.) P pressure on tubing and of the Mix and spot 30 sack as per NMOCD and BLM iss C cement from 3000 f pany and perf squeeze ho WOC & Tag. WOC & Tag. WOC & Tag. WOC & Tag. Bubmission # For CIMAREX RUNSON Submission) THIS SPACE FO	the Bond No. on file with BLM/BI soults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub cs Class C Cement on CIBP. I requirements. t. les @ 2750 ft, TIH with tubin for ference of the second case of the second of the second plate of the second Date of the second Title REGU	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been completion ing with 10 ppSEE ATT/ PU and displace NDITION by and squeeze 80 from 2245 grand squeeze 45 ell Information System the Carlsbad A LATORY ANALYST	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has ACHED FOR DNS OF APPR(2/25: 600c To TISAM	
following completion of the involvec testing has been completed. Final Al determined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 3970 well with mud laden PxA fluid 3) PU and spot 30 sacks Cla 4) RU wire line service comp sacks cement back to 2620 ft. 5) RU wire line service comp 14. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) PAULA B Signature (Electronic is	l operations. If the operation re pandonment Notices shall be fil inal inspection.) pressure on tubing and of the fill of the operation of the operation of the fill of the operation of the operation of the operation of the fill operation of the operation o	the Bond No. on file with BLM/BI sults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub cs Class C Cement on CIBP. I requirements. I requirements. t. bles @ 2750 ft, TIH with tubin A.g. A.g. A.g. bles @ 550 ft. THH with tubing 2255424 verified by the BLM W ENERGY COMPANY, sent to Title REGU Date 08/01/ DR FEDERAL OR STATE	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been completion ing with 10 ppSEE ATT/ PU and displace NDITION by and squeeze 80 from 2245 grand squeeze 45 ell Information System the Carlsbad A LATORY ANALYST	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has ACHED FOR DNS OF APPR(2/25: cooc To (T/Sa.H) accorded for PPCO DNMOCD8-/	
following completion of the involvec testing has been completed. Final Al determined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 397(well with mud laden PxA fluid 3) PU and spot 30 sacks Cla 4) RU wire line service comp sacks cement back to 2620 ft. 5) RU wire line service comp 14. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) PAULA B Signature (Electronic is Approved By Conditions of approval if any, are attached ertify that the applicant holds legal or eg	operations. If the operation repandonment Notices shall be fillinal inspection.) pressure on tubing and operations. oft. Mix and spot 30 sackars per NMOCD and BLM as per NMOCD and BLM sss C cement from 3000 f oany and perf squeeze how WOC & Tag. wany and perf squeeze how strue and correct. Electronic Submission # For CIMAREX RUNSON Submission) THIS SPACE FO Approval of this notice does uitable title to those rights in the toperations thereon. U.S.C. Section 1212, make it a	the Bond No. on file with BLM/BI sults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub cs Class C Cement on CIBP. I requirements. I requirements. t. bles @ 2750 ft, TIH with tubin Areg. Aref Areg. bles @ 550 ft. THH with tubing 2255424 verified by the BLM W ENERGY COMPANY, sent to Title REGU Date 08/01/ DR FEDERAL OR STATE s not warrant or e subject lease Office Areg.	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been completion ing with 10 ppSEE ATT/ PU and displace NDITION by and squeeze 80 From 2245 and squeeze 45 ell Information System the Carlsbad LATORY ANALYST 2014 OFFICE USE	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has ACHED FOR DNS OF APPR(2/25: coor 76 (7/5a.14) ccopied for 1900 20 NMOCD8-/ 8-5- Date	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 397(well with mud laden PxA fluid 3) PU and spot 30 sacks Cla 4) RU wire line service comp sacks cement back to 2620 ft. 5) RU wire line service comp sacks cement back to 2620 ft. 5) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 7) RU wire line service comp sacks cement back to 2620 ft. 8) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 7) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back t	operations. If the operation repandonment Notices shall be fillinal inspection.) pressure on tubing and operation.) pressure on tubing and operation.) oft. Mix and spot 30 sackars per NMOCD and BLM as per NMOCD and BLM ass C cement from 3000 f pany and perf squeeze how WOC & Tag. work and perf squeeze how bany and perf squeeze how strue and correct. Electronic Submission # For CIMAREX RUNSON Submission) THIS SPACE F(C) Approval of this notice does uitable title to those rights in the tot operations thereon. U.S.C. Section 1212, make it a statements or representations at	the Bond No. on file with BLM/BI sults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub cs Class C Cement on CIBP. I requirements. I requirements. t. bles @ 2750 ft, TIH with tubin Areg. Aref Areg. bles @ 550 ft. THH with tubing 2255424 verified by the BLM W ENERGY COMPANY, sent to Title REGU Date 08/01/ DR FEDERAL OR STATE s not warrant or e subject lease Office Areg.	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been completion ing with 10 ppSEE ATT/ PU and displace NDITION by and squeeze 80 From 2245 and squeeze 45 ell Information System the Carlsbad LATORY ANALYST 2014 OFFICE USE	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has ACHED FOR DNS OF APPR(2/25: coc 76 (7/5a.H) CCSPARD for PCO CONSTRACTOR NMOCD8-/ B-5- Date	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) MI & RU WSU. Check for brine. ND Tree, NU BOPs. 2) TIH and tag CIBP @ 397(well with mud laden PxA fluid 3) PU and spot 30 sacks Cla 4) RU wire line service comp sacks cement back to 2620 ft. 5) RU wire line service comp sacks cement back to 2620 ft. 5) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 7) RU wire line service comp sacks cement back to 2620 ft. 8) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 7) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back to 2620 ft. 6) RU wire line service comp sacks cement back t	operations. If the operation repandonment Notices shall be fillinal inspection.) pressure on tubing and operation.) pressure on tubing and operation.) oft. Mix and spot 30 sackars per NMOCD and BLM as per NMOCD and BLM ass C cement from 3000 f pany and perf squeeze how WOC & Tag. work and perf squeeze how bany and perf squeeze how strue and correct. Electronic Submission # For CIMAREX RUNSON Submission) THIS SPACE F(C) Approval of this notice does uitable title to those rights in the tot operations thereon. U.S.C. Section 1212, make it a statements or representations at	the Bond No. on file with BLM/BI sults in a multiple completion or re- led only after all requirements, inclu casing. Load casing and tub cs Class C Cement on CIBP. I requirements. I requirements. t. bles @ 2750 ft, TIH with tubin Areg. Aref Arez. bles @ 550 ft. THH with tubing 2255424 verified by the BLM W ENERGY COMPANY, sent to Title REGU Date 08/01/ DR FEDERAL OR STATE s not warrant or e subject lease Office Area.	A. Required subsequent reports sl completion in a new interval, a For iding reclamation, have been completion ing with 10 ppSEE ATT/ PU and displace NDITION ng and squeeze 80 from 2245 and squeeze 45 ell Information System the Carlsbad LATORY ANALYST 2014 OFFICE USE	hall be filed within 30 days rm 3160-4 shall be filed once oleted, and the operator has ACHED FOR DNS OF APPR(2/25: coc 7 (T/Sa.H) CCSDAD for PCC CD NMOCD8-/ 8-5- Date	

Additional data for EC transaction #255424 that would not fit on the form

32. Additional remarks, continued

۲

٩

sacks-cement-back to 2620-ft. WOC & Tag-above 250 ft.

6) RU wire line service company and perf squeeze holes @ 550 ft. TIH with tubing and squeeze 110 sacks cement back to surface. Verify cement to surface on all annuli.

7) Cut off well head 3 ft below GL. Weld on steel plate and install dry hole marker. Cut off anchors below ground level. Back drag and clean location. RD WSU and release all rental equipment.

Please see well bore diagram attached.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged**.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

Cimarex Energy Co. of Colorado KB - 8' above GL Amoco Federal #1 SWD 1665 FSL & 330 FEL Sec. 27, T-26-S, R-29-E, Eddy Co., NM 07/31/2014 Winston Kelly API: 30-015-24466 Perf & Squeeze 120 sacks Class "C" @ 100' to surface Perf & Squeeze 45 sacks Class "C" @ 550', WOC & Tag 8-5/8", 24# J-55 @ 450' 456 T/salt 2195 +/-B/salt 2678 +/-De/line 2878 Sord 2912 Charry Cyn 3820 1" to sart. cmt w/ 280 sx, cmt circ. Perf & Squeeze 80 sacks Class "C" @ 2750', WOC & Tag 130 shag 670-6-2259 TOC @ 2720' Spot 30 sacks Class "C" @3000" 🤳 Spot 30 sacks Class "C" on CIBP @ 3970' -4-1/2" CIBP @ 3,970' Delaware perfs (4022' - 4208') PBTD @ 4283' Cmt retainer @ 4283' Delaware perfs @ 4300', sqz w/ 250 sx CIBP @ 4800' 4-1/2" 11.6# J-55 @ 5820' 🖊 Williamson Perfs (4984' - 5004') cmt w/ 450 sx, TOC @ 2720' CIBP @ 5300' Getty Perfs @ (5350' - 5358') TD @ 6150'

Printed 8/1/2014

. •



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

Private Surface. These are BLM Minimum standarde Var will hand to wood will had an

Note:

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Solomon Hughes Natural Resource Specialist 575-234-5951

Jeffery Robertson Natural Resource Specialist 575-234-2230

Duncan Whitlock Environmental Protection Specialist 575-234-5926

Linda Denniston Environmental Protection Specialist 575-234-5974

Douglas Hoag Civil Engineering Tech 575-234-5979 Cody Layton Supervisory Multi Resources 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Amanda Lynch Natural Resource Specialist 575-234-5922

Jessie Rice Natural Resource Specialist 575-234-5913

Indra Dahal Natural Resource Specialist 575-234-5996

