District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action													
NAB 1424538884						OPERA	ГOR			ial Report		Final Repor	
Name of Company: BOPCO, L.P. 200737						Contact: Tony Savoie							
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220						Telephone No. 575-887-7329 Facility Type: Exploration and Production							
Facility Name: JRU-62 The flow line spill is 1600 ft. north of the well pad.						Pacifity Type: Exploration and Production							
Surface Owner: Federal Mineral Owner:						: Federal			API No. 30-015-35340				
	LOCATION OF RELEASE												
Unit Letter	Section	Township		th/South Line Feet from the E			ast/West Line County						
J 1 23S 30E									Eddy				
Latitude N 32 9. 334352 Longitude W 103.832156													
Type of Release: Crude oil and produced water NATURE OF RELEASE Volume of Release: 2 bbls crude Volume Recovered: None													
		oil and 8 bbls water											
Source of Re	lease: 2 7/8'	Date and Hour of Occurrence: 8/31/14 time unknown			Date and Hour of Discovery: 8/31/14 at 11:44 a.m.								
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required						If YES, To Whom?			11.77 d.m.				
By Whom? Was a Water	course Reac	Date and Hour If YES, Volume Impacting the Watercourse.											
☐ Yes ⊠ No						NM OIL CONSERVATION							
If a Watercourse was Impacted, Describe Fully.*						ARTESIA DISTRICT							
		SEP 0 2 2014											
JET V & ZUI4													
Describe Cause of Problem and Remedial Action Taken *													
Describe Cause of Problem and Remedial Action Taken.* The flow line leaked due to external corrosion. The well was shut in and a temporary repair clamp was installed on the affected pipe.													
Describe Are	a Affected a	nd Cleanup A	ction Tak	en *									
The spill imp	acted approx	kimately 720 :	sq.ft. of c	aliche road. All of	f the flu	id soaked into	the roadway.					;	
The impacted					Mani	dalinas for sni	Il romodiation					-	
The final remediation will be in accordance to the NMOCD and BLM guidelines for spill remediation.													
I horaby carti	fy that the in	formation air	an ahova	is true and comple	ata to th	a hast of my l	rnawladga and w	ndarstan	d that nur	wont to NIMC)CD ***	les and	
regulations al	l operators a	re required to	report and	d/or file certain re	lease no	otifications an	d perform correct	tive actio	ons for rele	eases which i	nay en	danger	
public health	or the enviro	onment. The	acceptance	e of a C-141 repor investigate and re-	t by the	NMOCD ma	rked as "Final Re	eport" do	es not reli	eve the opera	ator of	liability	
or the environ	ment. In ad	dition, NMO	CD accept	ance of a C-141 re	eport de	es not relieve	the operator of r	esponsib	oility for co	ompliance wat	ith any	other	
federal, state,	or local law:	s and/or regul	ations.	·			OH COM	· ·		DIT IT CLO			
Signature: 1 Dy Sauce						OIL CONSERVATION DIVISION							
Printed Name:	: Tony Savo	Approved by Environmental Specialist:											
			012/11/										
Title: Waste N	<u> Management</u>	and Remedia	tion Speci	alist	- A	Approval Date	: 4/1/19	E:	xpiration I	Date:			
E-mail Addres	ss: tasavoie@)basspet.com			c	Conditions of A	Approval:			Attached	П	ĺ	
Date: 9/2/14			30	Remediation per OCD Rule &									
Attach Additi	onal Sheet	s If Necessa	· .	PROPOSALING LATER THAN: 2RP-24U5									
			-			1110703	nolatiq"	TOMIN.		ZY	11-1	2445	