District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side.of form

		Release Notification and Corrective Action												
								OPERATOR				⊠ Fin	al Repor	
S.H								Contact Robert McNeil						
						Telephone No. (432) 230-0077								
200	Facility Name Down South State Com #4H Facility Type Tank Battery													
	Surface Owner: State Mineral Owner							Lease No. (API#) 30-015-37256						
		•		N OF REI	LEASE									
	Unit Letter P	Section 19	Township 26S	Range 28E	Feet from the	North	/South Line	Feet from the	East/We	st Line	County	Eddy		
		<u></u>		l	atitude N 32.0	D2223°	Longitude	e W 104.1191	1 7°		<u> </u>			
		NATURE OF RELEASE												
	Type of Release: Oil and Produced Water							Volume of Release 15 bbls oil Volume Reco				covered 0 bbls oil		
	Source of Release FWKO						25 bbls produced water Date and Hour of Occurrence			0 bbls produced water				
	Source of Release TWRO									Date and Hour of Discovery 12-08-2013 3:30 pm				
	Was Immediate Notice Given?							If YES, To Whom?						
4	 	☐ Yes ☐ No ☐ Not Required												
	By Whom?						Date and Hour 12-10-2013 07:12 am If YES, Volume Impacting the Watercourse.							
	☐ Yes ⊠ No							N/A						
	If a Watercou	se was Impacted. Describe Fully.*										·		
										i	NA OU	CONSER	VATIO	
Describe Cause of Problem and Remedial Action Taken.*										······································		ESIA DISTR		
į	ALIC 9 a 2014													
_1	A gasket on a	A gasket on a FWKO failed. Replaced the gasket to prevent reoccurrence. AUU 29 2014												
		·										ECEIVED	•	
	Describe Area Affected and Cleanup Action Taken.*						WECTIVED							
		nitially an estimated 15 bbls of oil and 25 bbls of produced water were released from a failed gasket on a FWKO. None of the fluids were recovered. The												
Ä		spill area is on the location and overspray on the adjacent pasture. Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech												
	prepared closu					i. Site w	as then thoug	in up to surface g	race with	erean bae	zkiiii materi	ar. rena rec		
73	Lharaba aartif	that the is	formation oi	gen abova :	s true and comple	te to th	hest of my tr	nowledge and un	deretand th	hat nuren	ant to NMC	CD rules on	nd	
	regulations all	hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger												
123								rked as "Final Rep						
	should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
	federal, state, or local haws and/or regulations.													
	Signature: Printed Name: Ike Tayarez (agent for COG) Ap							OIL CONSERVATION DIVISION Approved by District Supervisor:						
Target N														
3														
R	E-mail Address سر					Conditions of Approval:								
Date: 8 - 18 19. Phone: (432) 687-8110 + Mer														
		101/	10 5 1						_	וווו	-/1/			