Submit I Copy To Appropriate District NM OIL CONSERVATIONNEW Mexico Office	Form C-103
District I – (575) 393-6161 ARTESPACES, ARTESPACES and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	WELL APLNO
District II – (575) 748-1283 811 S. First St., Arlesia, NM 88210  SEPOL 5 2014 CONSERVATION DIVISION	30-015-22625
<u>District III</u> – (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE ☑ FEE ☐
District IV - (505) 476-3460	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	L-6654
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name State 19 Com
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well Gas Well Other	2
2. Name of Operator V-F PETROLEUM INC.	9. OGRID Number <b>24010</b>
3. Address of Operator P.O. Box 1889, Midland, Texas 79702	10. Pool name or Wildcat Millman South (Morrow)
4. Well Location	Willing South (Morrow)
Unit Letter N: 860 feet from the South line and 2,057 feet from the West line	
Section 19 Township 19-S Range 28-E NMPM Eddy County	
11. Elevation (Show whether DR, RKB, RT, GR 3,493' GR	, etc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING REMEDIAL WORK ARANDON REMEDIAL WORK REMEDIAL	
TEMPORARILY ABANDON	
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of	
starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  Approved for plugging of well bore only.	
Liability under bond is retained pending receipt	
	which may be found at OCD Web Page under Forms, www.emnrd.state.nm.us/ocd.
08/04/14 MI 2,300' 2 3/8" tbg for work string.	
Remove WH. MI & rack 80 jts 2 3/8" tbg. TIH open end to 2,327'. Install stripper head. Displace wellbore w/mud laden 10 pound brine wtr. Pull bttm of tbg to 500'. Mix & spot 50 sxs Class C cmt. TOH. WOC 4 hrs. TIH. Tag top of plug @ 311'. LD tbg out of derrick. Position bttm of tbg @ 100'. Mix & spot 25 sxs Class C cmt. Circ 1 bbl cmt to surf. LD all tbg. Wash cmt inside WH to 3' below ground level. RD rel WSU.	
08/07/14 MI backhoe, welder, roustabout crew.	
08/08/14 MI welder, roustabout crew & backhoe. Dig out cellar. Cut off WH 3' below ground level. Install dry hole marker. Back fill cellar. Clean loc. Cut off guy line anchors 3' below ground level. Plugging complete.	
I hereby-certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE	
Type or print name Eric Sprinkle E-mail address: eric@vfpetroleum.com PHONE: 432-683-3344	
For State Use Only	
APPROVED BY: DOOL TITLE DIST STORY DATE 9-9-2019  Conditions of Approval (if any):	
ASSIBILITY C103	

ال المعارضين المعارض ا