

SEP 22 2014

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submitted to the appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1436629023

Name of Company Apache Corporation <i>873</i>		Contact Bruce Baker	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address 2350 W Marland Blvd Hobbs NM 88240		Telephone No. (432) 631-6982		
Facility Name Tony Federal Battery		Facility Type Battery		
Surface Owner BLM	Mineral Owner	API No. 30-015-30244		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	18	17S	31E	1385'	FSL	1510'	FWL	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 150 barrels of water and 40 barrels of oil	Volume Recovered 140 barrels of water and 35 barrels of oil
Source of Release Water and Oil Tank	Date and Hour of Occurrence 9/19/2014 at 4:00 a.m.	Date and Hour of Discovery 9/19/2014 at 4:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (NMOCD) and Jim Amos (BLM)	
By Whom? Bruce Baker	Date and Hour 9/19/2014 at 11:30 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A short in the electrical panel caused a power outage at facility. The power outage caused all the transfer pumps and Lact unit to fail resulting in the tanks to overflow. The power was restored.

Describe Area Affected and Cleanup Action Taken.*
The release area was contained inside the bermed area and lease pad. A vacuum truck was dispatched to pick-up standing fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: Environmental Technician	Approval Date: <i>9/23/14</i>	Expiration Date:
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/22/2014 Phone: (432) 631-6982	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>10/23/14</i>	

* Attach Additional Sheets If Necessary

2RP-2509