Submit I Copy To Appropriate District State of New Mexico	Form C-103
Office District 1 – (575) 393-6161 1625 N. French Dr., Hobbs, NM & TESIA DISTRICT	Revised July 18, 2013 WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210SEP <b>2 2 2004</b> L CONSERVATION DIVISION	30-015-41758
811 S. First St., Artesia, NM 882105L1 <b>2 2 200</b> LL CONSERVATION DIVISION <u>District III</u> – (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV (505) 476-3460 <b>RECEIVED</b> Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Cinter Farms A Fee Com.
PROPOSALS.) 1. Type of Well: Oil Well G Gas Well Other	8. Well Number 3H
2. Name of Operator	9. OGRID Number
OXY USA Inc. 3. Address of Operator	16696 10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710	Culebra Bluff Bare Spring S.
4. Well Location	
	630 feet from the west line
Section 17 Township Z3S Range 23E 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM County Eddy
The Elevation (Snow Whenler ph, NKB, Kr, OK, Ele.) 3629 GR	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
PULL OR ALTER CASINGMULTIPLE COMPL CASING/CEMEN	
OTHER: OTHER: Co	unpletion I
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Control of Starting and Proposed Work).	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Control of Starting and Proposed Work).	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Con proposed completion or recompletion.</li> </ol>	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of ood test. RIH & perf @ 13499-13279,
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.</li> <li>RU CTU 7/3/14, RIH &amp; Tag PBTD @ 13576', pressure test to 8500# for 30 min, go</li> </ol>	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of ood test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561,
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.</li> <li>RU CTU 7/3/14, RIH &amp; Tag PBTD @ 13576', pressure test to 8500# for 30 min, got 13181-13066, 12966-12851, 12751-12636, 12536-12421, 12321-12206, 12106-1 11461-11346, 11246-11131, 11031-10916, 10716-106014, 104501-10386, 10286 682 holes. Frac in 17 stages w/ 145874g Treated Water + 50076g 15% HCl acid +</li> </ol>	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of ood test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561, 5-101714, 10071-9956, 9856-9741' Total - 2752533g 15# BXL w/ 3503900# sand,
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.</li> <li>RU CTU 7/3/14, RIH &amp; Tag PBTD @ 13576', pressure test to 8500# for 30 min, got 13181-13066, 12966-12851, 12751-12636, 12536-12421, 12321-12206, 12106-1 11461-11346, 11246-11131, 11031-10916, 10716-106014, 104501-10386, 10286</li> <li>682 holes. Frac in 17 stages w/ 145874g Treated Water + 50076g 15% HCl acid + RD Nabor. RIH &amp; clean out well, POOH, RIH with 2-7/8" tbg &amp; pkr &amp; set @ 8452'</li> </ul>	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of ood test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561, 5-101714, 10071-9956, 9856-9741' Total - 2752533g 15# BXL w/ 3503900# sand,
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.</li> <li>RU CTU 7/3/14, RIH &amp; Tag PBTD @ 13576', pressure test to 8500# for 30 min, got 13181-13066, 12966-12851, 12751-12636, 12536-12421, 12321-12206, 12106-1 11461-11346, 11246-11131, 11031-10916, 10716-106014, 104501-10386, 10286 682 holes. Frac in 17 stages w/ 145874g Treated Water + 50076g 15% HCl acid +</li> </ol>	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of ood test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561, 5-101714, 10071-9956, 9856-9741' Total - 2752533g 15# BXL w/ 3503900# sand,
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.</li> <li>RU CTU 7/3/14, RIH &amp; Tag PBTD @ 13576', pressure test to 8500# for 30 min, got 13181-13066, 12966-12851, 12751-12636, 12536-12421, 12321-12206, 12106-1 11461-11346, 11246-11131, 11031-10916, 10716-106014, 104501-10386, 10286</li> <li>682 holes. Frac in 17 stages w/ 145874g Treated Water + 50076g 15% HCl acid + RD Nabor. RIH &amp; clean out well, POOH, RIH with 2-7/8" tbg &amp; pkr &amp; set @ 8452'</li> </ul>	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of ood test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561, 5-101714, 10071-9956, 9856-9741' Total - 2752533g 15# BXL w/ 3503900# sand,
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.</li> <li>RU CTU 7/3/14, RIH &amp; Tag PBTD @ 13576', pressure test to 8500# for 30 min, got 13181-13066, 12966-12851, 12751-12636, 12536-12421, 12321-12206, 12106-1 11461-11346, 11246-11131, 11031-10916, 10716-106014, 104501-10386, 10286</li> <li>682 holes. Frac in 17 stages w/ 145874g Treated Water + 50076g 15% HCl acid + RD Nabor. RIH &amp; clean out well, POOH, RIH with 2-7/8" tbg &amp; pkr &amp; set @ 8452'</li> </ul>	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of ood test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561, 5-101714, 10071-9956, 9856-9741' Total - 2752533g 15# BXL w/ 3503900# sand,
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed com/pletion or recompletion.</li> <li>RU CTU 7/3/14, RIH &amp; Tag PBTD @ 13576', pressure test to 8500# for 30 min, got 13181-13066, 12966-12851, 12751-12636, 12536-12421, 12321-12206, 12106-1 11461-11346, 11246-11131, 11031-10916, 10716-106014, 104501-10386, 10286 682 holes. Frac in 17 stages w/ 145874g Treated Water + 50076g 15% HCl acid + RD Nabor. RIH &amp; clean out well, POOH, RIH with 2-7/8" tbg &amp; pkr &amp; set @ 8452' potential.</li> </ul>	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of ood test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561, 5-101714, 10071-9956, 9856-9741' Total - 2752533g 15# BXL w/ 3503900# sand, . Flow to clean up and test well for
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed com/pletion or recompletion.</li> <li>RU CTU 7/3/14, RIH &amp; Tag PBTD @ 13576', pressure test to 8500# for 30 min, got 13181-13066, 12966-12851, 12751-12636, 12536-12421, 12321-12206, 12106-1 11461-11346, 11246-11131, 11031-10916, 10716-106014, 104501-10386, 10286 682 holes. Frac in 17 stages w/ 145874g Treated Water + 50076g 15% HCl acid + RD Nabor. RIH &amp; clean out well, POOH, RIH with 2-7/8" tbg &amp; pkr &amp; set @ 8452' potential.</li> </ul>	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of ood test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561, 5-101714, 10071-9956, 9856-9741' Total - 2752533g 15# BXL w/ 3503900# sand,
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.</li> <li>RU CTU 7/3/14, RIH &amp; Tag PBTD @ 13576', pressure test to 8500# for 30 min, got 13181-13066, 12966-12851, 12751-12636, 12536-12421, 12321-12206, 12106-1 11461-11346, 11246-11131, 11031-10916, 10716-106014, 104501-10386, 10286 682 holes. Frac in 17 stages w/ 145874g Treated Water + 50076g 15% HCl acid + RD Nabor. RIH &amp; clean out well, POOH, RIH with 2-7/8" tbg &amp; pkr &amp; set @ 8452' potential.</li> <li>Spud Date:</li></ul>	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of ood test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561, 5-101714, 10071-9956, 9856-9741' Total 2752533g 15# BXL w/ 3503900# sand, . Flow to clean up and test well for
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed com/pletion or recompletion.</li> <li>RU CTU 7/3/14, RIH &amp; Tag PBTD @ 13576', pressure test to 8500# for 30 min, got 13181-13066, 12966-12851, 12751-12636, 12536-12421, 12321-12206, 12106-1 11461-11346, 11246-11131, 11031-10916, 10716-106014, 104501-10386, 10286 682 holes. Frac in 17 stages w/ 145874g Treated Water + 50076g 15% HCl acid + RD Nabor. RIH &amp; clean out well, POOH, RIH with 2-7/8" tbg &amp; pkr &amp; set @ 8452' potential.</li> </ul>	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of ood test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561, 5-101714, 10071-9956, 9856-9741' Total 2752533g 15# BXL w/ 3503900# sand, . Flow to clean up and test well for
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.</li> <li>RU CTU 7/3/14, RIH &amp; Tag PBTD @ 13576', pressure test to 8500# for 30 min, gc 13181-13066, 12966-12851, 12751-12636, 12536-12421, 12321-12206, 12106-1 11461-11346, 11246-11131, 11031-10916, 10716-106014, 104501-10386, 10286 682 holes. Frac in 17 stages w/ 145874g Treated Water + 50076g 15% HCl acid + RD Nabor. RIH &amp; clean out well, POOH, RIH with 2-7/8" tbg &amp; pkr &amp; set @ 8452' potential.</li> <li>Spud Date: 5 (a+4) ( + 4) Rig Release Date: 6 ( + 4)</li> </ul>	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of ood test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561, 5-101714, 10071-9956, 9856-9741' Total 2752533g 15# BXL w/ 3503900# sand, . Flow to clean up and test well for c (14) e and belief.
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.</li> <li>RU CTU 7/3/14, RIH &amp; Tag PBTD @ 13576', pressure test to 8500# for 30 min, got 13181-13066, 12966-12851, 12751-12636, 12536-12421, 12321-12206, 12106-1 11461-11346, 11246-11131, 11031-10916, 10716-106014, 104501-10386, 10286 682 holes. Frac in 17 stages w/ 145874g Treated Water + 50076g 15% HCl acid + RD Nabor. RIH &amp; clean out well, POOH, RIH with 2-7/8" tbg &amp; pkr &amp; set @ 8452' potential.</li> <li>Spud Date:</li></ul>	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of ood test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561, 5-101714, 10071-9956, 9856-9741' Total 2752533g 15# BXL w/ 3503900# sand, . Flow to clean up and test well for
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.</li> <li>RU CTU 7/3/14, RIH &amp; Tag PBTD @ 13576', pressure test to 8500# for 30 min, gc 13181-13066, 12966-12851, 12751-12636, 12536-12421, 12321-12206, 12106-1 11461-11346, 11246-11131, 11031-10916, 10716-106014, 104501-10386, 10280 682 holes. Frac in 17 stages w/ 145874g Treated Water + 50076g 15% HCl acid + RD Nabor. RIH &amp; clean out well, POOH, RIH with 2-7/8" tbg &amp; pkr &amp; set @ 8452' potential.</li> <li>Spud Date: 5/24/(14) Rig Release Date: 6/(14)</li> </ul>	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of nod test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561, 5-101714, 10071-9956, 9856-9741' Total 2752533g 15# BXL w/ 3503900# sand, . Flow to clean up and test well for c (14) e and belief. DATE $d (c) (4)$
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.         RU CTU 7/3/14, RIH & Tag PBTD @ 13576', pressure test to 8500# for 30 min, gc 13181-13066, 12966-12851, 12751-12636, 12536-12421, 12321-12206, 12106-1         11461-11346, 11246-11131, 11031-10916, 10716-106014, 104501-10386, 10286         682 holes. Frac in 17 stages w/ 145874g Treated Water + 50076g 15% HCl acid + RD Nabor. RIH & clean out well, POOH, RIH with 2-7/8" tbg & pkr & set @ 8452' potential.         Spud Date:       5 (24 ( ( f)         Rig Release Date:       6 ( ()         I hereby certify that the information above is true and complete to the best of my knowledg         SIGNATURE       ITTLE       Sr. Regulatory Advisor         Type or print name       David Stewart       E-mail address:       david stewart@	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of nod test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561, 5-101714, 10071-9956, 9856-9741' Total 2752533g 15# BXL w/ 3503900# sand, . Flow to clean up and test well for c (14) e and belief. DATE $d (c) (4)$
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.         RU CTU 7/3/14, RIH & Tag PBTD @ 13576', pressure test to 8500# for 30 min, gc 13181-13066, 12966-12851, 12751-12636, 12536-12421, 12321-12206, 12106-1         11461-11346, 11246-11131, 11031-10916, 10716-106014, 104501-10386, 10286         682 holes. Frac in 17 stages w/ 145874g Treated Water + 50076g 15% HCl acid + RD Nabor. RIH & clean out well, POOH, RIH with 2-7/8″ tbg & pkr & set @ 8452′ potential.         Spud Date:	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of nod test. RIH & perf @ 13499-13279, 1991, 11891-11776, 11676-11561, 5-101714, 10071-9956, 9856-9741' Total 2752533g 15# BXL w/ 3503900# sand, . Flow to clean up and test well for c (14) e and belief. DATE $d (c) (4)$