Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO 30-015-41783
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE X FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		·
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Hadrhamm 16 SWID
PROPOSALS.)		Hackberry 16 SWD 8. Well Number
1. Type of Well: Oil Well Gas Well Other Swb		1
Devon Energy Production Co., L.P. 405-552-6558		9. OGRID Number 6137
3. Address of Operator		10. Pool name or Wildcat
333 West Sheridan Ave, Oklahoma City, OK 73102		SWD; Dev-Fus-Mon-Simp-Ell
4. Well Location		
Unit Letter M: 330 feet from the South line and 280 feet from the West line		
Section 16	Township 19S Range 31E	NMPM County Eddy
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTI	[BSEQUENT REPORT OF: ORK ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
DOWNHOLE COMMINGLE.	_	-
CLOSED-LOOP SYSTEM □		_
OTHER: Workover \(\triangle \) OTHER: \(\triangle \) 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
Devon requests permission to do the following procedure.		
Procedure		
1) MIRU wireline crew.		
 Run perfs to open hole, set off guns. Trip out hole, lay down guns 		
4) MIRU pumps and equipment.		
5) Establish injection rate with produced water at 2,679 psi surface pressure.		
6) Shut in well after 3,000 bbls pumped. Record ISIP, 5 min, 10 min, 15 min SICP. 7) Repeat steps 5 and 6 pumping to 6,000 bbls.		
8) MIRU frac crew	5 6,000 buis.	•
9) Fracture open hole, do not exce	ed 8,500 psi.	
10) Repeat steps 5 and 6.11) Report to OKC and record in w	rellview.	
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
17 to the same of		
K. A. March		
SIGNATURE TITLE Regulatory Compliance Specialist DATE 10/13/2014		
Type or print name Linda Good	E-mail address: linda.good@dvr	n.com PHONE: 405-552-6558
For State Use Only		/
The second of th		
APPROVED BY: Conditions of Approval (if any):	TITLE DISTALLA	DATE 10/19/19
		/

