Submit 1 Copy To Appropriate District	State of Ne	ew Mexico		Form C-103
Office <u>Fristrict I</u> – (575) 393-6161	Energy, Minerals an	d Natural Resources		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	·		WELL API NO.	
<u>District II</u> – (\$75) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-24395	
<u>District III</u> – (505) 334-6178	1220 South S	t. Francis Dr.	5. Indicate Type of Lease  STATE ☐ FEE ☒	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, 1	NM 87505	6. State Oil & Gas Leas	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Suitte 1 0, 1		o. State Off & Gas Leas	e No.
87505 \ CARLES TAXABLE TO THE STATE OF THE S	ICEG AND DEPONTS ON I	WELL C	7 7 37 77 77	A
SUNDRY NOTI	ICES AND REPORTS ON V		7. Lease Name or Unit	Agreement Name
DIFFERENT RESERVOIR. USE "APPLIC			Jackson AT	
PROPOSALS.)			8. Well Number	
1. Type of Well: Oil Well	Gas Well Other		16	
2. Name of Operator			9. OGRID Number	
Yates Petroleum Corporation  3. Address of Operator			025575 10. Pool name or Wildo	at
105 South Fourth Street, Artesia, N	JM 88210		Eagle Creek; San Andre	ì
4. Well Location			Bugie Creek, Sun 7 mare	
	1650 feet from the	South line and	1650 feet from the	West line
	<del></del>		<del></del>	
Section 14	Township 17S		NMPM Eddy	County
	11. Elevation (Show wheti	her DR, RKB, RT, GR, etc.		
	<u> </u>	3493'GR		
10 (1)			D	
12. Check A	Appropriate Box to Indic	cate Nature of Notice,	Report or Other Data	
NOTICE OF IN	ITENTION TO:	SUB	SEQUENT REPOR	T OE:
PERFORM REMEDIAL WORK		REMEDIAL WOR		RING CASING ☐
TEMPORARILY ABANDON		COMMENCE DR		
PULL OR ALTER CASING	_	CASING/CEMEN	<del></del>	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM				
OTHER:		OTHER:		
13. Describe proposed or comp				
	ork). SEE RULE 19.15.7.14	NMAC. For Multiple Con	mpletions: Attach wellbor	e diagram of
proposed completion or rec	ompletion.			
Yates Petroleum Corporation plans t	to plug and abandon this wel	l as follows:		
rates renoteum corporation plans t	to plug and abandon tins wer	i as ionows.		
1. NU BOP. TOH with production	equipment.			
2. Make a scraper run to 1180'. Spo		plug to 765'. Verify that a	Il casing strings have ceme	ent on the backside
at surface. For casing strings withou	it cement on the backside at	surface, perforate and circu	ulate cement to surface as r	necessary.
3. Tag top of cement plug at 765'.		up to surface.		
4. Cut off wellhead, install marker a	and clean location.			
Wellbore schematics attached		Approved for plugging of well t	oore only. NM	OIL CONSERVATIO
wendore schematics attached		Liability under bond is retained	pending receipt	ARTESIA DISTRICT
•		of C-103 (Subsequent Report of which may be found at OCD W		OCT 08 2014
CONDITIONS OF APPROVAL ATTA	ACHED	Forms, www.cmnrd.state.nm.us	1	001 00 2014
Approval Granted providing w				RECEIVED
SI Completed by	Rig Rele	ease Date:		
<u>10/8/201</u>	5	<u> </u>		
	- :			
I hereby certify that the information	above is true and complete to	o the best of my knowledg	e and belief.	
	Î			•
CACHATAINE A A				
SIGNATURE (Charles	TITLE	Regulatory Reporting S	upervisor DATE Octo	ober 6, 2014
Type or print nameTina Hue	erta E mail addres	es tinah@vatasnatralaur	n com DHOME: 4	575 740 4160
Type or print name Tina Hue For State Use Only	erta E-mail addres	ss: <u>tinah@yatespetroleur</u>	n.com PHONE:	575-748-4168
PAN_	1.	7 1		
APPROVED BY:	W TITLE	VIST AWYEN	DATE 10	0/8/14
Conditions of Approval (if any):	See Attached	2.1'	~~	<del></del>
N	Sep Attention	(10)#S		
	M MANUEL	<del>-</del> -		


Well Name: <u>Jackson AT #16</u> Field: <u>Eagle Creek</u> Location: 1650' FSL & 1650' FWL Sec 14-17S-25E

County: Eddy State: New Mexico
GL: 3,493' Zero: KB:

Spud Date: <u>2/12/1983</u> Completion Date: <u>3/9/1983</u>

Comments: API # 30-015-24395

# BEFORE



Casing Progr	am
Size/Wt/Grade	Depth Set
10 ¾" 40# K-55	365'
7" 23# K-55	1,100'
4 ½" 9.5# K-55	1,478'

San Andres perfs 1,196'-1,423' (28)

4 ½" csg @ 1,479' cmtd w/ 200 sx.

TD 1,510'

6 1/4" hole

PBTD 1,478'

DATE: 9/8/2014

Well Name: <u>Jackson AT #16</u> Field: <u>Eagle Creek</u> Location: 1650' FSL & 1650' FWL Sec 14-17S-25E

County: Eddy State: New Mexico GL: 3,493' Zero: \_\_\_\_ KB:


Comments: API # 30-015-24395

PBTD 1,478'

TD 1,510'

### AFTER

Casing Program				
Size/Wt/Grade	Depth Set			
10 ¾" 40# K-55	365'			
7" 23# K-55	1,100'			
4 ½" 9.5# K-55	1,478'			



1,196'-1,423' (28)

4 ½" csg @ 1,479' cmtd w/ 200 sx.

## NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

### CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Yates Pel.	
Well Name & Number: Jackson	alles TA
API#: 30 015 - 24395	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 1 year of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 10/8/14

APPROVED BY: FU)

#### GUIDELINES FOR PLUGGING AND ABANDONMENT

#### DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub
  plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
  - o Fusselman
  - o Devonian
  - o Morrow
  - o Wolfcamp
  - o Bone Spring
  - o Delaware
  - o Any Salt Section (Plug at top and bottom)
  - o Abo
  - o Glorieta
  - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).