


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report

☒ Final Report

Name of Company	BOPCO, LP	260737	Contact	Tony Savoie	
Address	522 W. Mermod, Suite 704, Carlsbad, NM 88220			Telephone No.	(432)556-8730
Facility Name	James Ranch Unit #36			Facility Type	E&P

27686

Surface Owner	Federal	Mineral Owner	Federal	Lease No.	API #30-015-2786
---------------	---------	---------------	---------	-----------	------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	I	23S	30E	1980	North	1860	East	Eddy

Latitude 32.335615° North

Longitude 103.832117° West

NATURE OF RELEASE

Type of Release	Produced water and crude oil	Volume of Release	450 bbls of produced water and 5 bbls of crude oil	Volume Recovered	100 bbls
Source of Release	Produced water storage tank	Date and Hour of Occurrence	6/24/12, Hour unknown	Date and Hour of Discovery	6/24/12 7:30 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	NMOCD Emergency #104 and Jim Amos with the BLM		
By Whom?	Tony Savoie	Date and Hour	6/24/12, NMOCD at 9:14 a.m. BLM at 9:37 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The primary water pump failed to operate properly due to motor bearing problems. The secondary water transfer pump failed to operate due to Head Switch malfunction. The high level alarm failed to operate properly due to a calibration error and wiring problem. All failures were corrected the same day.

Describe Area Affected and Cleanup Action Taken.* Approximately 32,900 ft² of caliche road and tank battery pad area around the JRU-36 and the road going to the Hudson Federal Battery and adjacent well pad. Approximately 800 ft² of pasture land was impacted near the Hudson tank battery. Following initial response activities, the release was remediated as per NMOCD recommended guidelines. Please reference the attached *Remediation Summary & Risk-Based Site Closure Request* for remediation details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	Approved by District Supervisor:	
Printed Name: Tony Savoie	Approval Date: 8/14/14	Expiration Date: NA
Title: Waste Mgmt. & Remediation Specialist	Conditions of Approval:	
E-mail Address: TASavoie@BassPet.com		
Date: 1/22/14	Phone: 432-556-8730	

2R P-1204