
Submit 1 Corg To Appropriate District Office		Jew Mexico		Form C-103 Revised August 1, 2011	
District I			s WELL API NO.		
1625 N. French Dr., Hobbs, NM 88240	1625 N. French Dr., Hobbs, NM 88240			30-015-39064	
strict II OIL CONSERVATION DIVISION 1 A. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Le	5. Indicate Type of Lease		
Disrtict III	1000 Cauth	Ot Francia Dr	STATE		
1000 Rio Brazos Rd. Aztec, NM 87410 District IV	1000 Rio Brazos Rd. Aztec, NM 87410 District IV		6. State Oil & Gas Lea		
District IV Santa Fe, NM 87505				38-0017	
	CES AND REPORTS ON W		7. Lease Name or Uni		
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESERVIOR. USE "APP	A Empire	Abo Unit			
PROPOSALS.) 1. Type of Well: Oil Well Gas V	8. Well Number	103			
2. Name of Operator	/ellOther		9. OGRID Numer		
A		373			
3. Address of Operator 303 Veterans Airpar	10. Pool Name Empire: A	10. Pool Name Empire; Abo (22040)			
4. Well Location	K Lane, otc. 5000, mildiand,			(100 (12040)	
Unit Letter O	: 1175 feet from the		1310 feet from the		
Section 32	Township 17S	Range 28E		County Eddy	
		677' GL	· · · · · · · · · · · · · · · · · · ·	in the second	
				<u>, , , , , , , , , , , , , , , , , , , </u>	
12. Che	ck Appropriate Box To Indica	ite Nature of Notice,	Report, or Other Data		
	INTENTION TO:		SUBSEQUENT REI	PORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMED	IAL WORK		
TEMPORARILY ABANDON			ENCE DRILLING OPNS.		
PULL OR ALTER CASING		—	5/CEMENT JOB NG CASING		
		P AND			
OTHER:		OTHER			
13. Describe proposed or completed of					
any proposed work.) SEE RULE	,	: Attach weilbore diag	ram or proposed completio	n or recompletion.	
CONDITIONS OF A	PPROVAL ATTACHED	,	Approved for plugging of well be	ara only.	
	Les statue - completio		T (ability under bond is retained	bouque receibe	
	d providing work is		of C-103 (Subsequent Report of which may be found at OCD We	Well Plugging)	
Completed by	0-30-2015		Forms, www.cmnrd.state.nm.us/	ocd.	
Apache Corporation proposes					
be used for all f	uids from this wellbore and	d disposed of requi	red by OCD Rule 19.15	5.17.	
			AIBA	011 00110	
			1414	OIL CONSERVATION ARTESIA DISTRICT	
	-			OCT 3 0 2014	
Spud Date:		Rig Release Date:		001 0 0 2014	
I hereby certify that the information above is	true and complete to the best of my	knowledge and belief.		RECEIVED	
		-			
SIGNATURE Dur	2 DUNY TITLE	Sr. Reclamation	n Foreman DATE	10/22/14	
Type or print name	inn Burks E-mail add.	guinn.burks@apa	checorp.com_PHONE:	432-556-9143	
For State Use Only	1	DEPS	v Millen	infail ut	
APPROVED BY:	TITLE TITLE	VB/AL	JOCU () DATE	10/30/ 14	
Conditions of Approval (if any):		001	V	· /	
A See A	Hacked Cl	HS			

'



	•	LEASE NAME WELL #	
1. C		API #	30-015-39064
	SUPERCHE	COUNTY	Eddy, NM
	WELL BORE INFO.		PROPOSED PROCEDURE
0	11" Hole 8 5/8" 24# @ 497' w/ 440 sx to surf		6. PUH & spot 70 sx Class "C" cmt from 692' to surf. (7
622			Rvrs, Surface Shoe, & Water Board)
1245			5. PUH & spot 25 sx Class "C" cmt from 1280'-1030' (Queen)
1867			4. PUH & spot 45 sx Class "C" cmt from 2041'-1627' WOC/TAG (Grayburg/San Andres)
2489	DVT @ 3002' w/516 to surf		
3112			3. PUH & spot 65 sx Class "C" cmt from 3591'-2952' WOC/TAG (Glorieta, Yeso, & DV Tool)
3734			
4356			2. PUH & spot 60 sx Class "C" cmt from 4505'-3897' (Blinebry/Tubb)
4978			1. MIRU, RIH & verify CIBP @ 5762', CIRC w/MLF & spot 25 sx Class "C" cmt from 5762'-5512' WOC/TAG
5601			(Abo/Abo Reef)
	CIBP @ 5762' W/ 35' cmt		Abo perfs @ 5812'-5962'
6223	CIBP @ 5992' w/ 35' cmt 7 7/8" Hole 5 1/2" 17# @ 6223' w/ 492 sx DVT @ 3002' w/ 516 sx to surf	PBTD @ 5762' TD @ 6223'	Abo perfs @ 6012'-6084'

•

. .

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT
Operator: ADache
Well Name & Number: Empire Abo Unit 403
API #: 30-015-39064

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 1 year of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
10. Plugs may be combined after consulting with and getting approval from NMOCD.
11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 10/30/14

APPROVED BY:

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - o Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).