Form 3160-5 (August 2007)

UNITED STATES
DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0135

	Expires: July 31, 2	
Lease	Serial No.	_

OCD Artesia

BUREAU OF LAND MANAGEMENT						July 31, 2010		
SUNDRY NOTICES AND REPORTS ON WELLS					5. Lease Serial No. NMNM0405444			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well Oil Well Sa Gas Well Other					8. Well Name and No. TODD 23A FEDERAL 38			
2. Name of Operator	9. API Well No.							
2. Name of Operator Contact: ERIN WORKMAN DEVON ENERGY PRODUCTION CO.E-Mail: Erin.workman@dvn.com					30-015-35076			
3a. Address 333 WEST SHERIDAN AVEN OKC, OK 73102	o. (include area code 52-7970		10. Field and Pool, or Exploratory SAND DUNES					
4. Location of Well . (Footage, Sec., 7	11. County or Parish, and State			and State				
Sec 23 T23S R31E 660FNL 8		EDDY COUNTY, NM						
12. CHECK APPI	ROPRIATE BOX(ES) TO) INDICAT	E NATURE OF	NOTICE, RI	EPORT, OR OTHE	R DATA		
TYPE OF SUBMISSION	,	TYPE OF ACTION						
Notice of Intent	☐ Acidize	☐ De	epen	☐ Producti	ion (Start/Resume)	■ Water Shut-Off		
•	☐ Alter Casing	☐ Fra	cture Treat	Reclama		■ Well Integrity		
☐ Subsequent Report	Casing Repair	• —	w Construction	Recomp		Other		
☐ Final Abandonment Notice	_ · ·				arily Abandon	•		
13. Describe Proposed or Completed Ope	Disposal							
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fit Devon Energy Production Correcompletion proposal for the Attached: Approved NOI exte	ally or recomplete horizontally, it will be performed or provide operations. If the operation resondonment Notices shall be file nal inspection.) npany, LP respectfully recomplete and 23A Federal 38 that	give subsurface the Bond No. c ults in a multip d only after all	e locations and measure file with BLM/BI/ ole completion or rec requirements, include tension of time to	ured and true ve A. Required sub ompletion in a n ding reclamation o complete th	rtical depths of all pertin sequent reports shall be lew interval, a Form 316 n, have been completed, a	ent markers and zones. filed within 30 days 0-4 shall be filed once and the operator has		
Original (OAS STO Who be a	71 S	Tand Lete	1	NMOCD 199	F-14 ECEIVED /5		
14. I hereby certify that the foregoing is	For DEVON ENERGY Committed to AFMSS for	Y PRODUCTI	ON CO.,LP, sent by JENNIFER MA	to the Carlsba	ad /201(4)(), / [-])			
Name(Printed/Typed) ERIN WOF	RKMAN		Title REGUL	ATORY-COM	MPLIANCE PROF.			
Signature (Electronic S	Date 10/17/2	014 OCT	22.264	772				
	THIS SPACE FO	R FEDERA		OFFICE US	E/ //	loa		
Approved By			Title	CARLSBAT	O MANAGEMENT FIELD OFFICE	Date		
Conditions of approval, if any, are attached ertify that the applicant holds legal or equi which would entitle the applicant to conduct	table title to those rights in the		Office	,				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Todd 23A Federal 38 30-015-35076 Devon Energy Production Co., LP February 03, 2014 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by May 03, 2014.

- 1. Operator shall place CIBP at 14,655' and place a minimum of 25 sx class H cement plug on top. Tag required.
- 2. Operator shall place a balanced class H cement plug from 14,473'-14,223' to seal the top of the Morrow formation.

<u>NOTE:</u> Operator has the option of setting a solid plug on from the CIBP at 14,655'-14,223' instead of step 1 and 2.

- 3. Must conduct a casing integrity test to maximum treating pressure before any work can be done. Submit results to BLM.
- **4.** Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 5. Surface disturbance beyond the originally approved pad must have prior approval.
- 6. Closed loop system required.
- 7. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. Operator to have H2S monitoring equipment on location.
- 9. A minimum of a **5000** (**5M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (5M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

10. Subsequent sundry required detailing work done and completion report with the new formation. Operator to include well bore schematic of current well condition when work is complete.

JAM 020314