

District I,
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

DEC 15 2014

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1435042878

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.

2100737

Contact: Tony Savoie

Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220

Telephone No. 575-887-7329

Facility Name: Big Eddy Unit #74 Tank Battery

Facility Type: Exploration and Production

Surface Owner: Federal

Mineral Owner: Federal

API No. 30-015-22839

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	25	21S	28E					Eddy

Latitude N 32.456855 Longitude W 103.037608

NATURE OF RELEASE

Type of Release: Crude Oil and produced water	Volume of Release: 1 Bbl crude oil and 4 bbls produced water	Volume Recovered: 1 bbl total fluid
Source of Release: Facility flare stack	Date and Hour of Occurrence: 12/4/14 time unknown	Date and Hour of Discovery: 12/4/14 at approximately 1:00 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.

A valve was found closed on the production tank coming from the water dump line, the float valve failed on the scrubber causing fluid to escape from the flare stack. The closed valve was opened and the float valve was repaired.

Describe Area Affected and Cleanup Action Taken.*

The spill misted approximately 500 sq. ft. of pasture area and puddled up in an area of approximately 648 sq. ft. of earthen containment around the flare stack. The pasture area was washed down with micro-blaze. All of the free standing fluid was recovered with a vacuum truck. The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by <u>Specialist</u>	
Title: Waste Management and Remediation Specialist		Approval Date: <u>12/16/14</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>tasavoie@basspet.com</u>		Conditions of Approval:	
Date: 12/15/14		Remediation per O.C.D. Rules & Guidelines	
Phone: 432-556-8730		SUBMIT REMEDIATION PROPOSAL NO	
		LATER THAN: <u>1/16/15</u>	

* Attach Additional Sheets If Necessary

2RP-2664