

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT Form C-141

Revised August 8, 2011

DEC 15 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1435050931

Name of Company: BOPCO, L.P.		OPERATOR	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Contact: Tony Savoie	
Facility Name: PLU-333H Flow Line spill approximately 1.64 miles S.E. of the well and approximately 963 ft. N.E. of the Tank Battery at the PLU-78		Telephone No. 575-887-7329	
		Facility Type: Exploration and Production	T.S. 39294
Surface Owner: Federal		Mineral Owner: Federal	API No. 30-015-39924

LOCATION OF RELEASE							
Unit Letter P	Section 24	Township 24S	Range 24E 30S	Feet from the	North/South Line	Feet from the	East/West Line
							County Eddy

Latitude N 32.196777 Longitude W 103.826680

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 2 bbl oil and 6 bbls produced water	Volume Recovered: 5 bbls. Total fluid
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence: 12/8/14 time unknown	Date and Hour of Discovery: 12/8/14 at approximately 4:45 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The flow line developed a leak due to external corrosion. A repair clamp was placed on the affected area until the flow line could be drained and a section of pipe replaced.		
Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 270 sq.ft. of pasture land and approximately 1450 sq.ft. of lease road. The flow-line is located in an area with at least 10 other flow lines. There have been previous spills from the older flow lines in the corridor. The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: Tony Savoie		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: [Signature]	
Title: Waste Management and Remediation Specialist		Approval Date: 12/16/14	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com		Conditions of Approval:	
Date: 12/15/14 Phone: 432-556-8730		Remediation per O.C.D. Rules & Guidelines	
* Attach Additional Sheets If Necessary		SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 1/16/15	

Attached ☐

2RP-2667