

NM OIL CONSERVATION

ARTESIA DISTRICT

State of New Mexico
Energy Minerals and Natural Resources

OCT 15 2014

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Release Notification and Corrective Action

NAB143548931

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Chevron Midcontinent, L.P. <u>241333</u>	Contact	Stephen Gwin
Address	15 Smith Rd., Midland, TX 79705	Telephone No.	575-263-0427 cell: 575-408-0073
Facility Name	Pardue Farms 26-1/Softail CTB	Facility Type	Battery

Surface Owner	Mineral Owner	API No.	<u>30-D15-22627</u>
---------------	---------------	---------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	26	23S	28E	1980	North	660	West	Eddy

Latitude 32.77764 Longitude -104.064382

NATURE OF RELEASE

Type of Release	Flare	Volume of Release	~300 MCF	Volume Recovered
Source of Release	Flare	Date and Hour of Occurrence	10/8/2014 4:30 PM	Date and Hour of Discovery
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher	
By Whom?	Stephen Gwin	Date and Hour	10/9/2014 10:00 AM	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.		

If a Watercourse was Impacted. Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

One of the electric compressor engines lost suction and was automatically shut down. The shutdown of the compressor engine resulted in the routing of the sales gas to the emergency/ upset flare. The flare operated as designed as a safety device.

Describe Area Affected and Cleanup Action Taken.*

The malfunctioning actuator was reset and the compressor engine was turned on to flow gas to sales line.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Stephen Gwin</u>	OIL CONSERVATION DIVISION	
Printed Name: Stephen Gwin	Approved by Environment Specialist: <u>Mike Bratcher</u>	
Title: Health and Environment Specialist	Approval Date: <u>10/15/14</u>	Expiration Date: <u>N/A</u>
E-mail Address: Stephen.gwin@chevron.com	Conditions of Approval: <u>FINAL</u>	Attached <input type="checkbox"/>
Date: 10/15/2014	Phone: 575-263-0427	

* Attach Additional Sheets If Necessary

2RP-2671