# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135

·	Expires:		
Lease Seri	ial No.		

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					NMNMU4U5444A			
					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.			
Type of Well     Gas Well				8. Well Name and No. TODD 22N FED 14				
Name of Operator					9. API Well No. 30-015-32734-00-S1			
			3b. Phone No. (include area code) Ph: 405-552-7970			10. Field and Pool, or Exploratory INGLE WELLS-DELAWARE		
4. Location of Well (Footage, Sec., T	)	*,	· ·	11. County or Parish,	and State			
Sec 22 T23S R31E SESW 66				EDDY COUNTY, NM				
12. CHECK APPI	ROPRIATE BOX(ES) TO	) INDICATE	NATURE OF	NOTICE, F	REPORT, OR OTHE	R DATA		
TYPE OF SUBMISSION								
Notice of Intent     ■	☐ Acidize	□ Deep	epen		ction (Start/Resume)	☐ Water Shut-G	Off	
<del>-</del>	☐ Alter Casing	☐ Fracture Treat		□ Reclar	☐ Reclamation		Well Integrity	
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	□ Recon	nplete	Other		
☐ Final Abandonment Notice	. Change Plans	Plug	and Abandon	□ Temporarily Abandon		•	:	
	☐ Convert to Injection	□ Plug	Back .	.   Water Disposal				
following completion of the involved testing has been completed: Final Al determined that the site is ready for following procedure:  -Test Anchors -MIRU WSU -ND WH, NU BOPE & test -TOH with 2-7/8 tubing & BHA-Make gauge run to 8000? KE-TIH with retrievable packer to if casing does not test, run cafor P&A -if casing does test,	bandonment Notices shall be fil inal inspection.)  LP respectfully requests  Accept	recomplete the state of the sta	equirements, include Todd 22N F	ed 14 with the	on, have been completed,	i OIL CONSE ARTESIA DIST	RVAT TRICT 2014	
14. I hereby certify that the foregoing is	Electronic Submission # For DEVON ENERG	GY PRODUCT	ON CO LP, ser	nt to the Carls	sbad	No. 10		
Name (Printed/Typed) ERIN WO	mitted to AFMSS for proce RKMAN	samy by JEN			(153AM01005E) OMPLIANCE PROF	<del></del>		
		-		7	PPRINFIT			
Signature (Electronic	Submission)		Date 11/25	2014	IIIOVED			
	THIS SPACE FO	OR FEDERA	L OR STAT	OFFICE	185 2 g 2014			
Approved By  Conditions of approval, if any, are attache certify that the applicant holds legal or equal to the certify that the applicant holds legal or equal to the certify that the applicant holds legal or equal to the certify that the applicant holds legal or equal to the certificant holds legal or equal to the certifica	ed. Approval of this notice does	s not warrant or	Title	DIJOEAL	motion Da	ON Baje		
which would entitle the applicant to cond	uct operations thereon.		Office	7		<u> </u>		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any posto any matter w	rson knowingly a ithin its jurisdiction	nd willfully to on.	make to any department o	agency of the Unite	d	

#### Additional data for EC transaction #281952 that would not fit on the form


#### 32. Additional remarks, continued


- -TIH with packer to 8000? and make swab runs to determine oil cut from perforated zone 8056-8077? KBM

- KBM
  -Repeat at 7700? for perforated zone 7741-7750?
  -Repeat at 6950? for perforated zone 7000-7014?
  -Repeat at 6800? for perforated zone 6871-6878?
  -Based on results, request plug back of non-productive zones
  -Wireline set 5-1/2? CIBP @ 6820?
  -Dump Bail 35? of Cement, Estimating top of cement plug at 6785?
  -Load and circulate hole with 2% KCL
  -Test casing and CIBP w/ cement plug to 500 psi at surface for 30 minutes with chart test & NMOCD/BLM witness
  -Recomplete uphale in Upper Brushy Canyon and/or Cherry Canyon based on geology recomplete uphale in Upper Brushy Canyon and/or Cherry Canyon based on geology recomplete.
- -Recomplete uphole in Upper Brushy Canyon and/or Cherry Canyon, based on geology recommendation -ND BOP, NU WH -RDMO WSU -Return well to production

Attachments: Current Wellbore

Proposed Wellbore





## Todd 22N Fed 14 30-015-32734 Devon Energy Production Co., LP November 28, 2014 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by February 28, 2015.

- 1. Operator shall place a balanced class H cement plug from 8,300'- 8,100'to seal the top of the Bone Spring formation. WOC and tag.
- 2. Must conduct a casing integrity test to 1500 psi or 0.22 psi per foot whichever is greater. If casing test fails, submit remediation or P&A plan to the BLM.
- 3. If producing zone is found unproductive, operator shall place CIBP at 6,820' and operator may place 35' class C cement on top in order to recomplete in the Brushy and/or Cherry Canyon. Tag required.

<u>NOTE:</u> Operator must add 25sx class C cement to the top of the CIBP prior to abandoning the Delaware zone.

- 4. Must conduct a casing integrity test to maximum treating pressure before any work can be done. Submit results to BLM.
- 5. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 6. Surface disturbance beyond the originally approved pad must have prior approval.
- 7. Closed loop system required.
- 8. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 9. Operator to have H2S monitoring equipment on location.

- 10. A minimum of a **3000** (**3M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 11. Subsequent sundry required detailing work done and completion report with the new formation. Operator to include well bore schematic of current well condition when work is complete.
- 12. See attached for general requirements.

JAM 112814

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220

575-234-5972

### **General Requirements for Plug Backs**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **ninety (90)** days from this approval.

If you are unable to plug back the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class "C"**, for up to 7,500 feet of depth or **Neat Class "H"**, for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.