Form 3160-5 (March 2012)

Final Abandonment Notice

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

5. Lease Serial No. NM-0531075

SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. NM70951C 1. Type of Well 8. Well Name and No. FNRU #9 ✓ Oil Well Other Gas Well 2. Name of Operator STRATA PRODUCTION COMPANY 9. API Well No. 30-015-35008 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area P.O. BOX 1030 ROSWELL, NM 88202 FORTY NINER RIDGE; DELAWARE 575-622-1127 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 330 FSL & 2630 FWL. SEC. 10 - 123S - R30E 11. County or Parish, State **EDDY** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction ✓ Recomplete ✓ Subsequent Report ADD ADDITIONAL PAY Change Plans Plug and Abandon Temporarily Abandon Plug Back Convert to Injection Water Disposal

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

3-05-2014 MIRU workover rig, reverse pumps, and wireline. Set CIBP @ 7100'. Perforate 6642'-7030' w/ 20 holes, acidize w/ 1500 gal 15% NeFe acid, frac w/ 96,000#. Perforate 6124'-6156' w/ 20 holes, acidize w/ 1000 gal 15% NeFe acid, frac /w 115,000#. Perforate 5810'-5914' w/ 23 holes, acidize w/ 1000 gal 15% NeFe acid, frac w/ 109,000#.

5-16-2014 MIRU workover unit and reverse pumps. Drill through CIBP @ 7100'. Install Andrews Pump THC pump. Turn well to production

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NM OIL CONSERVATION

ARTESIA DISTRICT

DEC 3 0 2014

ACCEPTED FOR RECORD

BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE

RECEIVED	
14. Thereby certify that the foregoing is true and correct. Name (Printed/Typed)	IVED
Paul Ragsdale	
Tit	itle Operations Manager
Signature Jan Raydule Day	ate 06/16/2014
Approved by	
	Title Date:
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certif that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person	on knowingly and willfully to make to any department or agency of the United States any fals