District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resource's

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

| Release Notification and Corrective Action | |
|---|---|
| | OPERATOR |
| Name of Company BOPCO, LP | Contact Tony Savoie |
| Address 522 W. Mermod, Suite 704 Carlsbad, NM 88220 | Telephone No. (432) 556-8730 |
| Facility Name Poker Lake Unit #79 | Facility Type E & P |
| Surface Owner Federal Mineral Owner | : Federal Lease No. B-10679 |
| LOCATION OF RELEASE | |
| Unit Letter Section Township Range 30E Feet from the Nort | h/South Line Feet from the East/West Line County Eddy |
| Latitude N 32.154414 Longitude W 103.857821 | |
| NATURE OF RELEASE | |
| Type of Release Produced water and crude oil | Volume of Release: 40 bbls of produced water and 20 bbls of crude oil. Volume Recovered: 10 bbls total fluid |
| Source of Release: Heater Treater | Date and Hour of Occurrence 5/2/11, Hour unknown 5/2/11 10:00 a.m. |
| Was Immediate Notice Given? X Yes No Not Required | If YES, To Whom? Mike Bratcher via voicemail |
| By Whom? Tony Savoie | Date and Hour: 5/2/11 10:51 a.m. |
| Was a Watercourse Reached? ☐ Yes ☑ No | If YES, Volume Impacting the Watercourse. |
| If a Watercourse was Impacted, Describe Fully.* | |
| Describe Cause of Problem and Remedial Action Taken.* A gasket failed on the heater treater fire tube. During initial response activities, the heater was isolated, and the gasket was replaced. | |
| Describe Area Affected and Cleanup Action Taken.* The caliche pad around the pumping well and tank battery location had isolated packets of produced water and crude oil. The liquid also travelled down a lease road for approximately 360 ft. The entire area of the well pad and battery location was also covered with a fine mist of crude oil and produced water; this was approximately 67,500 sq. ft. The pasture land located to the South West of the battery was also affected with the fine mist of crude oil and produced water; this area was approximately 33,600 sq. ft. The release was remediated as per NMOCD guidelines. Please see the attached <i>Remediation Summary & Risk-Based Site Closure Request</i> , dated May 2012, for details of remediation activities and laboratory analytical results from confirmation soil samples. | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | |
| | OIL CONSERVATION DIVISION |
| Signature: | |
| Printed Name: Bens. Arguijo (Agent of Beco LP) | Approved by District Supervisor: |
| Title: Was Formander, Basin Environmental | Approval Date: 9/3/14 Expiration Date: M |
| E-mail Address: tasavoie@basspet.com Siarmip & basspinu.com Conditions of Approval: Attached Date: 2/14/12 Phone: (432) 556-8730 (806) 549-9597 | |

RECEIVED
FEB:14 2013
NMOCD ARTES!A