UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No. NMNM114971

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned we	ll. Use form 3160-3 (APD) for su	ch proposals.		6. If Indian, Allottee of	or Tribe Name	
SUBMIT IN TRI	PLICATE - Other instructions on	reverse side.		7. If Unit or CA/Agre	ement, Name and/or No.	
Type of Well Gas Well	8. Well Name and No. OWL DRAW 22-27 B2AP FED COM 1H					
Name of Operator MEWBOURNE OIL COMPAN	Contact: JACKIE		9. API Well No. 30-015-41430			
3a. Address PO BOX 5270 HOBBS, NM 88241		e No. (include area code 5-393-5905)	10. Field and Pool, or Exploratory BONE SPRING		
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish,	and State	
Sec 15 T26S R27E Mer NMP		EDDY COUNTY, NM				
12. CHECK APPI	ROPRIATE BOX(ES) TO INDICA	ATE NATURE OF I	NOTICE, RE	PORT, OR OTHE	R DATA	
TYPE OF SUBMISSION		TYPE O	TYPE OF ACTION			
☐ Notice of Intent	_	Deepen Fracture Treat	☐ Production ☐ Reclama	on (Start/Resume)	☐ Water Shut-Off ☐ Well Integrity	
Subsequent Report ■	☐ Casing Repair ☐	New Construction	☐ Recompl	ete	Other	
☐ Final Abandonment Notice		Plug and Abandon	. —		Drilling Operations	
	☐ Convert to Injection ☐	Plug Back	☐ Water Di	sposal		
Attach the Bond under which the wor following completion of the involved	ally or recomplete horizontally, give subsurk will be performed or provide the Bond Noperations. If the operation results in a minandonment Notices shall be filed only after nal inspection.) B77'. Ran 5877' of 9 5/8" 40# HCL! Mixed @ 12.5#/g w/2.13 yd. Tail v @ 1:30 P.M. 06/22/14. Drop bomb mt to the pit. Cmt 2nd stage w/45t w/2.13 yd. Tail w/200 sks Class C/14. Circ 13 sks of cmt to the pit. Telested csg to 1500# for 30 mins,	lo. on file with BLM/BIA	A. Required subsompletion in a ne	equent reports shall be sw interval, a Form 316 have been completed, a Lite bugh DVMM OIL ARTE	ifiled within 30 days 3-4 shall be filed once and the operator has CONSERVATION 2 2015	
14. I hereby certify that the foregoing is	true and correct.		-			
Name(Printed/Typed) JACKIE LA	Electronic Submission #257012 ver For MEWBOURNE OIL C Committed to AFMSS for process	OMPANY, sent to the	ė Carlsbad M. on 01/15/2	154	FOR RECORD	
Signature (Electronic S	ubmission)	Date 08/14/20	014	JAN 2	2 2015	
	THIS SPACE FOR FEDE	RAL OR STATE	OFFICE US	E () /sh	ch Han	
Approved By		Title	· .	BUREAU OF LAN CARLSBAD	ID MANAGEMENT FIELD OFFICE	
	. Approval of this notice does not warrant table title to those rights in the subject least operations thereon.					

Additional data for EC transaction #257012 that would not fit on the form

32. Additional remarks, continued

Bond on file: NM1693 nationwide & NMB000919

NELDING SERVICES, AVC

Company Mewboard Date 6-23-14	4
Lease Owl draw 23/27 BOAP Fed Collecting Edy Co NM.	L
Drilling Contractor Pallerson 187 Plug & Drill Pipe Size 11 (28/4)	aIF
Accumulator Pressure: Soco Manifold Pressure: 1500 Annular Pressure:	500
Accumulator Function Test - OO&GO#2	
To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)	
 Make sure all rams and annular are open and if applicable HCR is closed. Ensure accumulator is pumped up to working pressure! (Shut off all pumps) 	
Open HCR Valve. (If applicable) Close annular. Close all pipe rams.	
4. Open one set of the pipe rams to simulate closing the blind ram. 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater sy 6. Record remaining pressure / 4000 psi. Test Fails if pressure is lower than required to 1500 psi. 1500	stems). 1.
a. (950 psi for a 1500 psi system) b. (1200 psi for a 2000 & 3000 psi system) 7. If annular is closed, open it at this time and close HCR.	

To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:

 a. [800 psi for a 1500 psi system] b. [1100 psi for 2000 and 3000 psi system]
 - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
 - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
 - 3. Record pressure drop / Oco psi. Test fails if pressure drops below minimum.
- Minimum: a. [700 psi for a 1500 psi system] b. [900 psi for a 2000 & 3000 psi system]

To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- o Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, (manifold psi should go to 0 psi) close bleed valve.
 - 1. Open the HCR valve, (if applicable)
 - 2. Close annular
 - 3. With pumps only, time how long it takes to regain the required manifold pressure.
 - 4. Record elapsed time / 10 32 Se dest fails if it takes over 2 minutes.
 - a. (950 psi for a 1500 psi system) b. (1200 psi for a 2000 & 3000 psi system)



WELDING • BOP TESTING
NIPPLE UP SERVICE • BOP LIFTS • TANDEM
MUD AND GAS SEPARATORS

٠.		WELDING SERVIC	E 8	Lovington, N	GAS SEPAFIM • 575		Pg	of
	(IAbr	. Membourne		6	600	12-14	Invoice #	B47235
	Compan	2 wl draw 22/27	220 C.1	Date:				157
	ease:	11/ 0/2	Drill Pipe	146 11	Contracti	or: FGDT GU	SOIN RIE#	naxwell
			Drill Pipe		alled BOP		or Dan	· · · · · · · · · · · · · · · · · · ·
	ppropriate	Casing Valve Must Be Open During BOP T	est *	inst	alled BUP		Valve Must Be Open/Disal	oled To Test Kill Line Valve
			#26	'n	* 1.5 * - 1.5		A A	Dart 🗐 🗕
٠				L.		$f \cap \widehat{f}$) g	Valve #19
		o h o o h o	#2	7) 1	2 0			Stand Pipe
		Annular #15	#4 (\$.	Kelly/ Top		Valve #24
	•		<u>=</u> ∕ ااا——ا			Drive		· [1]
	ſ .	Pipe Rams #12			,	IBOP (B	#22	#23 TIW S Valve
			#3 () ~8°		#17		#18
,			#1	#8B Mud Gau		Manual &	اسا	
				Valve		#16	Pump Valve P	ump Valve #21
	#11 #1		ـــاـــــــــــــــــــــــــــــــــ	HJ				
	Œ	Pipe Rame win		Choke				
					•			
C-	5-4-	Casing						
-	TEST #	ITEMS TESTED	TEST LENGT	H LOW PSI	HIGH PSI		REMARKS	
ا	TEST #	ITEMS TESTED 15.97	TEST LENGT	H LOW PSI	HIGH PSI	Tessed	REMARKS	
ı	TEST #	15.97 12.97	10/10	H LOW PSI 250	1	Passed Passed	REMARKS	
	TEST #	15, 9, 7 12, 9, 7 12, 10, 8	10/10 10/10	250	1	Passed	REMARKS	
1	12	15,9,7 12,9,7 12,10,8	10/10	250	1500 3000 3000	Passed Passed	REMARKS	
7	12	15, 9, 7 12, 9, 7 12, 10, 8 12, 10, 8, 4, 5, 8 1	10/10 10/10 10/10 3 10/10	250 250 250	7500 3000 3000 3000	Passed Passed	REMARKS	
?	12	15,9,7 12,9,7 12,10,8 13,10,8,4,581 13,11,1,2,6,30	10/10 10/10 10/10 3 10/10	250	/502 3000 3000 3000 5000	Passed Passed		
?	12	15,9,7 12,9,7 12,10,8	10/10 10/10 10/10 3 10/10	250 250 250	7500 3000 3000 3000	Passed Passed Passed Passed Passocal	Ly to 3	20000
?	12	15,9,7 12,9,7 12,10,8 13,10,8,4,581 13,11,1,2,6,30	10/10 10/10 10/10 3 10/10 10/10	250 250 250 250	1500 3000 3000 3000 3000 3000	Passed Passed Passed Passed Passed Choles	Ly to 3	200 os
7	1234567	15,9,7 12,10,8 12,10,8,4,5,81 13,11,1,26,30 13,11,25,24,6,30	10/10 10/10 10/10 3 10/10 3 30MpT	250 250 250 250 250 250	1500 3000 3000 3000 3000 3000	Passed Passed Passed Passed Choles	Ly to 3	200 os
?	123456 78	15,9,7 12,10,8 12,10,8,4,5.81 13,11,1,26,30 13,11,25,24,6,30	10/10 10/10 3 10/10 3 10/10 3 3 mpl	250 250 250 250 250 250	7500 3000 3000 3000 3000 3000 3000	Passed Passed Passed Passed Passed Choles Passed Passed	Ly to 3	20000 50x
7	1234567	15,9,7 12,10,8 12,10,8,4,5,81 13,11,1,2,6,30 13,11,25,24,6,30 16	10/10 10/10 10/10 3 10/10 3 3 mg T. 10/10	250 250 250 250 250 250 250	7500 3000 3000 3000 3000 3000 3000 3000	Passed Passed Passed Passed Passed Choles Passed Passed	Ly to 3	20000 5PF
7	123456 78	15,9,7 12,10,8 12,10,8,4,5.81 13,11,1,26,30 13,11,25,24,6,30	10/10 10/10 3 10/10 3 10/10 3 3 mpl	250	7500 3000 3000 3000 3000 3000 3000	Passed Passed Passed Passed Passed Choles Passed Passed	Ly to 3	2000
?	123456 78	15,9,7 12,10,8 12,10,8,4,5,81 13,11,1,2,6,30 13,11,25,24,6,30 16	10/10 10/10 10/10 3 10/10 3 3 mg T. 10/10	250 250 250 250 250 250 250	7500 3000 3000 3000 3000 3000 3000 3000	Passed Passed Passed Passed Passed Choles Passed Passed	Ly to 3	200 os
?	123456 78	15,9,7 12,10,8 12,10,8,4,5,81 13,11,1,2,6,30 13,11,25,24,6,30 16	10/10 10/10 10/10 3 10/10 3 3 mg T. 10/10	250 250 250 250 250 250 250	7500 3000 3000 3000 3000 3000 3000 3000	Passed Passed Passed Passed Passed Choles Passed Passed	Ly to 3	2000
7	123456 78	15,9,7 12,10,8 12,10,8,4,5,81 13,11,1,2,6,30 13,11,25,24,6,30 16	10/10 10/10 10/10 3 10/10 3 3 mg T. 10/10	250 250 250 250 250 250 250	7500 3000 3000 3000 3000 3000 3000 3000	Passed Passed Passed Passed Passed Choles Passed Passed	Ly to 3	20000 504
7	123456 78	15,9,7 12,10,8 12,10,8,4,5,81 13,11,1,2,6,30 13,11,25,24,6,30 16	10/10 10/10 10/10 3 10/10 3 3 mg T. 10/10	250 250 250 250 250 250 250	7500 3000 3000 3000 3000 3000 3000 3000	Passed Passed Passed Passed Passed Choles Passed Passed	Ly to 3	2000 5PF
7	123456 78	15,9,7 12,10,8 12,10,8,4,5,81 13,11,1,2,6,30 13,11,25,24,6,30 16	10/10 10/10 10/10 3 10/10 3 3 mg T. 10/10	250 250 250 250 250 250 250	7500 3000 3000 3000 3000 3000 3000 3000	Passed Passed Passed Passed Passed Choles Passed Passed	Ly to 3	2000
7	123456 78	15,9,7 12,10,8 12,10,8,4,5,81 13,11,1,2,6,30 13,11,25,24,6,30 16	10/10 10/10 10/10 3 10/10 3 3 mg T. 10/10	250 250 250 250 250 250 250	7500 3000 3000 3000 3000 3000 3000 3000	Passed Passed Passed Passed Passed Choles Passed Passed	Ly to 3	200 os
7	123456 78	15,9,7 12,10,8 12,10,8,4,5,81 13,11,1,2,6,30 13,11,25,24,6,30 16	10/10 10/10 10/10 3 10/10 3 3 mg T. 10/10	250 250 250 250 250 250 250	7500 3000 3000 3000 3000 3000 3000 3000	Passed Passed Passed Passed Passed Choles Passed Passed	Ly to 3	2000





