

WELL API NO.

30-015-34935

5. Indicate Type of Lease

STATE

FEE X

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

SWD 4-22-27

8. Well Number

001

9. OGRID Number

229137

10. Pool name or Wildcat

SWD; DELAWARE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other SWD

2. Name of Operator

COG OPERATING LLC

3. Address of Operator

600 W. ILLINOIS AVE., MIDLAND, TEXAS 79701

4. Well Location

Unit Letter H : 2310 feet from the NORTH line and 1060 feet from the EAST line
Section 04 Township 22S Range 27E NMPM EDDY County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3,100' - GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON X
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A
CASING/CEMENT JOB ☐

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) TAG EXISTING 5-1/2" CIBP + CMT. @ +/-2,485'; CIRC. WELL W/ PXA FLUID.
- 2) PUMP 25 SXS. CMT. @ 1,794'-1,674' (T/DLWR.); WOC X TAG CMT. PLUG.
- 3) MIX X CIRC. TO SURF. 70 SXS. CMT. @ 475'-3'.
- 4) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER.

DURING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM W/ A STEEL TANK AND HAUL CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17.

CONDITIONS OF APPROVAL ATTACHED

Approval Granted providing work is Completed by

Feb 24, 2016

Rig Release Date:

Approved for plugging of well bore only.
Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmard.state.nm.us/oed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE: AGENT DATE: 02/17/15

Type or print name: DAVID A. EYLER

E-mail address: DEYLER@MILAGRO-RES.COM

PHONE: 432.687.3033

For State Use Only

APPROVED BY:  TITLE: _____

DATE: _____

Conditions of Approval (if any):

RODado

Dir & Supervisor

2/24/15

* see Attached COA's

Well: SWD 4-22-27 No. 1

Location: 2310' FNL 1060' FEL
H-4-22-27
Eddy NM
30-015-34935

Zero: 14' AGL


KB: 3114'

GL: 3100'

Casing Program:

Size	Wt.	Grade	Conn	Depth
8 5/8"	24	J55	JK	423'
5 1/2"	17	J55	LTC	5334'
2 7/8"	6.5	J55	EVE	IPC

@ 1953' MD (1948' TVD) 2294' FNL, 943' FEL



1st: 450 Super H (Circ 204 sx)

2nd: 500 HLC + 200 "C" (Circ 103 sx)

Well: SWD 4-22-27 No. 1

Location: 2310' FNL 1060' FEL
H-4-22-27
Edy NM
30-015-34935


Zero: 14' AGL

KB: 3114'

GL: 3100'

Casing Program:

Size	Wt.	Grade	Conn	Depth
8 5/8"	24	J55	JT	423'
5 1/2"	17	J55	LTC	5334'
2 7/8"	6.5	J55	EVE	IPC



@ 1953' MD (1918' TVD) 2294' FNL, 943' FEL
 8 5/8" @ 423'
 375" C" (circ 103x)

Pump 25 SXS. CMT. @ 1794'-1674' - TAG

5 1/2" CSBP @ 2520' w/ 35' cmt. (03/31/12 - 04/04/12)

DVE 3117'

CIBP 3360' + 1 bailer cmt.

4164-4214' (18) Del 3

4810-18' (27) Del 2

5168-93 (48) Del 2

5 1/2" @ 5334'

1st: 450 Super H (circ 204 sx)

2nd: 500 HLC + 200" C" (circ 103 sx)

DAS 02/17/15

NEW MEXICO OIL CONSERVATION DIVISION
DISTRICT 2 OFFICE
811 S. FIRST STREET
ARTESIA, NM 88210
(575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: CO6

Well Name & Number: SWD-4-22-27 #1

API #: 30-015-34935

1. Produced water **will not** be used during any part of the plugging & abandonment operation.
2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
4. Trucking companies being used to haul oilfield waste fluids to a disposal – commercial or private – shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
5. A subsequent C-103 will serve as notification that the well bore has been plugged **ONLY**. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
10. Plugs may be combined after consulting with and getting approval from NMOCD.
11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 2/24/2015

APPROVED BY:

RD

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - Fusselman
 - Devonian
 - Morrow
 - Wolfcamp
 - Bone Spring
 - Delaware
 - Any Salt Section (Plug at top and bottom)
 - Abo
 - Glorieta
 - Yates (this plug is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).