1						· .		
Form 3160-5 (August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM01165 6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRI	rerse side.		7. If Unit or CA/Agreement, Name and/or No.					
1. Type of Well	· · ·	· · ·	8. Well Name and No. GLOCK 17 B2EH FEDERAL 1H					
2. Name of Operator Contact: JACKIE LATHAN MEWBOURNE OIL COMPANY E-Mail: jlathan@mewbourne.com					9. API Well No. 30-015-42664			
3a. Address 3b. Phone N. PO BOX 5270 Ph: 575-39 HOBBS, NM 88241 Ph: 575-39			. (include area co 3-5905	de)	10. Field and Poo BONE SPR	eld and Pool, or Exploratory DNE SPRING		
4. Location of Well (Footage, Sec., T	11. County or P			arish, and State				
Sec 17 T20S R29E Mer NMP			EDDY COUNTY, NM					
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE	NATURE O	F NOTICE, RI	EPORT, OR OT	HER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION							
 Notice of Intent Subsequent Report 	 Acidize Alter Casing 		racture Treat		mplete X Other porarily Abandon Drilling Operations			
Final Abandonment Notice	 Casing Repair Change Plans Convert to Injection 	Construction and Abandon Back	 Recomp Tempor Water D 					
 Describe Proposed or Completed Ope If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi 10/11/14 TD 17 1/2" hole. Ran Class C (35:65:4) w/additives. @ 14.8#/g w/1.33 yd. Plug dow to 1250#. At 11:00 A.M. 10/13 	Illy or recomplete horizontally, gi k will be performed or provide th operations. If the operation resu andonment Notices shall be filed nal inspection.) 1337' of 13 3/8" 54.5# J55 Mixed @ 12.5 #/g w/2.20 wn @ 10:00 AM 10/12/14.	ive subsurface he Bond No. or lls in a multipl l only after all n 5 & 48# H40 yd. Tail w/20 Circ 94 sks	locations and mean file with BLM/E e completion or re requirements, incl ST&C csg. C 00 sks Class C of cement to p	asured and true ve IA. Required sub- ecompletion in a n uding reclamation emented with (w/1% CaCl2. if. WOC. Teste	rtical depths of all p sequent reports sha lew interval, a Form h, have been comple 500 sks Mixed	pertinent markers and ll be filed within 30 of 3160-4 shall be filed	zones. lays l once	
1/4" bit. Charts & Schematic attached.	100	2/11/15	NM O	IL CONSERV	ATION			
, · · ·			ACCOR		ARTESIA DISTRICT			
Bond on file: NM1693 nationwi Bond on file: 22015694 nation	1	MOCD	FEB 06 2015					
					k	RECEIVED		
14. Thereby certify that the foregoing is Name(Printed/Typed) JACKIE LA Signature (Electronic Si	Electronic Submission #27 For MEWBOURN Committed to AFMSS for ATHAN		PANY, sent to by DEBORAH	the Carlsbad HAM on 01/28/2 ORIZED REPI	ACCEPTE		CORD	
	THIS SPACE FOR					3 4 2015	+-+	
					- IAD	The Nam	<u>x</u>	
Approved By			Title		BUREAU OF CARLSE	LAND MANAGEN BAD FIELD DEFICE	IENT	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office					
Fitle 18 U.S.C. Section 1001 and Title 43 U States any false, fictitious or fraudulent st	J.S.C. Section 1212, make it a cri atements or representations as to	ime for any per any matter wit	son knowingly ar hin its jurisdictio	nd willfully to main.	ke to any departmen	t or agency of the U	nited	

ï

٠

. .

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

NAN WELDING SERVICES

Company Mer Burne Date 10-13-Lease Glock 17 BaEH Fed. #14 County Eddy N.M. Drilling Contractor Patter 500 Plug & Drill Pipe Size 2 (2) 3. 4 Accumulator Pressure: 200 Manifold Pressure: 1500 Annular Pressure: Accumulator Function Test - 00&GO#2

To Check - USABLE FLUID IN THE NITROGEN BOTTLES, (III.A.2.c.i. or if or iii)

• Make sure all rams and annular are open and if applicable HCR is closed. • Ensure accumulator is pumped up to working pressure! (Shut off all pumps)

1. Open HCR Valve. (If applicable)

2. Close annular. 3. Close all pipe rams.

4. Open one set of the pipe rams to simulate closing the blind ram.

.5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).

6 Record remaining pressure 500 psi. Test Falls if pressure is lower than required:

a. [950 psi for a 1500 psi system] b. [1200 psi for a 2000 & 3000 psi system]

7. If annular is closed, open it at this time and close HCR.

To Check PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.).

• Stan with manifold pressure at, or above, maximum acceptable pre-charge pressure: a. (800 psi for a 1500 psi system) b. [1100 psi for 2000 and 3000 psi system]

1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure) 2. Close bleed line. Barely burnp electric pump and see what pressure the needle jumps up to. 3: Record pressure drop 30 pst. Test fails if pressure drops below minimum. • Minimum: a (700 psi for a 1500 psi system.) b (900 psi for a 2000 & 3000 psi system)

To Check THE CAPACITY OF THE ACCUMULATOR PUMPS (III A.2.f.)

• Isolate the accumulator bottles or spherical from the pumps & manifold.

• Open the bleed off valve to the tank, [manifold psi should go to 0 psi] close bleed valve

1. Open the HCR valve. [if applicable]

2. Close annular 3. With pumps only, time how long it takes to regain the required manifold pressure.

4. Record elapsed time 1:23 ... Test fails if it takes over 2 minutes.

a. [950 psi for a 1500 psi system] b. [1200 psi for a 2000 & 3000 psi system]

WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS _____ of <u>/</u>. Pg. / Welding Ser Lovington, NM • 575-398-4540 * 69018 Company: MEWBOULDE Date: 10-13-14 Lesse: Glock 17 B2FH Fed # Drilling Contractor: 10TTE 501 Plug Size & Type: 12"C22 Drill Pipe Size Tester Anic . . that Required BOP: 250 Appropriate Casing Valve Must Be Open During BOP Test Check Valve Must Be Open/Disabled To Test Kill Line Valves #26 Dart Valve #19 #2 10000 Stand Pipe Valve Kélly/ #24 Annular #15 #4 Тор #5 Drive (C) H22. #23 TIW Pipe Rams #12 -----IBOP Valve قت ا #3 #18 #17 Blind Rams #13 -#8B Manual LE KOR Mud Gauge IBOP <u>o nan</u> Valve Pump Valve Pump Valve #16 #21 #20 #7 #8 #11 #10 #9 #25 Pipe Rams #14 Super Choke Casing 1250 ITEMS TESTED TEST LENGTH LOW PSI HIGH PSI REMARKS TEST # 250 何对 0' ruc 1250 250 45 1250 250 10 a 1250 4 $(\cap$ £J. 1250 250 ar Ľ Raj. 00 1250 & Bloed 259 Æ ressure. U 0 1250 150 250 250 8 (5 25 250 Q brko υ 24 2 34 25 ×. 8.15 ê.

17







