

NM OIL CONSERVATION

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

ARTESIA DISTRICT

FEB 25 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141
Revised August 8, 2011

RECEIVED

Release Notification and Corrective Action

NAB1505733333

OPERATOR

Initial Report Final Report

Name of Company <i>Cimarex Energy</i> <i>1621683</i>	Contact <i>Christine Alderman</i>
Address <i>600 N Marienfeld Ste 600 Midland TX</i>	Telephone No. <i>432-853-7059</i>
Facility Name <i>Liberty 24 Fed #4</i>	Facility Type <i>Production</i>

Surface Owner <i>BLM</i>	Mineral Owner	API No. <i>30-015-42262</i>
--------------------------	---------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>D</i>	<i>24</i>	<i>25S</i>	<i>26E</i>	<i>330</i>	<i>FNL</i>	<i>660</i>	<i>FWL</i>	<i>Eddy</i>

Latitude *32.12176* Longitude *-104.25277*

NATURE OF RELEASE

Type of Release <i>oil</i>	Volume of Release <i>40 bbls</i>	Volume Recovered <i>40 bbls</i>
Source of Release <i>tank</i>	Date and Hour of Occurrence <i>2/24/15 afternoon</i>	Date and Hour of Discovery <i>2/24/15 afternoon</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Mike Bratcher/Sol Hughes</i>	
By Whom? <i>Christine Alderman</i>	Date and Hour <i>2/25/15 11:00am</i>	<i>10:22 AM - e-mail</i>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The drain valve on the flare scrubber was left open allowing gas to go to tank. Tanks were full enough that the gas rolling the oil caused the oil to splash out the thief hatches.

Describe Area Affected and Cleanup Action Taken.*
All fluids were contained in a LINED containment and were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Christine Alderman</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <i>ESH Supervisor</i>	Approval Date: <i>2/26/15</i>	Expiration Date:
E-mail Address: <i>calderman@cimarex.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date:	Phone: <i>432-853-7059</i>	

* Attach Additional Sheets If Necessary

2 RP-2839