

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

MAR 6 2015

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB150684211 192463 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: OXY USA WTP Limited Partnership	Contact: Chris Jones
Address: 102 S. Main St. Carlsbad, NM 88220	Telephone No.: 575-628-4121
Facility Name: Winston Gas SWD #4	Facility Type: SWD

Surface Owner: Federal	Mineral Owner:	API No.: Lease #: 30-015-30337
------------------------	----------------	--------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	31	21S	24E	1535'	North	660'	West	Eddy

Latitude 32.43826 N Longitude -104.54515 W

NATURE OF RELEASE

Type of Release: <b>Produced Water</b>	Volume of Release: <b>30 bbl</b>	Volume Recovered: <b>15 bbls</b>
Source of Release: <b>Bull Plug Broke</b>	Date and Hour of Occurrence <b>2/26/15</b>	Date and Hour of Discovery <b>2/26/15</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <input type="checkbox"/> The bull plug broke on the discharge line of the red pump causing a release of 30 barrels of produced water. The facility was shut-in, the plug was replaced and the facility was put back into service. A vacuum truck was immediately called to the location and 15 barrels of produced water was recovered. Talon/LPE was contracted to perform an initial site assessment and soil sampling.		
Describe Area Affected and Cleanup Action Taken.* <input type="checkbox"/> The majority of the spill remained in the steel facility under the equipment. However the berm was breached on the east of the facility.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <b>Chris Jones</b> <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.com, c=US Date: 2015.03.06 08:17:57 -06'00'</small>	OIL CONSERVATION DIVISION	
Printed Name: <b>Chris Jones</b>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <b>HES Specialist</b>	Approval Date: <b>3/9/15</b>	Expiration Date: <b>N/A</b>
E-mail Address: <b>Christopher.Jones@oxy.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>3/5/2015</b> Phone: <b>575-628-4121</b>	Remediation per O.C.D. Rules & Guidelines	

\* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO  
DATE THAN: 4/9/15

2RP-2870