## **NMOCD**

Form 3160-5 (August 2007)

**UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Διν	tes	10
4 34	100	10

5. Lease Serial No.

•	OMB N Expires:		

FORM APPROVED

 	-	
	C	

Do not use the		RIS ON WE			•	•
	is form for proposals to II. Use form 3160-3 (AP	drill or to re-e D) for such pr	enter an oposals.		6. If Indian, Allottee	or Tribe Name
SUBMIT IN TR	PLICATE - Other instruc	ctions on reve	rse side.		7. If Unit or CA/Agre	eement, Name and/or No.
Type of Well	her				8. Well Name and No GODFREY MP F	
Name of Operator     YATES PETROLEUM CORP	Contact: ORATIONE-Mail: tinah@yate	TINA HUERTA espetroleum.com	<del>)</del>		9. API Well No. 30-005-60630-0	00-S1
3a. Address 105 SOUTH 4TH STREET ARTESIA, NM 88210		3b. Phone No. ( Ph: 575-748 Fx: 575-748-		e)	10. Field and Pool, or PECOS SLOPE	Exploratory E-ABO
4. Location of Well (Footage, Sec., 7	T., R., M., or Survey Description				11. County or Parish,	and State
Sec 10 T7S R25E SWNE 198	30FNL 1980FEL				CHAVES COU	NTY, NM
12 CHECK ADD	ROPRIATE BOX(ES) TO	INDICATE	NATUDE OF	NOTICE DI	EDODT OF OTUE	
	ROPKIATE BOX(ES) TO	INDICATE		<del> </del>		K DATA
TYPE OF SUBMISSION			TYPEO	F ACTION		·
■ Notice of Intent	☐ Acidize	□ Deepe	en	☐ Product	ion (Start/Resume)	■ Water Shut-Off
	☐ Alter Casing	Fracti	•	☐ Reclam	ation	☐ Well Integrity
☐ Subsequent Report	☐ Casing Repair	□ New 0	Construction	☐ Recomp		Other
☐ Final Abandonment Notice	☐ Change Plans	🛛 Plug a	and Abandon		arily Abandon	
	Convert to Injection	Plug l	3ack	■ Water D	Disposal	
Yates Petroleum Corporation  1. MIRU all safety equipment	as needed. No casing re cap it with 35 ft cement. 1	covery will be	attempted.	,	SPD 3/16	;≱ecord D
<ol> <li>Set a CIBP at 3650 ft and sp.</li> <li>Perforate at 1590 ft and sp.</li> <li>Perforate at 450 ft and sp.</li> <li>Perforate at 450 ft and sp.</li> <li>Perforate at 60 ft and sp.</li> <li>Perforate at 60 ft and sp.</li> <li>Remove all surface equipments.</li> </ol>	e casing shoe and across it a 25 sx Class C cement shoe, inside and outside c a 15 sx Class C cement p	top of Glorieta plug from 350 asing. WOC a olug from 60 ft	n, inside and ou #50 ft - 400 ft. This and tag plug. up to surface.	utside casing is puts a 100	NI	M OIL CONSERVAT ARTESIA DISTRICT FEB 25 2015
<ul> <li>3. Perforate at 1590 ft and sp</li> <li>328 ft plug across intermediat</li> <li>WOC and tag plug.</li> <li>4. Perforate at 450 ft and spc</li> <li>ft plug across surface casing</li> <li>5. Perforate at 60 ft and spot</li> </ul>	e casing shoe and across it a 25 sx Class C cement shoe, inside and outside c a 15 sx Class C cement p	top of Glorieta plug from 350 asing. WOC a olug from 60 ft	n, inside and ou #50 ft - 400 ft. This and tag plug. up to surface.	utside casing is puts a 100	NI.	יייואו כנטייי
Perforate at 1590 ft and sp 328 ft plug across intermediat WOC and tag plug.     Perforate at 450 ft and spc ft plug across surface casing 5. Perforate at 60 ft and spot 6. Remove all surface equipn  14. Thereby certify that the foregoing is	e casing shoe and across at a 25 sx Class C cement shoe, inside and outside c a 15 sx Class C cement p nent, weld dry hole marke strue and correct.  Electronic Submission #X For YATES PETRI	top of Glorieta plug from 350 asing. WOC a plug from 60 ft or and clean loc	transide and our state of the surface of the surfac	utside casing s puts a 100 egulations.	s System	FEB <b>25</b> 2015
Perforate at 1590 ft and sp 328 ft plug across intermediat WOC and tag plug.     Perforate at 450 ft and spc ft plug across surface casing 5. Perforate at 60 ft and spot 6. Remove all surface equipn  4. I hereby certify that the foregoing is	e casing shoe and across at a 25 sx Class C cement shoe, inside and outside of a 15 sx Class C cement p nent, weld dry hole marke strue and correct. Electronic Submission #2 For YATES PETRO	plug from 350 casing. WOC a clug from 60 ft or and clean local company with the company compan	transide and our state of the surface of the surfac	utside casing s puts a 100 egulations.  Il Information to the Roswe 12/12/2015 (15	s System	FEB <b>25</b> 2015
Perforate at 1590 ft and sp 328 ft plug across intermediat WOC and tag plug.     Perforate at 450 ft and spot ft plug across surface casing sp. Perforate at 60 ft and spot ft. Remove all surface equipmed.  I hereby certify that the foregoing is Co	e casing shoe and across at a 25 sx Class C cement shoe, inside and outside c a 15 sx Class C cement p nent, weld dry hole marke strue and correct. Electronic Submission # For YATES PETRO mmitted to AFMSS for proceed.	top of Glorieta plug from 350 casing. WOC a slug from 60 ft or r and clean loc 291440 verified DLEUM CORPO cessing by DAV	transide and our state of the surface of the surfac	utside casing s puts a 100 egulations.  Ell Information to the Roswe 12/12/2015 (15 EPORTING	s System II DRG0044SE)	FEB <b>25</b> 2015
3. Perforate at 1590 ft and sp 328 ft plug across intermediat WOC and tag plug. 4. Perforate at 450 ft and spot ft plug across surface casing sp. 5. Perforate at 60 ft and spot ft. Remove all surface equipmed.  14. Thereby certify that the foregoing is Contame (Printed/Typed)  Contame (Printed/Typed)  TINA HUE	e casing shoe and across at a 25 sx Class C cement shoe, inside and outside c a 15 sx Class C cement p nent, weld dry hole marke strue and correct. Electronic Submission # For YATES PETRO mmitted to AFMSS for proceed.	top of Glorieta plug from 350 casing. WOC a slug from 60 ft or r and clean loc 291440 verified DLEUM CORPO cessing by DAV	transide and our fit. This fit. This plug up to surface ation as per research by the BLM West ation, sent of GLASS on 0 Title REG R	egulations.  Il Information to the Roswe 12/12/2015 (15	System II DRG0044SE) SUPERVISOR	FEB <b>25</b> 2015
3. Perforate at 1590 ft and sp 328 ft plug across intermediat WOC and tag plug.  4. Perforate at 450 ft and spot ft plug across surface casing sp. 5. Perforate at 60 ft and spot ft. Remove all surface equipmed.  14. Thereby certify that the foregoing is Converted (Printed/Typed)  Converted (Printed/Typed)  TINA HUE	e casing shoe and across at a 25 sx Class C cement shoe, inside and outside c a 15 sx Class C cement p nent, weld dry hole marke  strue and correct.  Electronic Submission #2 For YATES PETRO DERTA  Submission)	top of Glorieta plug from 350 casing. WOC a slug from 60 ft or r and clean loc 291440 verified DLEUM CORPO cessing by DAV	transide and our fit. This fit. This plug up to surface ation as per research by the BLM West ation, sent of GLASS on 0 Title REG R	egulations.  Il Information to the Roswe 12/12/2015 (15)  OFFICE US	System II DRG0044SE) SUPERVISOR SE	FEB <b>25</b> 2015
3. Perforate at 1590 ft and sp 328 ft plug across intermediat WOC and tag plug. 4. Perforate at 450 ft and spot ft plug across surface casing sp. 5. Perforate at 60 ft and spot 6. Remove all surface equipmed at 14. I hereby certify that the foregoing is compared to the surface equipmed at 15 perforate at 60 ft and spot 6. Remove all surface equipmed at 15 perforate at 60 ft and spot 6. Remove all surface equipmed at 15 perforate at 60 ft and spot 6. Remove all surface equipmed at 15 perforate at 60 ft and spot 6. Remove all surface equipmed at 15 perforate at 60 ft and spot 6. Remove all surface equipmed at 15 perforate at 60 ft and spot 6. Remove all surface equipmed at 15 perforate at 450 ft and spot 6. Remove all surface equipmed at 15 perforate at 450 ft and spot 6. Remove all surface equipmed at 15 perforate at 450 ft and spot 6. Remove all surface equipmed at 15 perforate at 450 ft and spot 6. Remove all surface equipmed at 15 perforate at 450 ft and spot 6. Remove all surface equipmed at 15 perforate at 450 ft and spot 6. Remove all surface equipmed at 15 perforate at 450 ft and spot 6. Remove all surface equipmed at 15 perforate at 450 ft and spot 6. Remove all surface equipmed at 15 perforate at 450 ft and spot 6. Remove all surface equipmed at 15 perforate at 450 ft and spot 6. Remove at 15 perforate at 450 ft and spot 6. Remove at 15 perforate at 450 ft and spot 6. Remove at 15 perforate at 450 ft and spot 6. Remove at 15 perforate at 450 ft and spot 6. Remove at 15 perforate at 15	e casing shoe and across It a 25 sx Class C cement Ishoe, inside and outside c a 15 sx Class C cement p nent, weld dry hole marke It true and correct. Electronic Submission #2 For YATES PETRO MINISTER PACE FO THIS SPACE FO  d. Approval of this notice does	top of Glorieta plug from 350 casing. WOC a slug from 60 ft or r and clean loc 291440 verified DLEUM CORFO cessing by DAV	the HLM We praction as per research to the HLM We praction as per research to the HLM We praction, sent of the HLM Sent of the	egulations.  Il Information to the Roswe 12/12/2015 (15)  OFFICE US	System II DRG0044SE) SUPERVISOR SE	FEB 2 5 2015  RECEIVED
3. Perforate at 1590 ft and sp 328 ft plug across intermediat WOC and tag plug. 4. Perforate at 450 ft and spot ft plug across surface casing sp. 5. Perforate at 60 ft and spot 6. Remove all surface equipmed at 14. I hereby certify that the foregoing is Company (Printed/Typed) TINA HUE Signature (Electronic Special Signature)	e casing shoe and across It a 25 sx Class C cement Ishoe, inside and outside of a 15 sx Class C cement p Inent, weld dry hole marke Is true and correct. Electronic Submission #2 For YATES PETRI ISHOM SUBMISSION THIS SPACE FO  IT A Submission)  THIS SPACE FO  IT A Submission of this notice does all able title to those rights in the	top of Glorieta plug from 350 casing. WOC a slug from 60 ft or r and clean loc 291440 verified DLEUM CORFO cessing by DAV	the HLM We praction as per research to the HLM We praction as per research to the HLM We praction, sent of the HLM Sent of the	egulations.  Il Information to the Roswe 12/12/2015 (15)  OFFICE US  EUM ENGINE	System II DRG0044SE) SUPERVISOR SE	FEB 2 5 2015  RECEIVED

APPROVED FOR 3 MONTH PERIOD \*\* BLM REVISED \*\* BLM REVISED \*\* MONTH PERIOD **CONDITIONS OF APPROVAL** MAY 2 0 2015 ENDING

## Revisions to Operator-Submitted EC Data for Sundry Notice #291440

**Operator Submitted** 

**BLM Revised (AFMSS)** 

Sundry Type:

ABD NOI

ABD NOI

Lease:

NMNM10893

NMNM10893

Agreement:

Operator:

YATES PETROLEUM CORPORATION 105 SOUTH FOURTH STREET ARTESIA, NM 88210 Ph: 575-748-1471

YATES PETROLEUM CORPORATION 105 SOUTH 4TH STREET ARTESIA, NM 88210

Admin Contact:

TINA HUERTA REG REPORTING SUPERVISOR E-Mail: tinah@yatespetroleum.com

Ph: 575-748-4168 Fx: 575-748-4585

**Tech Contact:** 

TINA HUERTA

REG REPORTING SUPERVISOR

E-Mail: tinah@yatespetroleum.com

Ph: 575-748-4168

Fx: 575-748-4585

Location:

State:

NM CHAVES County:

Field/Pool:

Well/Facility:

PECOS SLOPE; ABO

GODFREY MP FEDERAL 1 Sec 10 T7S R25E SWNE 1980FNL 1980FEL

TINA HUERTA REG REPORTING SUPERVISOR E-Mail: tinah@yatespetroleum.com

Ph: 575-748-4168 Fx: 575-748-4585

TINA HUERTA

REG REPORTING SUPERVISOR. E-Mail: tinah@yatespetroleum.com


Ph: 575-748-4168 Fx: 575-748-4585

NM CHAVES

PECOS SLOPE-ABO

GODFREY MP FEDERAL 1 Sec 10 T7S R25E SWNE 1980FNL 1980FEL

WELL NAME: GODFREY MP FEO#1 FIELD AREA: PECOS SLOPE ABO LOCATION: 1980 FNL 7. 1980 FEL SEC 10 775 R25E GL: 3821 ZERO: 9 AGL: 'KB: 3830 ORIG. DRLG./COMPL. DATE: CASING PROGRAM: COMMENTS: DRILLED & COMPLETED IN 1980. 103/4" 400' CMT - 275 5KS, CIAC BEFORE 7"C 1312' CM7- 300 SKS, CIRC tm. Tops San Andres 442' Glorieta: 1540' 4,012-22 (20) 412" @ 4672 CMT- 450 SKS - SKETCH NOT TO SCALE -



## BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90<sup>th</sup> day provide the BLM Roswell Field Office (RFO), prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged. Failure to do so will result in enforcement action. Unless the well has been properly plugged, the rig shall not be removed from over the hole without prior approval.
- 2. <u>Notification</u>: Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

- 6. <u>Dry Hole Marker:</u> All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10 feet in length, 4 feet above the ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.