

RECEIVED

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

**OPERATOR** ☒ Initial Report ☒ Final Report

**Name of Company:** COG Operating LLC **Contact:** Robert McNeill

**Address:** 600 West Illinois Avenue, Midland TX 79701 **Telephone No.:** 432-230-0077

**Facility Name:** Canvas back 13 Federal #3H **Facility Type:** Battery

**Surface Owner:** Federal **Mineral Owner:** Federal **API No.:** 30-015-41529

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	13	24S	31E	190'	North	1470'	East	Eddy

**Latitude:** 32.2240821559095 **Longitude:** -103.727746743736

### NATURE OF RELEASE

Type of Release: Oil and Water	Volume of Release: 10 bbls Oil; 250 bbls PW	Volume Recovered: 10 bbls Oil; 248 bbls PW
Source of Release: Tank	Date and Hour of Occurrence: 2/27/2015 10:00 am	Date and Hour of Discovery: 2/27/2015 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Jim Amos - BLM	
By Whom? Lupe Carrasco	Date and Hour: February 28, 2015 10:36 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

If a Watercourse was Impacted, Describe Fully.\*



MAR 19 2015

RECEIVED

Describe Cause of Problem and Remedial Action Taken.\*  
This release was caused when a transfer pump failed to start. It subsequently cause the water tank to over flow. Vacuum trucks were dispatched to recover the standing fluid and put back in the tank.

Describe Area Affected and Cleanup Action Taken.\*  
The release occurred within a lined facility. All fluids were able to be recovered and the facility put back into production.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 3/20/15	Expiration Date:
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: March 19, 2015 Phone: 575-748-6940		

\* Attach Additional Sheets If Necessary

2RP-2899