NM OIL CONSERVATION

ARTESIA DISTRICT

State of New Mexico **Energy Minerals and Natural Resources**

MAR 2 0 2015

Form C-141 Revised August 8, 2011

Sut Poli C Edpy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr.

Santa Fe, NM 87505

District I

District II

District III

District IV

1625 N. French Dr., Hobbs, NM 88240

1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

811 S. First St., Artesia, NM 88210

Release Notification and Corrective Action **OPERATOR** Initial Report Final Report von Energy Production Co LP Contact: Brian Kuh, Devon Completions Foreman (6137)PO Box 250 Artesia, NM 88211 Address: Telephone No. 575-616-1540 Near Cotton Draw Unit 214H Facility Name: Facility Type: Well location - OFF PAD Surface Owner: State Mineral Owner: Federal API No. 30-015-41537 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County 31E C 36 **24S** 200 North 1710 West **Eddy** Latitude: 32 deg 10' 49.931" N ____ Longitude: 103 deg 44' 4.25" W NATURE OF RELEASE Produced Water from Trunk Line Type of Release: Volume of Release: 6 bbls Volume Recovered: 1 bbl Date and Hour of Occurrence Source of Release: Date and Hour of Discovery Water transfer trunk line 3/18/2015, 2:45 PM 3/18/2015, 2:45 PM Was Immediate Notice Given? If YES, To Whom? OCD Artesia - Mike Bratcher BLM Carlsbad - Jim Amos By Whom? Date and Hour: 3/19/15, 8:30 AM - OCD phones out of order 3/20/15, 7:30 AM - voicemail to Mike Bratcher Brian Kuh, Completions Foreman 3/19/15, 8:30 AM - voicemail to Jim Amos Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. Yes No N/A If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Bosque Supervisor turned on pump to send water to Cotton Draw Unit 214 Poseidon tank. When the water started flowing, the hose separated from the hammer union off of the trunk line causing the spill. Describe Area Affected and Cleanup Action Taken.* The spill traveled approximately 8 feet to the North, 8 feet to the East, 7 feet to the West, and 22 feet to the South of the point of release. A vacuum truck was used to clean up as much water as possible, approximately 1 barrel. Alfredo's was called in to take soil samples, I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Printed Name: Denise Menoud Approved by Environmental Specialist: Approval Date: 5 Title: Field Admin Support **Expiration Date:** E-mail Address: Denise.Menoud@dvn.com Conditions of Approval: Attached Remediation per O.C.D. Rules & Guidelines Date: 3/20/2014 Phone: 575-746-5544 SUBMIT REMEDIATION PROPOSAL NO. Attach Additional Sheets If Necessary LATER THAN: