

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

MAR 19 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

NA81507948548

Name of Company: Devon Energy Production Co LP (6137) <i>0137</i>		Contact: Danny Velo, Devon Completions Foreman
Address: PO Box 250 Artesia, NM 88211		Telephone No. 575- 703-3360
Facility Name: Cotton Draw 14 Fed 3H		Facility Type: Well location
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42504

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	14	25S	31E	330	North	1200	East	Eddy

Latitude: ___ Longitude: ___

NATURE OF RELEASE

Type of Release: NONE, pump fire contained in equipment	Volume of Release: N/A	Volume Recovered: N/A
Source of Release: Frac Pump caused fire in the pump only	Date and Hour of Occurrence 3/12/2015; 1:00 A.M.	Date and Hour of Discovery 3/12/2015; 1:00 A.M.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Mike Bratcher BLM-Jeff Robertson	
By Whom? Danny Velo, Completions Foreman	Date and Hour: OCD-3/19/15; attempted to leave voice mail, not working; Main line not working. 3/19/15 12:15 PM: Per Jeff/BLM, not recordable, just an equipment failure, do not file C141.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*

During pumping operation for frac job, the internal parts of the pump power end of the pump overheated causing a small fire at the pump. The pump was shut down and the fire was put out using a fire extinguisher. After the fire was out and no possibility of a flare up, they released pressure off the lines, rigged down the pump, and it was removed from the line. Damage was contained to the pump power end and no other damage resulted.

Describe Area Affected and Cleanup Action Taken.*

There was no affected area and the pump was removed from the line. (Note: No GIS mapping available yet, well too new)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Denise Menoud</i>	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 3/20/15	Expiration Date: N/A
E-mail Address: Denise.Menoud@dmv.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 3/19/2015	Phone: 575-746-5544	

* Attach Additional Sheets If Necessary

2RP-2902