UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135

Expires: July 31, 2010

5. Lease Serial No.
NMNM0554499

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

abandoned we	II. Use form 3160-3 (API	D) for such p	roposals.	<i>*</i>	o. 11 maian, motice of	Tribe Name
SUBMIT IN TRI	PLICATE - Other instruc	ctions on rev	erse side.	•	7. If Unit or CA/Agree 891013810B	ment, Name and/or No.
Type of Well	ner		· .		Well Name and No. ROSS DRAW UNI	T 26
Name of Operator RKI EXPLORATION & PROD		HEATHER B kixp.com	REHM		9. API Well No. - 30-015-33083-0	0-S1
3a. Address 210 PARK AVE SUITE 900 OKLAHOMA CITY, OK 73102	2	3b. Phone No Ph: 405-99 Fx: 405-996		e)	10. Field and Pool, or I ROSS DRAW	Exploratory
4. Location of Well (Footage, Sec., T Sec 34 T26S R30E NENE 450	C, R., M., or Survey Description, وفي المنظمة	date & 11	9-1803		11. County or Parish, a EDDY COUNTY	
12. CHECK APPI	ROPRIATE BOX(ES) TO) INDICATE	NATURE OF	NOTICE, RI	EPORT, OR OTHER	R DATA
TYPE OF SUBMISSION		.,	ТҮРЕ (OF ACTION		
☑ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	□ New	ture Treat Construction and Abandon	☐ Reclam	olete arily Abandon	□ Water Shut-Off □ Well Integrity □ Other
13. Describe Proposed or Completed Op- If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab- determined that the site is ready for fi PLEASE CANCEL ET#288603 RKI EXPLORATION & PROD	ally or recomplete horizontally, rk will be performed or provide operations. If the operation respondenment Notices shall be file inal inspection.) FOR THE RECOMPLET UCTION REQUESTS TO	give subsurface the Bond No. or sults in a multipled only after all n	ocations and mean file with BLM/Ble completion or re equirements, inch	sured and true ve A. Required sul completion in a inding reclamation by using the	ertical depths of all pertine bsequent reports shall be f new interval, a Form 3160 n, have been completed, a following proposed	ent markers and zones. Tiled within 30 days -4 shall be filed once and the operator has
procedure. NU 3K# BOP; TOH w/ 2 7/8? Spot 25 sx Class C cement (1. Spot 40 sx Class C cement (1. TIH w/ tubing to 50? below 5? 6.3 gps, 1.32 cfs yield), flush v	tubing; set 5?? CIBP @ 5 4.8 ppg, 6.3 gps, 1.32 cfs 4.8 ppg, 6.3 gps, 1.32 cfs ? casing stub (estimated 3 vith 17? bbls heavy mud.	,520?. Co yield), EOT (yield) 3,235?). Spot POH w/ 10 st	3,550?. S 75 sx Class C ds tubing. WO	ZS S Spot plus Logic 12 cement (14.8 CT. RIH and	x cmt 3500-	MAR 23 2015 RECEIVED
14. I hereby certify that the foregoing is Contained (Printed/Typed) HEATHER	Electronic Submission #2 For RKI EXPLOF ommitted to AFMSS for pro	291219 verified RATION & PR Dicessing by J	DLLC, sent to MES AMOS on	the Carlsbad 03/12/2015 (1 LATORY AN	5JA0216SE) ALYST	
Signature (Electronic S			Date 02/11/		<i>∕NO</i>	3/2Y/15
ejector,	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE	
Approved By James	a. ams	:	Title S	AET	·	3-17-15 Date
Conditions of approval, if any, are attached ertify that the applicant holds legal or equivalent would entitle the applicant to conductive the IS U.S.C. Section 1001 and Title 43	itable title to those rights in the ct operations thereon. U.S.C. Section 1212, make it a c	subject lease	Office Z	d willfully to ma	ske to any department or a	gency of the United
States any false, fictitious or fraudulent s	tatements or representations as	to any matter wi	hin its jurisdiction	i.		

Réjected: ** BLM REVISED ** BLM REVI

Additional data for EC transaction #291219 that would not fit on the form

32. Additional remarks, continued

plug (maximum tag depth 50? above cut off point, estimated 3,185?). EOT @ 1,060?.

Spot 60 sx Class C cement (14.8 ppg, 6.3 gps, 1.32 cfs yield), RIH and tag plug (maximum tag depth 960?). EOT @ 800?. Spot 60 sx Class C cement (14.8 ppg, 6.3 gps, 1.32 cfs yield), RIH and tag plug (maximum tag depth 695?).

Spot 20 sx Class C cement (14.8 ppg, 6.3 gps, 1.32 cfs yield).

PLEASE REFER TO ATTACHED DIAGRAM.

Spot Alug 1000'-696 WOC Tag (B/Soft, Show)

Spot plug 60 - Sart.

(5) 60 -	Operator KKI
	Wall Name (NO. Ross Dead Unit 2
Hole Size 12/4	API 3001533083
	450 (D)S 660 (D) SEC. 34
ALL STREET	T 26 S R 30 E Eddy CTY
3.55 SXS Cement	The state of the s
	R-111-P
TOC AT Surf	Secretary Potosh
	Cove/Karst
85/8 Casing Set at 746	LOC Hobitat
818	to the times
Hole Size 77/8	Top Salt 950
	Base Seit 3450
696 woc (65)	Control of the contro
550 SXS Cement (T/Salt, Show)	FORMATIONS
330 3x3 cement (1/30)	Rustler 700
(CBL)	
TOC A+ 3000 (CBL)	Solado 1060
	Cast: le 1620
	Bell Cyn 3440
3) Spot (mf from 3285- 3)55 woc Tag Cut/Au//@ 3235 hope	Charlet Cyn 4391
3 sec woc tog	TO DIRECT AND THE SECRETARY OF THE PROPERTY OF
Cut/Au/1@ 3235 hope	No industry Constitution of the State Control of th
	September 1987 The September 1987 Se
2) Spot Cont from	Evaluation of the section of the contract of t
3500' - 3370, WOC Tag //	
(B/Sa/t)	DVT
	PERFORATIONS.
	5556 5590 Cherry
	Cy
	A SUCKET COLOR STORE AND A SUCKET AND A SUCK
	edgi egil getangi nekigani sakapaka kilinaka kilinaka kilinaka pelakir anggari kilinaka kilin
Little	
6 1 (CTAA 0 5520 ////	Street St
D Set CIBA @ 5520 Cap CIBA W/ 25 SY ent	der en et en
CON -IDI	·
5/2 Casing Set at 5710	
	T 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
TO A+ 5710 POTO 5710	James A. Amos
	575-234-5909

575-361-2648

RKI Exploration & Production, LLC UCBHWW Federal 2

Plugging and Abandonment Procedure

Brushy Draw

Section 25 T26S R29E Eddy County, NM

API # 30-015-23786 Property No. 157500

Spud Date: 2/1/86 Comp Date: 3/14/86

KB Elev: 2,947' GL Elev: 2,937' 3,188 **PBTD:** 3,120' Marker Joint: N/A Producing Formations: Ramsey 2,071'-3,089'

CASING SUMMARY:

Safety Factor = 80% of new applied to burst, collapse and tension parameters in table

-		Surety rate		пен арри	iva to equet, vem	apoe and yer	ioron param	eters in tao.	<u> </u>		
	Size	Depth (ft)	Weight (#/ft)	Grade psi	Connection Type	Capacity (bb/s/ft)	ID (in)	Drift (in)	Burst (psi)	Collapse (psi)	Tension (lbs)
	8 5/8" -	433'	24	J-55	ST&C	0.0637	8.097	7.972 、	-2,360	1,100	195,000
I	4½":	3,135'	9.5/10.5	J-55	ST&C /	0.0159	4.052	3.927	3,550	-2,650	80,000

8 5/8" 24# J-55 STC: 0'-433'- TOC @/surface

Production: 4 1/2" 10.5# J-55 STC: 0' - 3,188'; TOC @ 830' per calculation

COMPLETION HISTORY TO DATE: Ramsey 3,071'-3,089'. Well temporarily abandoned in 2009.

OBJECTIVE: Plug and abandon. Well is uneconomic.

RKI REQUIRES THAT HARD HATS, STEEL TOE BOOTS, FIRE RETARDANT CLOTHING, AND SAFETY GLASSES BE WORN ON LOCATION

HOLD SAFETY MEETING PRIOR TO OPERATIONS

NO IGNITION SOURCES WITHIN 100

PROCEDURE:

- 1) MI RU Service Unit. Set flow back tank and lay flowline. Set 1 clean frac tank and fill with 480 BFW.
- 2) HO PU. MI RU hot oiler. Pressure test tubing, pump to 400 psi. Unseat pump. Pump 40 bbls hot water w/ paraffin dispersant. RD MO hot oiler.
- 3) TOH, LD rods, pump. Send rods, pump in for inspection.
- ND WH, NU 3K# BOP.
- 5) TIH w/ cement retainer, 2 3/8" tubing to 3,020'. Set retainer @ 3,020'. Sting out of retainer. Sting into retainer. UCBHWW Federal 10 Plugging and Abandonment Procedure 201501 Pg 1 of 2

- 6) MIRU cementers. Load backside with FW and pressure to 500 psi.
- 7) Squeeze Ramsey w/ 25 sx Class C cement (14.8 ppg, 6.3 gps, 1.32 cfs yield), flush with 11 bbls FW. Sting out of retainer and dump 25 sx cement on top of retainer. POH w/ 3 jts. tubing.
- 8) Circulate hole w/ 45 bbls. heavy mud. TOH w/ retainer stinger, LD 2,300' tubing.
- 9) MI RU wireline. RIH w/ JB/GR to 600'. Perforate 4 deep penetration holes @ 533'.
- 10) Open annulus and monitor. Squeeze 100 sx Class C cement (14.8 ppg, 6.3 gps, 1.32 cfs yield) from 533'-300', flush with 4½ bbls heavy mud. WOCT. RIH and tag plug (maximum tag depth 383').
- 11) TOH, LD tubing.
- 12) RIH and perforate 4 deep penetration holes @ 60'. RD MO wireline:
- 13) ND BOP. Install B-1 flange w/ valve. Squeeze 20 sx Class C cement (14.8 ppg, 6.3 gps, 1.32 cfs yield) from 60' to surface. RD MO cementers.
- 14) Cut-off casinghead. WO cap with well name/number, operator name, date. Set from top of casing to minimum 4' above ground level, install a minimum 4" in diameter marker with WO cap with operator, well name/number and date.
- 15) Remove all equipment, safety anchors, clean up and reclaim surface location.

RKI Contact List:

RKI	Title	Office	Cell	
Ken Fairchild	Production Manager	405-996-5764	469-693-6051	
Gene Thompson	Production Superintendent	575-885-1313	817-908-9219	
Paul Munding	Senior Production Engineer	405-996-2140	405-820-2825	
Jaime McAlpine	Engineering Consultant	405-996-5741	405-850-6685	

Emergency Contacts - New Mexico:

Carlsbad Medical Center Hospital: (575) 887-4100 2430 W. Pierce St., Carlsbad, NM 88220

Sheriff's Office: Lea County Sheriff Dept (575) 396-3611

Eddy County Sheriff Dept (575) 887-7551

Emergency Contacts - Texas:

Hospital: Reeves County Hospital (432) 447-3551

2323 Texas St, Pecos TX 79772

Sheriff's Office: Reeves County Sheriff Dept (432) 445-4901 Loving County Sheriff Dept (432) 377-2411



